

CL-415

MODEL CL-215-6B11 (CL-415 Variant) SERVICE BULLETIN INDEX

DESCRIPTION:

This Service Bulletin is an index Service Bulletins issued for CL-215-6B11 (CL-415 Variant) aircraft.

This index is provided for reference and is updated periodically. Additional Service Bulletins are distributed directly to operators and are also available through the Viking Air website. These additional bulletins will be included in this index at the next revision.

Effective October 1, 2016, Viking has reserved the use of Service Bulletins to document mitigation or corrective actions related to continuing airworthiness. Previously issued Service Bulletins are not affected.

Technical Bulletins have been introduced and are used to document technical data for purposes not related to continuing airworthiness. Technical Bulletins for CL-415 are indexed in TB V215-4000.

ORGANIZATION:

This index is divided into two parts:

1. Part 1 lists Service Bulletins issued before October 1, 2016
2. Part 2 lists Service Bulletins issued after October 1, 2016

Each Part is divided into two sections:

1. Section 1 lists Service Bulletins in numerical sequence.
2. Section 2 lists Service Bulletins grouped by applicable ATA chapter.

CL-415

VIKING*

THIS PAGE INTENTIONALLY LEFT BLANK

CL-415

MODEL CL-215-6B11 (CL-415 Variant) SERVICE BULLETIN INDEX

PART 1

Service Bulletins issued before October 1, 2016

SECTION 1 NUMERICAL SEQUENCE

DEFINITIONS:

215-

This column contains the number of the Service Bulletin. Service Bulletins listed in Part 1 of this index use the prefix “215-”, for example Service Bulletin 215-4024.

Service Bulletins with the letter “A” preceding the number are Alert Service Bulletins, for example 215-A4452. These are identified as requiring urgent operator action, and may be mandated by Airworthiness Directive.

Note: There are some breaks in the numbering sequence. This is due to Service Bulletin numbers having been reserved for use by the manufacturer and then subsequently not issued, or other legacy change reasons.

DATE OF ISSUE

This column contains the issue month and year of the applicable revision, as listed in the SUBJECT column.

SUBJECT

This column contains the title of the Service Bulletin, and any applicable revision numbers.

The column also contains applicable Info Sheets. Info Sheets are documents used to communicate supplemental information that did not require a revision of the Service Bulletin. Info Sheets should be retained with the applicable Service Bulletin.

Cancelled Service Bulletins and Proposal Sheets are also listed in this column for reference, but are not distributed.

MOD SUMMARY

This column contains applicable design change document numbers, intended for manufacturer reference only. These design change documents are not distributed.

KIT DRAWING

This column contains applicable drawing numbers or Restrictions/Special Instruction numbers.

EFFECTIVITY

This column contains applicable aircraft serial numbers. Effectivity may be also be affected by aircraft configuration and modification/conversion status.

Note: Applicability of Service Bulletins may be subject to Airworthiness Directives.

COMPLIANCE

Review the Reason and Description paragraphs to evaluate requirements and benefits of compliance.

This column lists a compliance category, using abbreviations as follows:

M – Mandatory

Service Bulletins with this compliance category were developed for inspections or modifications that are to be incorporated within a specified time frame. Mandatory compliance is subject to applicable Airworthiness Directives.

R – Recommended

Service Bulletins with this compliance category were developed for the incorporation of modifications to enhance performance, upgrade equipment, replace obsolete parts, or make other product improvements to improve maintainability.

RBD – Recommended Before Delivery

Service Bulletins with this compliance category were developed for modifications to be incorporated after an aircraft is manufactured, but before delivery to an operator.

C/O – Customer Option

Service Bulletins with this compliance category were developed for the incorporation of optional modifications.

ATA REF.

This column lists the applicable ATA chapter reference number.

SECTION 2 ATA CHAPTER SEQUENCE

DEFINITIONS:

215-

This column contains the number of the Service Bulletin. Service Bulletins listed in Part 1 of this index use the prefix “215-“, for example Service Bulletin 215-4024.

Service Bulletins with the letter “A” preceding the number are Alert Service Bulletins, for example 215-A4452. These are identified as requiring urgent operator action, and may be mandated by Airworthiness Directive.

Note: There are some breaks in the numbering sequence. This is due to Service Bulletin numbers having been reserved for use by the manufacturer and then subsequently not issued, or other legacy change reasons.

SUBJECT

This column contains the title of the Service Bulletin, and any applicable revision numbers.

The column also contains applicable Info Sheets. Info Sheets are documents used to communicate supplemental information that did not require a revision of the Service Bulletin. Info Sheets should be retained with the applicable Service Bulletin.

Cancelled Service Bulletins and Proposal Sheets are also listed in this column for reference, but are not distributed.

COMPLIANCE

Review the Reason and Description paragraphs to evaluate requirements and benefits of compliance.

This column lists a compliance category, using abbreviations as follows:

M – Mandatory

Service Bulletins with this compliance category were developed for inspections or modifications that are to be incorporated within a specified time frame. Mandatory compliance is subject to applicable Airworthiness Directives.

R – Recommended

Service Bulletins with this compliance category were developed for the incorporation of modifications to enhance performance, upgrade equipment, replace obsolete parts, or make other product improvements to improve maintainability.

CL-415



RBD – Recommended Before Delivery

Service Bulletins with this compliance category were developed for modifications to be incorporated after an aircraft is manufactured, but before delivery to an operator.

C/O – Customer Option

Service Bulletins with this compliance category were developed for the incorporation of optional modifications.

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4000	July 96	Service Bulletin Index					N/A
	Nov 96	Rev. 1					N/A
	March 97	Rev. 2					N/A
	Sept. 97	Rev. 3					N/A
	Dec. 97	Rev. 4					N/A
	March 98	Rev.5					N/A
	Oct.98	Rev. 6					N/A
	Dec. 98	Rev. 7					N/A
	March 99	Rev. 8					N/A
	Sept. 99	Rev. 9					N/A
	Dec. 99	Rev. 10					N/A
	March 00	Rev. 11					N/A
	Oct. 00	Rev. 12					N/A
	March 01	Rev. 13					N/A
	Oct. 01	Rev. 14					N/A
	July 02	Rev. 15					N/A
	Dec. 02	Rev. 16					N/A

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	May 03	Rev. 17					N/A
	Feb. 04	Rev. 18					N/A
	Aug. 04	Rev. 19					N/A
	Jan. 05	Rev. 20					N/A
	Aug. 05	Rev. 21					N/A
	Jan. 06	Rev. 22					N/A
	Dec. 06	Rev. 23					N/A
	Aug. 07	Rev. 24					N/A
	Jan. 08	Rev. 25					N/A
	Oct. 08	Rev. 26					N/A
	June 09	Rev. 27					N/A
	July 10	Rev. 28					N/A
	Jan. 11	Rev. 29					N/A
	Nov. 11	Rev. 30					N/A
	July 12	Rev. 31					N/A
	Aug. 13	Rev. 32					N/A
	June 14	Rev. 33					N/A

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	Jan. 15	Rev. 34					N/A
	Mar. 15	Rev. 34-1					N/A
	June 15	Rev. 34-2					N/A
	Nov 15	Rev. 34-3					N/A
	Feb. 16	Rev. 35					N/A
	May 16	Rev. 35-1					N/A
	Jan 20	Rev 36					N/A
	Jan 21	Rev 37					N/A
4001	Dec. 94	Equipment Installation and Removal for Ferry Flights	415-70092 L		2001 to 2990 as specified	RBD	25
	May 95	Rev. 1	415-70092 Q 415-80247 D				
	July 98	Rev. 2	415-70092 R 415-80247 J 415-80797 A				
	March 00	Rev. 3	415-70092 R 415-80247 J 415-80797 A 415-80916 A				

CL-415



MODEL CL-215-6B11 (415)
 SERVICE BULLETIN INDEX
 PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	Nov. 08	Rev. 4	415-70092 T 415-80247 J 415-80797 A 415-80916A 415-78755 A 415-78756 A	(RSI) FRSI-415-3709 A 215T64070 E 215T50529 A 215T70452 A K215T40007 J K215T40017 A K215-70008 D, EO D-3 K215T40023 E K215T30011 NC K215T30031 A K215T30027 E K215T51021 G K215T70468 NC, EO NC-2 K215T40088 NC K215T40089 NC (For A/C 2068) EX215T20040 NC, EO NC-4	(415-78755 for 2068 only)		
4002	Jan. 01	Modification to the Cockpit Heater System	415-80064 C-1	215T95017 A-2 215-95080 D-10 215-30029 H-12	2003, 2004, 2008, and 2009	R	21
4004	Dec. 94	Modification to the Foam System Piping	415-80136 C	215T40008 NC, EO NC-10 215T40007 B, EO B-5	2002 and 2003	RBD	42
4005		Service Bulletin Cancelled					
4006	March 97	Inspection/Replacement of the Flap Asymmetry Interconnect Fitting	415-80326 A		2001 to 2019	R	57
	March 98	Rev. 1					

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4007	Dec. 94	Installation of Fixed Piping in the Water Tanks	415-80149 B	K215T40018 K215T40019 NC, EO NC-1 215T40007 B, EO B-3	2003 and 2004 Post-Delivery 2001, 2002, 2006 and 2007 Pre-Delivery	R	42
4008	Dec. 94	Modification to the Main Distribution Centre/ Combustion Heater Shield Assembly	415-80156 NC	215T52100 G, NIEO 2	2002 and 2003	RBD	53
4009	Dec. 94	Installation of a Rubber Gasket on the Compressor/Condenser Removal Cover Assembly	415-80117 B	215T95630 A	2001, 2002, 2004, and 2006	RBD	21
4010	May 95	Restricted to Utility and Utility to Restricted	Memo C649581		2001 to 2990	R	25
	May 10	Rev. 1					
4011	April 95	Installation of a Garmin 165 Global Positioning System	415-80146 B		2001 to 2030	C/O	34
	May 95	Rev. 1	415-80146 E				
	Aug. 95	Rev. 2	415-80146 F		2001 to 2990		
	April 96	Rev. 3	415-80146 H				
	Dec. 96	Info Sheet			2001 to 2019, 2022 to 2026, and 2028 to 2990		
	June 98	Proposal Sheet			2001 to 2990		

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	July 98	Rev. 4	415-80146 H-4		2001 to 2019, 2022 to 2026, 2028 to 2934, and 2040 to 2990		
	April 99	Rev. 5	415-80146 H-5 415-80866 A 415-80775 A	K215T51020 J	2001 to 2019, 2022 to 2026, 2028 to 2934, and 2043 to 2990		
	July 99	Info Sheet			2001 to 2019, 2022 to 2026, 2028 to 2934, and 2051 to 2990		
	July 00	Info Sheet			2001 to 2019, 2022 to 2026, 2028 to 2934, and 2051 to 2990		
4012	Jan. 95	Rework of the Flight Engineer Seat Support Structure	415-80108 C	215-40047, EO B-7	2002	R	25
4013	Dec. 94	Replacement of the Nose Landing Tire	415-80074 A	215-85000 H, EO H-2 215-85002 J	2001, 2002, 2004, and 2006	RBD	32
4014	Dec. 94	Addition of Placards on the Foam Tanks	415-80106 NC	Aero Novation Drawing: 215-2501 C, EO C-3	2001 to 2004 and 2006	RBD	42

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4015	Dec. 94	Installation of Protective Sleeves on the Exterior Cap Chains	415-80138 NC	215T60690 A, EO A-12 215T60200 NC, NC-5 215T64058 A, EO A-8	2002 and 2003	RBD	28
4016	Dec. 94	Rework to the Aileron Gust Lock	415-80145 NC	215T92355 A, EO A-3 215T92502 B, EO B-5 215T52025 F	2002 and 2003	RBD	27
4017	Dec. 94	Installation of a Bonding Jumper on the Pressure Refuel Line	415-80163 NC	215T64062 NC, EO NC-10 and NIEO1	2002 and 2003	RBD	28
4018	Dec. 94	Installation of a Charge Chart on the Accumulator Charging-Bay Access Door	415-80150 NC	215T75008 NC 215T75050 B, EO B-7	2002 and 2003	RBD	29
4019	Dec. 94	Removal/Installation of a Slotted Pin	415-80191 A		2001, 2002, and 2004	RBD	27
	March 99	Rev. 1	415-80191A 415-80760 A		2001, 2002, 2004, 2009, 2011 to 2013, and 2031 to 2040		
	Jan. 01	Rev. 2	415-80191A 415-80760 B		2001, 2002, 2004, 2009, 2011 to 2013, and 2031 to 2040		
	Feb. 01	Info Sheet			2009 to 2014 and 2031 to 2040		

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	April 01	Rev. 3	415-80760 B		2009 to 2014 and 2031 to 2040		
4020	Dec. 94	Modification to the Foam System Piping	215-80194 NC	215T40008 NC, EO NC-11	2001 to 2004 2006 and 2007	RBD	42
4021	Dec. 94	Inspection of the Main Landing Gear Shock Strut Assembly	415-80198 A	215-87500 G, EO G-8 215-87501 AJ	2001, 2002, 2004, and 2006	RBD	32
4022	Dec. 94	Installation of a Decal on the ATC Transponder Antenna Assembly	415-80199 A		2001, 2002, 2004, and 2006	RBD	34
	July 95	Rev.1	415-80199 B	215-70844 NC, EO NC-5	2002, 2004, and 2006		
4023	Dec. 94	Replacement of the Mechanical Fuel Control Unit	415-80159 NC	215T60402, NIEO 93	2001, 2002, and 2006-Pre and 2003, 2004, 2008, and 2009 Post delivery	R	71
	Nov. 95	Info Sheet (Cancels SB)					71
4024	Jan. 95	Replacement of the Flight Control Panel	215-80241 A	215T51649 B 215T93800 B15 215T50724 A, EO A-1 215T51660 D	2001, 2002, and 2006-Pre 2003, and 2004, Post-Delivery	R	27
4025	Dec. 94	Removal of Access Ladder Mounting Studs	415-80245 NC	215T40016 C, NIEO 2	2003 and 2004	RBD	25
	Feb. 98	Info Sheet			2003, 2004 2029 and 2030		

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	July 98	Info Sheet			2003, 2004, 2029, 2030, 2035 and 3036		
	May 01	Info Sheet			2003, 2004, 2029, 2030, 2035, 3036, and 2051		
	Nov. 03	Info Sheet	415-80245 F		2003, 2004, 2029, 2030, 2035, 3036, 2051, 2059, 2060, and 2062		
	June 05	Info Sheet	415-80245 F-1		2003, 2004, 2029, 2030, 2035, 3036, 2051, 2058 to, 2060, and 2062		
4026	Jan. 95	Replacement of the Onboard Compressor Wash System Drain Line	415-80202 A	215T75017 C 215T60695, EO A-3	2001, 2002, and 2006	RBD	49
4027	Jan. 95	Replacement of the Glareshield Shroud	415-80115 A	215-40200, EO B-3	2002	RBD	25
4028	Jan. 95	Replacement of Screws for the Emergency Battery	415-80131 NC	215T52020, EO A-2	2002	RBD	33

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4029	Jan. 95	Replacement of the Water Door Tension Rods	415-80144 A	215T26000, EO B-15 215T26018, EO NC-6 215T26080 NC	2001, 2006, and 2007 Pre and 2002 to 2004 Post-Delivery	R	42
	June 97	Info Sheet			2001, 2006, and 2007 Pre-Delivery 2003 and 2004 Post-Delivery		
4030	Feb. 95	Installation of Fuel Transfer Line Protective Covers	415-80179 A		2001 to 2004 and 2006 to 2008	R	28
	June 95	Rev. 1	415-80179 B	215T64060, EO B-3	2002 to 2004 and 2008		
	March 96	Info Sheet			2003, 2004 and 2008		
4031	Oct. 96	Application of External Paint and Registration Markings for the Government of Quebec Aircraft	415-80637 B	215T40471 and 215T40472	2023	R	11
4032	July 95	Provision for Lockwiring the Rudder-Pedal Adjustment Cables	415-80179 A		2002 to 2004	R	27
	March 96	Info Sheet			2003 and 2004		
4033	Jan. 95	Washer Part Number Change for the Battery Hold Down Assembly	415-80204 NC	215T52206, EO F-1	2006	RBD	24

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4034	April 97	Replacement of the Nose Wheel Steering (NWS) Input-Lever End-Cap	415-80669 A		2001 to 2027	R	32
	April 97	Info Sheet			2001 to 2030		32
	July 97	Rev. 1	415-80669 B				
4035	April 95	Replacement of the Foam Refill/Bilge Pump Switch	415-80215 A		2001 to 2004 and 2006 to 2012	R	42
	July 95	Rev. 1	415-80215 A-1		2002 to 2004, 2008, 2009, and 2012		
	Jan. 96	Rev. 2	415-80215 A-2	215T52005, EO G-1	2003, 2004, 2008, 2009, and 2012		42
4036	May 97	Replacement of the Ejector Pump Collector Tank Fasteners	N/A		2001 to 2027	C/O	28
	Dec. 98	Rev. 1					
	May 04	Rev. 2	415-81182 A	K215T64190 NC	2001 to 2990		
4037	Jan. 95	Rework of the Water Door Beam Attachment Holes	415-80231 NC	215T33506, NIEO 3	2002	RBD	42
4038	Nov. 96	Replacement of the Water Door Torque Shaft Seals	415-80234 A		2003 and 2004	R	42

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4039	Jan. 95	Provision for a Ground Support Equipment Blanking Plate	415-80251 NC	215T96700, NIEO 5	2001, 2002, 2006, and 2007	RBD	49
4040	Jan. 95	Onboard Compressor Wash Harness Routing	415-80160 A	215T52270 A	2001	RBD	71
4041	Jan. 95	Modification to the High Frequency Communication Antenna Routing	415-80158 NC	K215T70321, EO NC-1 215T00001, NIEO 55	2002	RBD	23
4042	Jan. 95	French Instructions Placard for the Oil Replenishment System	415-80157 A	215T63906, EO NC-2	2002	RBD	79
4043	Jan. 95	Exterior Markings French Translation	415-80208 NC	215T40008, EO NC-12 215-30078, EO A8	2001, 2002, 2006, and 2007	RBD	11
	March 96	Info Sheet			2001, 2006, and 2007		
4044		Service Bulletin Cancelled					
4045	April 96	Water Door Sealing Improvements	415-80417 A 415-80408 NC 415-80451 NC-1	K215T33500 A	2002 to 2005, 2008, 2009, and 2012	R	42
4046	Jan. 95	Replacement of the Trim Comparator Unit	415-80265 NC	215T50942 E 215T52100 J	2002 Pre and 2001, 2003, 2004 and 2006 to 2010 Post-Delivery		
4047	July 96	Modification to the Rudder Auto-Trim System	415-80425		2003 to 2005, 2008, 2009, and 2012	R	27

CL-415



MODEL CL-215-6B11 (415)
 SERVICE BULLETIN INDEX
 PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	Sept. 97	Rev. 1	415-80425 C-1 415-80286 E	K215T53001 E	2003 to 2005, 2008, 2009, and 2012		
4048	March 95	Relocation of the Collector Tank Manual Shut-Off Valve Controls	415-80283 A		2001 to 2004 and 2006 to 2013	R	28
	Sept. 95	Rev.1	415-80283 D-1 415-80393 A-1	K215T64066 A	2003 to 2005, 2008, 2009, and 2012		
	Aug. 96	Info Sheet			2003 to 2005, 2008, 2009, and 2012		
4049	Jan. 97	Structural Provision for the Emergency Locator Transmitter (ELT) Models 8.1 and 14.1	415-80579 A		2001 to 2990	R	25
	Feb. 98	Proposal Sheet			2001 to 2990		
	Nov. 04	Rev. 1	415-80579 A 415-81211 A	K215T51029 A			
4050	June 95	Refuel Aircraft with the Battery Master Switch Off	415-80246 E		2002 to 2005, 2008, 2009, and 2012	R	24
	Nov. 95	Rev. 1	415-80246 E-2		2003 to 2005, 2008, 2009, and 2012		

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4051	March 96	Rev. 2	415-80246 F				
	March 98	Rev. 3	415-80246 G	K215T52005 F			
	July 98	Modification to the Portable Oxygen Bottle Installation Proposal Sheet			2003 to 2005, 2008, 2009, 2012, 2016, 2017, 2019 to 2023, and 2026 to 2990	R	35
	Sept. 03	Modification to the Portable Oxygen Bottle Installation	415-80285 B-3		2003 to 2005, 2008, 2009, 2012, 2016, 2017, 2019 to 2023, and 2026 to 2990	R	35
	March 04	Rev. 1					
	Sept. 05	Rev. 2	415-80285 C	K215T40028 D	2003 to 2005, 2008, 2009, 2012, 2016, 2017, 2019, 2020 to 2023, and 2026 to 2990		

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	March 10	Info Sheet	415-80285 E		2003 to 2005, 2008, 2009, 2012, 2016, 2017, 2019 to 2023, 2026 to 2062, and 2064 to 2990		
4052	Feb. 95	Relocation of the Cockpit Fire Extinguisher Bottle	415-80266 NC		2001 to 2030	R	26
	July 95	Rev. 1	415-80266 A	K215T40020 A	2002 to 2004, 2008, 2009, and 2012		
	March 96	Info Sheet			2003, 2004, 2008, 2009, and 2012		
4053	Feb. 95	Replacement of the Hydraulic Accumulator Decal	415-80275 NC		2001 to 2004 and 2006 to 2009	R	12 27
	May 95	Info Sheet			2002		
	June 95	Rev. 1	415-80275 NC-1	215T75083, EO B-8	2002 to 2004		
	March 96	Info Sheet			2003 and 2004		
4054	March 95	Installation of Instructional Decals on the Flight Engineer Seat	415-80289 NC		2001 to 2004, and 2006 to 2010	R	25

CL-415



MODEL CL-215-6B11 (415)
 SERVICE BULLETIN INDEX
 PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4055	July 95	Rev. 1	415-80289 B	215T40018 A 215T40009 B, NIEO 1	2002 to 2004, 2008 and 2009	R	79
	March 96	Info Sheet			2003, 2004, 2008 and 2009		
	July 98	Rev. 2	415-80289 B-1		2003, 2004, 2008 and 2009		
	March 95	Replacement of the Oil Replenishment Placard and Markings	415-80279 NC		2001, 2002, 2006, 2007, and 2010		
	June 95	Rev. 1	415-80279 C		2002		
	Feb. 98	Info Sheet			2013 and 2014		
4056	June 05	Info Sheet	415-80279 C-3	2013, 2014, and 2057	R	71	
	Aug. 95	Installation of Engine External Wash	415-75122 C-1	2002 and 2005			
	March 96	Info Sheet		2005			
	Feb. 98	Proposal Sheet		2001 to 2990			
	Feb. 98	Rev. 1	415-75122 C-3	2003 to 2005, 2008, 2009, 2012, 2016, 2017, 2019 to 2023, 2026, and 2027			

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4057	March 01	Info Sheet			2003 to 2005, 2008, 2009, 2012, 2016, 2017, 2019 to 2023, 2026 to 2990		
	Feb. 04	Rev. 2	415-75122 C-4 415-81160 B		2003 to 2005, 2008, 2009, 2012, 2016, 2017, 2019 to 2023, and 2026, to 2990		
	March 05	Info Sheet					
	Dec. 10	Rev. 3	415-75122 C-4 415-81160 C	215T60700 D			
	Sept 11	Info Sheet					
	March 97	Installation of Standardized Fasteners	415-80631 A		2001 to 2036	C/O	42, 53, and 54
	March 98	Rev. 1	415-80631 B-1		2001 to 4045		
	Feb. 08	Info Sheet					

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4058	Feb. 95	Replacement of the Ground Auxiliary Power Unit (GAPU) Compressor/Turbine Wash Restrictor Valve	415-80277 NC	215T60695, EO A-5	2001, 2002, 2006, 2007, 2010, and 2011	R	49
4059	June 95	Replacement of the Flight Control Handwheel	415-80332 A		2001, 2002, 2005 to 2007, and 2012	C/O	27
	Jan. 96	Info Sheet					
	Dec. 06	Info Sheet	415-80332 A-1		2001, 2003 to 2009, and 2012		
4060	June 95	Modification to the Ground Auxiliary Power Unit (GAPU) Electrical System	415-80259 B 415-80297 C	K215T50026 NC	2002	R	80
4061	Feb. 95	Reinforcement of the Main Landing Gear (MLG) Actuator Compartment	415-80307 NC	215-32021, NIEO 3	2002 to 2004 and 2006 to 2008	R	53
4062	Feb. 95	Installation of a Decal on the Airspeed Limitations Placards	415-80312 NC	215T51300, NIEO 1	2004	R	11
	Jan. 96	Info Sheet					
4063	Feb. 96	Installation of an Alternate Power Source for the Empennage and the Main Distribution Centre (MDC) Service Light	415-80375 B	K215T50520 A	2001 to 2022	R	33
	Oct. 96	Info Sheet			2001 to 2019 and 2022		
	Feb. 98	Proposal Sheet			2001 to 2022		

CL-415



MODEL CL-215-6B11 (415)
 SERVICE BULLETIN INDEX
 PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4064	March 97	Replacement of the Junction Box (JB) Tray	415-80273 A-1		2001 to 2004 2006 to 2009	R	39
4065	March 95	Replacement of the VHF Integrated Navigation Receivers	415-80299 NC		2008 and 2009	R	34
	Aug. 96	Info Sheet			2008, 2009, 2020, and 2021		
	Feb. 98	Info Sheet			2008, 2009, 2020, 2021, 2029, and 2030		
	Feb. 00	Info Sheet			2008, 2009, 2020, 2021, 2029, 2030, 2035, 2036, 2045, 2047, and 2048		
	April 00	Info Sheet			2008, 2009, 2020, 2021, 2029, 2030, 2035, 2036		
	Dec. 00	Info Sheet			2001 to 2046 and 2049 to 2990		
	Dec. 03	Rev. 1	415-80299 NC 415-81204 A	K215T51014 NC	2001 to 2044, 2046 and 2049 to 2062		

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	March 10	Info Sheet	415-80299 A-1 415-81204 B		2001 to 2028, 2031 to 2044, 2046 to 2049, 2050, and 2052 to 2062		
4066	March 95	Replacement of the Rudder Trim Actuator and Transmitter Screws	415-80276 NC	215T90817 B, EO B-10	2008 and 2009	R	27
	Aug. 95	Rev. 1			2003, 2004, 2008 and 2009		
4067	May 95	Installation of an Alternate Power Source for the Oil Replenishment System	415-80316 NC		2001 to 2009 and 2012		24
	April 96	Rev. 1	415-80316 A		2001 to 2020		
	Oct. 96	Info Sheet			2001 to 2019		
	Oct. 02	Rev. 2	415-80316 A-1 415-80500 H				
	Aug. 03	Rev. 3	415-80316 B 415-80500 H	K215T51022 C	2001 to 2019	R	
4068	April 96	Replacement of the Oil Replenishment Placard	415-80402 A		2003 to 2005, 2008, 2009, 2012, 2016, 2017, 2019, and 2020	R	79

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	Oct. 96	Info Sheet			2003 to 2005, 2008, 2009, 2012, 2016, 2017, and 2019		
4069	May 95	Ferry Flight Equipment Installation	415-70092 Q 415-80247 C		2008	R	25
4070	Aug. 95	Replacement of the Service Interphone Jack FS 541.0	415-80342 NC		2001 to 2022	C/O	23
	Oct. 96	Info Sheet			2001 to 2019 and 2022		
4071	Sept. 95	Replacement of the Release Latch for the Pitch Disconnect Handle	415-80400 NC		2001 to 2027	C/O	27
	Oct. 96	Info Sheet			2001 to 2019, 2022 to 2024, 2026, and 2027		
	Dec. 96	Info Sheet			2001 to 2019, 2022 to 2024, and 2026		
4072	Dec. 95	Modification to the Ground Water-Filling System	415-80399 C		2001 to 2990	C/O	42
	March 96	Rev. 1	415-80399 E	K215T27000 B	2001 to 2026		
	Oct. 96	Info Sheet			2001 to 2024 and 2026		42

CL-415



MODEL CL-215-6B11 (415)
 SERVICE BULLETIN INDEX
 PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	April 97	Info Sheet			2001 to 2024 and 2026 to 2043		
	Feb. 98	Proposal Sheet			2001 to 2026		
	May 14	Rev. 2	415-80399 F 415-79863 A	K215T27000 C K215T27200 NC	2001 to 2024 and 2026 to 2043		
4073	Sept. 95	Replacement of the Fasteners on the Oil Replenishment Door	415-80415 NC		2001 to 2022	C/O	79
	Oct. 96	Info Sheet			2001 to 2019 and 2022		
4074	Oct .95	Replacement of Fasteners for Access Panels 255-6 and 255-7	415-80347 A	K215T30032 NC	2001 to 2021	C/O	53
	Oct. 96	Info Sheet			2001 to 2019		
4075	April 97	Modification to the Water Drop Control System	415-80517		2001 to 2036	C/O	42
	April 97	Rev. 1	415-80517 C		2001 to 2036		
	May 97	Rev. 2	415-80517 C-2 415-80694 B 415-80713 A		2001 to 2027 and 2029		
	July 97	Rev. 3	415-80517 C-2 415-80694 B 415-80713 A	K215T51031 B K215T51045 NC	2001 to 2027 and 2029		

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4076	Feb. 96	Installation of a Front-Spar Lower-Skin Access Panel	415-80456 NC	K215T10117 A	2001 to 2990	R	57
	Dec. 96	Rev. 1	415-80456 B-2		2001 to 2019, 2022 to 2025, and 2027 to 2990		
	April 97	Rev. 2	415-80456 B-2 415-80670 A		2001 to 2019, 2022 to 2025, and 2027 to 2990		
	April 01	Info Sheet					
	Feb. 06	Info Sheet	415-80670 C		2001 to 2990		
	March 10	Info Sheet	415-80670 E-2				
	April 11	Rev. 3	415-80456 B-2 415-80670 E-3				
	Sept. 14	Rev. 4					
4077	June 97	Replacement of the Airspeed Indicator Nipple (Static Side)	415-80690 A		2001 to 2036	R	34
	July 97	Info Sheet					
4078	Jan. 96	Prevention of Water Accumulation on the Pilot and Copilot Side Consoles	415-80411 NC		2001 to 2028	C/O	53
	Aug. 96	Info Sheet					

CL-415



MODEL CL-215-6B11 (415)
 SERVICE BULLETIN INDEX
 PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	Oct. 96	Info Sheet					
	Dec. 96	Info Sheet			2001 to 2019, 2022 to 2024, and 2028		
	Oct. 97	Rev. 1	415-80411 NC4 415-80728 A	K215T30019 C K215T30035 NC	2003 to 2005, 2008, 2009, 2012, 2016, 2017, 2019 to 2023, and 2026 to 2050		
4079	Aug. 95	Replacement of the Air Data Computer (ADC) Placard	415-80392 NC		2001 to 2022	C/O	34
	Oct. 96	Info Sheet			2001 to 2019 and 2022		
4080	May 96	Introduction of Parker Gull Integrated Instrument Display System (IIDS)	415-80405 E		2001 to 2020	R	31
	June 96	Rev. 1	415-80405 H		2001 to 2019		
	June 97	Rev. 2	415-80405 H 415-80636 B	K215T64045 E	2001, 2002, 2007, 2010, 2011, 2013 to 2015, and 2018		
	April 14	Rev. 3	415-80405 H 415-80636 B 415-79617 A-1	K215T64045 H	2001 to 2027 and 2029		

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4081	June 95	Modification to the Landing Gear Control Handle Wiring Harness	415-80391 NC		2001, 2006, and 2007	R	32
	Aug. 95	Rev. 1	415-80391 A		2001 to 2009 and 2012		
	March 96	Info Sheet			2001, 2003 to 2009, and 2012		
4082	June 95	Identification of the Collector Tank Shut-Off Valve Positions	415-80393 NC	215T64057, EO B-2	2001, 2006, and 2007	RBD	28
4083	June 95	Replacement of the Compressor Wash Option Decal	415-80243 NC		2001, 2002, 2005 to 2007, and 2010 to 2018	R	71
4085	Jan. 97	Installation of Guides for the Pressure Relief Valve	415-80568 A		2001 to 2035		
4086	Oct. 95	Installation of the AFT Hydraulic Bay Floor	415-80281 A		2003, 2004, 2008, and 2009	C/O	53
	April 96	Rev. 1	415-80281 B	215T32001 A-1	2001 to 2990		
	Dec. 96	Info Sheet			2001 to 2026 and 2028 to 2990		
	Feb. 98	Proposal Sheet			2001 to 2990		

CL-415



MODEL CL-215-6B11 (415)
 SERVICE BULLETIN INDEX
 PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	Feb. 00	Info Sheet			2001 to 2026, 2028 to 2044, and 2049 to 2990		
	April 10	Info Sheet	415-80281 B-4		2001 to 2026, 2028 to 2044, 2049 to 2971, and 2076 to 2990		
4087	April 98	Installation of a Fuel Drain Quick Disconnect	415-80813 A	K215T60502 D	2001 to 2022	R	28
	Feb. 98	Proposal Sheet			2001 to 2022		
4088	Oct. 95	Installation of a Permanent Propeller-Balancing Harness	415-80434 A		2003, 2004, 2008, and 2009	C/O	61
	Dec. 97	Rev. 1	415-80434 D		2001 to 2990		
	Feb. 98	Rev. 2	415-80434 D				
	Feb. 98	Proposal Sheet			2001 to 2990		
	Aug. 98	Rev. 3	415-80434 E		2001 to 2990		
	Oct. 98	Info Sheet	415-80434 F				
	Dec. 99	Rev. 4	415-80434 G				
	Oct. 04	Rev. 5	415-80434 H				

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	Feb. 07	Rev. 6	415-80434 K	K215T50034 F K215T50035 G			
	April 08	Info Sheet					
	Mar. 13	Info Sheet	415-79044 B 415-80434 K	K215T50034 F K215T50035 J			
4089	Sept. 95	Installation of Power-Lever Witness-Marking Decals	415-80407 NC	215T93800, EO B-16	2001 to 2022	C/O	76
	Oct. 96	Info Sheet			2001 to 2019 and 2022		
4090	July 95	Replacement of the Rudder Trim Compensator Unit (RTCU)	415-80425 NC	K215T53001-6 A	2001, 2006, and 2007	R	22
4091	June 97	Replacement of the Airspeed Limitations Placards	415-80647 NC		2001 to 2031	R	20
	Oct. 97	Info Sheet					
4092	Jan. 00	Replacement of the Water Door Proximity Switches	415-80850 E		2001 to 2990	R	42
	Nov. 01	Rev. 1	415-80972 A 415-80981 A 415-80925 F 415-80850 G-1		2001 to 2065		

CL-415



MODEL CL-215-6B11 (415)
 SERVICE BULLETIN INDEX
 PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF	
4093 A4094	July 02	Rev. 2	415-80972 A 415-80981 A 415-80925 G 415-80850 G-1		2001 to 2065			
	Oct. 02	Info Sheet						
	Dec. 05	Info Sheet	415-80925 H		2001 to 2062			
	Nov. 09	Rev. 3	415-80972 A 415-80981 A-2 415-80925 L 415-80850 G-1	K215T26003 H (Kit 215-4092 basic) K215T51511 F (Kit 215-4092A) K215T51512 G (Kit 215-4092A and B)	2001 to 2065			
			Service Bulletin Cancelled					
	Sept. 96	Introduction of Automatic Battery/Essential Bus Tie Modification Rev. 1 (Issue NC proof instl only)	415-80532 L		2001 to 2022	R	24	
	Feb. 97	Rev. 2	415-80532 M-1 415-80697 A (415-80470 D A/C 2012 only)					
Oct. 02	Rev. 3	415-80532 M-1 415-80697 D (415-80470 D A/C 2012 only)	K215T51026 K K215T51024 B (For A/C 2012 only)	2001 to 2036				

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4095	Oct. 95	Installation of a WX-1000 Stormscope	415-80439 B	K215T70302 NC	2005	C/O	34
4096	Oct. 95	Installation of an Observer Seat	415-80439 B		2005	C/O	25
	April 97	Rev. 1	415-80702 A		2029		25
	Nov. 00	Rev. 2	415-81070 A	K215T40032 A	2051		25
4097	April 97	Software Update to Parker Gull Electronic System Division (GESD) Integrated Instrument Display System (IIDS)	415-80636 C		2001 to 2029		31
	April 97	Info Sheet			2001 to 2027 and 2029		
	June 97	Rev. 1	415-80636 C-1	K215T51040 A	2001 to 2027 and 2029		
4098	May 97	Installation of Corrosion Protective Tape on the Engine Intake V-Band Coupling	415-80678 A		2001 to 2031	R	30
4099	June 96	Miscellaneous Improvements to the Two-Pump Foam System	415-80511 B	K215T40033 A	2001, 2002, 2006, 2007, 2010, 2011, 2013, to 2015, 2018, 2024, and 2025	C/O	42
	Sept. 96	Info Sheet					

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4100	June 96	Miscellaneous Improvements to the One-Pump Foam System	415-80459 NC 415-80481 A	K215T33001 NC K215T40034 A	2003 to 2005, 2008, 2009, 2012, 2016, 2017, 2019 to 2023, and 2026 to 2030	C/O	42
4101	Jan. 96	Installation of a Caution Decal for the Attitude and Heading Reference System (AHRS) Unit	415-80464 NC	K215T52010 NC	2001 to 2027	C/O	34
	Oct. 96	Info Sheet			2001 to 2024, 2026, and 2027		
	Dec. 96	Info Sheet			2001 to 2024		
4102	May 97	Modification to the Flapper Door	415-80650 A-1		2001 to 2043	R	42
	Nov. 97	Rev. 1	415-80650 B				
	Feb. 98	Rev. 2	415-80650 D				
	March 98	Info Sheet			2001 to 2033, and 2040 to 2043		
	April 99	Rev. 3	415-80650 D 415-80811 C	K215T28036 D	2001 to 2043		
4103	Feb. 96	Replacement of the Probe Down Microswitches	415-80258 A		2001 to 2012	R	42

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4104	Sept. 96	Installation of a Flip Guard for the Onboard Compressor Wash Pump Switch	415-80457 NC-1		2001, 2002, 2006, 2007, 2010, 2011, 2013 to 2015, 2018, 2024, and 2025	C/O	71
4105	Oct. 97	Modification to the Direct Vision (DV) Window Drains	415-80643 C	K215T30019 C	2001, 2002, 2006, 2007, 2010, 2011, 2013 to 2015, 2018, 2024, and 2025	C/O	53
	Dec. 11	Info Sheet			2001 to 2990		
4106	Aug. 96	Improved access to Elevator-Actuator Rod-End Attachment-Bolt	415-80371 NC 415-80165 NC		2001 to 2024	R	55
4107	Jan. 96	Replacement of the Foam Tank Access Panels	415-80236		2001 to 2025	R	42
	Oct. 96	Info Sheet			2001 to 2024		
	March 97	Rev. 1	415-80236 NC1 415-80676 A		2001 to 2026		
4108	Nov. 95	Replacement of the Lower Finlet L/E Skins	415-80435 NC		2001 to 2028	R	55
	Oct. 96	Info Sheet			2001 to 2019, 2022 to 2024, and 2026 to 2028		

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	Dec. 96	Info Sheet			2001 to 2019, 2022 to 2024, and 2028		
	April 97	Info Sheet			2001 to 2019, 2022 to 2024,		
4109	Jan. 96	Incorporation of Control Assembly (C/A) B9860 on Aircraft 2002	B9860		2002		N/A
	April 96	Rev. 1					
4110	Feb. 96	Installation of a Packer on the Hydraulic-Accumulator Access Door	415-80478 A		2001 to 2009 and 2011 to 2025	R	53
	Oct. 96	Info Sheet			2001 to 2009 and 2011 to 2024		
4111	Aug. 01	Replacement of the Main Landing Gear (MLG) and Nose Landing Gear (NLG) Harnesses	415-80736 G		2001 to 2050	R	32
	Aug. 01	Info Sheet					
	March 05	Rev. 1	415-80736 K 415-81233 A				
	May 05	Rev. 2	415-80736 K 415-81283 A				

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	Jan. 06	Rev. 3		215-85000, RNIEO 601 215-85000, RNIEO 602 (supersedes 215-85000, RNIEO 601) 215-85000, RNIEO 603 215-85000, RNIEO 604 (supersedes 215-85000, RNIEO 602 and 603) 215-85006, RNIEO 601 215-85006, RNIEO 602 (supersedes 215-85006, RNIEO 601) 215-87500, RNIEO 604 215-87500, RNIEO 605 (supersedes 215-87500, RNIEO 604) 215-87500, RNIEO 607 215T58019, RNIEO 601 and 602			
4112	June 96	Replacement of the Magnaghi Servo Actuators	415-80416 A		2001 to 2024	M	27
	Aug. 96	Rev. 1	415-80416 A		2001 to 2024		
4113	July 97	Application of External Paint Scheme and Markings for the Italian Aircraft	415-80664 A-1	215T40475 C 215T40476 NC	2003, 2004, 2008, 2009, 2020 and 2021	R	11

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	Feb. 98	Info Sheet			2003, 2004, 2008, 2009, 2020, 2021, 2029 and 2030		
4114	July 96	Refrigerant Conversion in the Air Conditioning System	415-80503 A		2001 to 2030	C/O	21
	Dec. 96	Info Sheet			2001 to 2025 and 2027 to 2030		
4115	Feb. 98	Installation of a Backup O-Ring on the Starter/Generator Proposal Sheet			2001 to 2990	R	24
4116	Feb. 96	Replacement of the Water Door Isolator Valve	415-80424 NC-1		2001, 2003 to 2009, and 2012	R	42
4117	May 97	Installation of Additional Parameters to the Flight Data Recorder (FDR)			2001, 2002, 2006, 2007, 2010, 2011, 2013 to 2015, 2018, 2024, and 2025	R	31
	April 99	Rev. 1	415-80498 F	K215T52011 E			

CL-415



MODEL CL-215-6B11 (415)
 SERVICE BULLETIN INDEX
 PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4118	June 01	Auxiliary Power Unit (APU) Control Panel Relocation in Accordance with Limited Supplemental Type Certificate (LSTC) No. Q-LSA01-023 (415-4118 This is an Installation Instruction Document, not a Service Bulletin)			2001, 2002, 2006, 2007, 2010, 2011, 2013 to 2015, 2018, 2024, and 2025	C/O	49
4119	Oct. 97	Relocation of the Foam Tank Vent Pipe	415-80534 B		2001 to 2038	R	42
	Sept. 98	Rev. 1	415-80534 E		2001 to 2043		
	Feb. 99	Rev. 2	415-80534 F				
	March 04	Rev. 3	415-80534 H	K215T40036 F			
	July 04	Info Sheet					
4120	Feb. 96	Installation of Dual Power Supply	415-80470 C	K215T51024 A	2012	R	24
	March 96	Info Sheet					
4121	Dec. 02	Modification to the Foam Selector Valves (One Pump System)	415-80765 B	K215T40045 A	2003, to 2005, 2008, 2009, 2012, 2016, 2017, 2019 to 2023, and 2026 to 2040	R	42
4122	March 96	Provision for Lockwiring the Uplock Actuator Hose Assemblies	415-80446 NC	K215T26000 NC	2001 to 2024	C/O	42

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4123	May 96	Replacement of the Emergency-Brake Control Cable	415-80460 NC 415-80502 A		2001 to 2030	C/O	32
	Feb. 98	Proposal Sheet			2001 to 2030		
4124	June 96	Removal of a Fouling Nutplate from the Floor-Seal Assembly	415-80112 NC		2001 to 2004, 2006, 2008 to 2010	R	42
4125	April 96	Replacement of the sealing Nut and Retainer in the Motive Flow Line	415-80440 NC		2001 to 2019	R	73
4126	April 96	Installation of a Propeller-Restraint Attachment Bracket	415-80428 A		2001 to 2017	C/O	25
	Feb. 97	Rev. 1	415-80428 A 415-80666 A		2001 to 2028		
4127	Feb. 98	Installation of an On-Board Compressor Wash Pump (One Foam Tank Configuration) Proposal Sheet			2001 to 2990 with 1 foam tank configuration	C/O	71
4128	Aug. 96	Replacement of the Spring in the Artificial Feel Spring-Pot Assembly	415-80516 A		2001, 2002, 2006, 2007, 2010, 2011, 2013 to 2015, 2018, 2024, and 2025	C/O	27
	Feb. 98	Proposal Sheet			2001 to 2025		

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	June 03	Info Sheet	415-80516 A-2		2001, 2002, 2006, 2007, 2010, 2011, 2013 to 2015, 2018, 2024, 2025, and 2055 to 2057		27
	Feb. 06	Rev. 1	415-80516 C-1		2001 to 2990		
	July 06	Rev. 2	415-80516 C-1				
	April 07	Info Sheet	415-80516 C-2		2001 to 2064 and 2066 to 2990		
	Oct. 07	Info Sheet	415-80516 C-3		2001 to 2990		
	Feb. 09	Rev. 3	415-80516 C-3 415-78720 A-1		2001 to 2990		
	June 09	Rev. 4	415-80516 C-3 415-78720 A-1	K215T92303 A	2001 to 2990		
	June 11	Info Sheet	415-80516 C-3 415-78720 A-1 415-79185 A1				
	April 12	Rev. 5	415-80516 C-3 415-78720 A-1 415-79185 A-2 415-79374 A 415-79479 A	K215T92303 C			

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
A4130	Oct. 13	Rev. 6 Service Bulletin No. 215-A4130 Cancelled. Only Alert Wire 215-A4130 was issued See Service Bulletin 215-4332 when available	415-80516 C-3 415-78720 A-1 415-79185 A-2 415-79374 A 415-79479 A 415-79656 A	K215T92303 D			
4131	Sept. 96	Installation of Up-Lock Priority Valves	415-80625 A		2001 to 2030	R	42
	April 97	Rev. 1		K215T26001 NC	2001 to 2027 and 2029 to 2033		
	April 97	Info Sheet			2001 to 2027 and 2029		
4132	June 96	Installation of an Enable/Disable Switch in the Water Drop Control System	415-80561 A	K215T51028 NC	2001 to 2009	C/O	42
4133	April 98	Replacement of the Water Drop Control (WDC) Panel	415-80752 A1		2001 to 2990	R	42
	March 99	Rev. 1	415-80752 A-1 415-80849 B				
	Nov. 99	Rev. 2	415-80846 A-1 415-80752 A-2 415-80849 B-1	K215T51034 A	2001 to 2044		

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4134	Jan. 98	Circuit Improvements Added to Prevent False/Misleading Indications	415-80549 A 415-80551 A 415-80552 A		2001 to 2027	R	27 30
	Sept. 98	Rev. 1					
	Aug. 03	Rev. 2	415-80549 A 415-80551 A 415-80552 A 415-80861 A	K215T51027 NC K215T51033 NC K215T51032, RNIEO 602			
4135	Sept. 96	Installation of a Metric Graduation Scale on the Fuel Dipstick	415-80537 A	K215T64067 NC	2001 to 2039	C/O	25
	April 97	Info Sheet	415-80537 A-1		2001 to 2027 and 2029 to 2039		
	Feb. 98	Proposal Sheet			2001 to 2039		
	Nov. 98	Info Sheet	415-80537 B		2001 to 2039		
	Aug. 00	Info Sheet	415-80537 B-1		2001 to 2041		
4136	Feb. 98	Installation of Evaporator/Blower Insulation Blankets Proposal Sheet			2001 to 2990	R	26
4137	Nov. 02	Replacement of the Foam Vacuum Relief Valve	415-80754 B	K215T40038 A	2001 to 2045	R	42

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4138	May 97	Modification to the Fuel Cell Interconnect Drain System	415-80533 B	K215T64055 A	2001 to 2038	R	28
	July 99	Info Sheet					
4139	Jan. 01	Modification to the Oil Cooler Fairing Structure	415-80994 A		2001 to 2057	C/O	57
	Oct. 02	Rev. 1	415-80994 A 415-81176 A	215T13000, RNIEO 601	2001 to 2990		
	Dec. 05	Info Sheet	415-81176 B		2001 to 2062		
4140		Service Bulletin Cancelled					
4141	Dec. 96	Modification to the Pressure Refueling System	415-80284 NC		2001 to 2023	R	28
4142	Oct. 96	Material Change of the AFT Hydraulic Bay Bulkhead Tee Fitting	415-80259 NC		2001 to 2024	R	29
4144	Sept. 03	Inspection/Rework of the Elevator Normal Trim Actuator Programming Lever	415-80544 B		2001 to 2020 and 2031 to 2042	R	27
4146	Jan. 97	Special Inspection – Missing Rivets at Bulkhead FS 234.5, RBL 48.0, WL 140.0	415-80640 A		2001 to 2026	R	53
	March 97	Info Sheet					

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1



215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4147	Feb. 01	Modification to the Foam Selector Valves	415-80765 A		2001, 2002, 2006, 2007, 2010, 2011, 2013 to 2015, 2018, 2024, and 2025	R	42
	Dec. 02	Rev. 1	415-80765 B	K215T40045 A	2001, 2002, 2006, 2007, 2010, 2011, 2013 to 2015, 2018, and 2024		
4148		Service Bulletin Cancelled					
4149	July 97	Replacement of the Restrictor Assemblies for the Water Door Actuators	415-80625 D	K215T26002 NC	2001 to 2027 and 2029	R	42
4150	July 97	Application of External Paint and Registration Markings for Aircraft Serial No. 2028	415-80692 A-1	215T40471, NIEO 1 215T40472, NIEO 1 215T40473, NIEO 2	2028	R	11
4151	July 97	Application of a Protective Coating on the Water Door Proximity Switches	415-80689 B		2001 to 2035	R	42
4152	Oct. 98	Installation of a Check Valve and a Relief Valve in the Powered Rudder Hydraulic System	415-80722 C-2	K215T75082 A	2001 to 2036	R	27
4153	May 97	Installation of Centre Pedestal Support Struts	415-80714 A		2024	R	53
	Feb. 00	Rev. 1	415-80714 E	K215T93805 B	2001 to 2990	R	53

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4154	June 97	Installation of an Onboard Compressor/Turbine Wash System (Two Foam Tank Configuration)	415-80690 A 415-80717 A		2003 to 2005, 2008, 2009, 2012, 2016, 2017, 2019 to 2023, and 2026 to 2990	C/O	71
	May 98	Rev. 1	415-80717 C				
	Aug 98	Proposal Sheet			2003 to 2005, 2008, 2009, 2012, 2016, 2017, 2019 to 2023, and 2026 to 2990		
	May 06	Rev. 2	415-80717 C1 415-80948 C1	K215T60520 E	2003 to 2005, 2008, 2009, 2012, 2016, 2017, 2019 to 2023, 2026 to 2045 and 2047 to 2990		
4155	April 98	Installation of a Diode in the LH Pump Power Legend	415-80703 B	K215T51030 B	2001 to 2036	R	28
4156	Oct. 97	Addition of a Washer on the Aileron Control Rod	415-80726 A		2001 to 2040	R	27
	June 01	Rev. 1	415-80726 B	K215-92100 B			

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4157	July 99	Replacement of the Accumulator Pressure Gauge	415-80799 A		2001 to 2040	R	27 32
	March 00	Info sheet					
	Aug. 00	Info Sheet					
	Feb. 07	Rev. 1	415-80799 B	K215T75251 A			
	Oct. 08	Info Sheet					
4158		Service Bulletin Cancelled					
4159	Nov. 04	Oil Cooler Corrosion Protection	415-80655 B		2001 to 2050	R	79
	Jan. 06	Rev. 1					
	Jan. 07	Rev. 2					
	Aug. 07	Rev. 3		K215T63013 NC			
4160	May 98	Addition of Corrosion Protection to the Navigation Tail Light Assembly Proposal Sheet			2001 to 2990	R	33
4161		Service Bulletin Cancelled					

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4162	May 99	Installation of a Third Crewmember Intercom Proposal Sheet			2001 to 2990 except for A/C with option CR23-025 installed	C/O	23
	June 99	Installation of a Third Crewmember Intercom	415-80803 B		2003 to 2005, 2008, 2009, 2012, 2016, 2017, 2019 to 2023, and 2026 to 2990		
	May 03	Rev. 1	415-80803 F		2003 to 2005, 2008, 2009, 2012, 2016, 2017, 2019 to 2023, and 2026 to 2050		
	Nov. 09	Rev. 2	415-80803 G	K215T51205 F	2003 to 2005, 2008, 2009, 2012, 2016, 2017, 2019 to 2023, and 2026 to 2050		
	Nov. 12	Rev. 3	415-80803 G 415-79671 A	K215T51205 G	2001 to 2990		

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	Dec. 15	Rev. 4	415-80803 H 415-79671 A	K215T51205 H	Aircraft Validity: 2001 to 2050 (without Customer Option CR 23-025) Service Effectivity: 2038, 2042, 2044, and 2050		
4163	Jan. 98	Replacement of the Flap Position Indicator	415-80789 A	K215T51301 NC	2001 to 2050	C/O	27
	Aug. 98	Proposal Sheet			2001 to 2050		
	Feb. 06	Info Sheet	415-80789 C		2001 to 2990		
4164	Sept. 98	Installation of Speed Bugs on the Airspeed Indicator (ASI)	415-80786 A	K215T51302 NC	2001 to 2990	C/O	34
	Oct. 98	Proposal Sheet			2001 to 2990		
	March 10	Info Sheet	415-80786 D				
4165	Nov. 99	Addition of High Cam Light Indicators on the Engine Control Panel	415-80788 D		2001, 2002, 2006, 2007, 2010, 2011, 2013 to 2015, 2018, 2024, and 2025	C/O	31
	Nov. 98	Proposal Sheet			2001 to 2990		

CL-415



MODEL CL-215-6B11 (415)
 SERVICE BULLETIN INDEX
 PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	Aug. 00	Info Sheet					
	March 05	Rev. 1	415-80788 E 415-81218 A				
	Nov. 10	Rev. 2	415-80788 F 415-81218 A-2	K215T51055 D-1			
	June 14	Rev. 3	415-80788 F 415-81218 A-2 415-79685 A	K215T51055 E			
	Nov. 14	Rev. 4	415-80788 F 415-81218 A-2 415-79685 A 415-79956 A	K215T51055 F	Aircraft Validity: 2001 to 2990 Service Effectivity: 2001, 2002, 2006, 2007, 2010, 2013 to 2015, 2024, 2057, 2063, 2065, 2076, 2077, 2078, 2080, to 2083, 2085, 2086, 2091		
4166	May 04	Installation of a Foam Pump Injection Failure Indication	415-80796 E	K215T51060 D	2001, 2002, 2006, 2007, 2010, 2011, 2013 to 2015, 2018, 2024, and 2025	C/O	42

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1



215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	Sept. 04	Info Sheet			2001, 2002, 2006, 2007, 2010, 2011, 2013 to 2015, 2018, 2024, 2025, and 2057		
	Dec. 05	Info Sheet	415-80796 F-1		2001, 2002, 2006, 2007, 2010, 2011, 2013 to 2015, 2018, 2024, 2025, 2057 and 2063		
	Feb. 07	Info Sheet	415-80796 G-1		2001, 2002, 2006, 2007, 2010, 2011, 2013 to 2015, 2018, 2024, 2025, 2057, 2063, and 2065		
	Dec. 11	Rev. 1	415-80962 E 415-80796 G-1 415-78970 A-1	K215T30047 C K215T51060 G			
4167	May 98	Installation of an Access Panel for the Rudder Actuator Proposal Sheet			2001 to 2990	C/O	53

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4168	Feb. 00	Installation of an Access Panel for the Rudder Actuator	415-80962 A		2001 to 2990		
	Jan. 09	Rev. 1	415-80962 E	K215T30047 C			
	March 99	Addition of Short Protection to the Battery Charger System	415-80780 C		2001 to 2042	R	24
	April 99	Rev. 1	415-80780 D-1				
	Oct. 99	Info Sheet					
	Oct. 01	Rev. 2		415-80780 E 415-80992 D	K215T52210 H	2001 to 2059	
4169	Jan. 03	Info Sheet					
		Service Bulletin Cancelled					
4170	Oct. 97	Installation of a Rescue Boat Handling Package	415-80784 A 415-80785 A	215-30160, DVNIEO 2 215T00001, RNIEO 608 and 609	2031	C/O	25
4171	Dec. 97	Addition of Anti-Skid Paint to the Top of the Aircraft	415-80783 A		2001 to 2990	C/O	11
	July 99	Rev. 1	415-80783 B	K215T40480 A			
4172	June 98	Relocation of the Left-Hand Nacelle External Engine Wash Coupling Proposal Sheet			2001 to 2990	C/O	71

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	Feb. 99	Relocation of the Left-Hand Nacelle External Engine Wash Coupling	415-80764 C		2001 to 2990	C/O	71
	May 99	Info Sheet					
	March 00	Info sheet					
	Feb. 01	Info sheet					
	July 04	Rev. 1		K215T60700 B			
	Dec. 10	Info sheet	415-80764 D 415-79252 A				
	Oct. 14	Rev. 2	415-80764 D	K215T60700 C			
4173	April 98	Replacement of the List of Content Decal for the Spare Bulb Kit	415-80794 A		2001 to 2039	R	25
	May 99	Rev. 1	415-80794 B	K215T52118 A			
4174	Feb. 98	Installation of a Metric Ground Fill Adaptor	415-80807 A	215T27016, RNIEO 601	2029 and 2030	C/O	42
	Oct. 98	Info Sheet	415-80807 A-1		2029, 2030, 2035, and 2036		
	May 01	Info Sheet	415-80807 A-2		2029, 2030, 2035, 2036, and 2051		

CL-415



MODEL CL-215-6B11 (415)
 SERVICE BULLETIN INDEX
 PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4175	Nov. 03	Info Sheet	415-80807 A-3		2029, 2030, 2035, 2036, 2051, 2059, 2060, and 2062		
	Sept. 04	Info Sheet	415-80807 A-4		2001 to 2990		
	Dec. 05	Info Sheet	415-80807 C				
	Feb. 98	Application of Italian Internal/External Markings and Paint Scheme	415-80664 A-2 415-80776 A-1		2029 and 2030	C/O	11
	March 98	Rev. 1	415-80664 -2 415-80776 A-1 415-80519 A-1 415-80808 A 415-80814 A				11
	May 01	Rev. 2	415-80664 C 415-80776 A-3 415-80519 A-1 415-80808 B 415-80814 A-1	215T40474 F, NIEO 2 215T40475 C 215T40476 E, NIEO 4 K215T40020, RNIEO 601 215-40530, RNIEO 601 and 602 215T52024, EO NC-6 215T40700 H	2029, 2030, 2035, and 2036		11
	May 05	Info Sheet	415-80664 C-1 415-80776 A-4 415-80808 B-1 415-80814 A-2		2029, 2030, 2035, 2036, and 2058		

CL-415



MODEL CL-215-6B11 (415)
 SERVICE BULLETIN INDEX
 PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4176	May 05	Installation of an Auto Probe Retraction System	415-81219 A		2057	C/O	42
	Dec. 05	Info Sheet	415-81219 A-1		2057 and 2063		
	March 07	Rev. 1	415-81219 E	K215T93810 C	2057, 2063, and 2065		
	Aug. 10	Info Sheet	415-81219 E-1		2057, 2063, 2065, and 2076 to 2990 2001 to 2990		
4183	April 00	Installation of a VHF/FM Press-To-Talk (PTT) Feature on the Pilot and Copilot Control Handwheel Proposal Sheet				C/O	23
	May 00	Installation of a VHF/FM Press-To-Talk (PTT) Feature on the Pilot and Copilot Control Handwheel	415-80827 C				
	March 05	Rev. 1	415-80827 E	K215T51046 D			
A4184	March 99	Special Inspection and Modification of the High Current Feed Thru in the MDC	415-80810 B		2001 to 2044	R	24
	Feb. 00	Rev. 1	415-80810 D	K215T52180 B (RSI) C-3160 A			

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4185	July 98	Re-Inforcement of the Wing Leading Edge	415-80787 B		2001 to 2990	R	57
	March 99	Rev. 1	415-80787 C	K215T11503 A 215T11514 NC-2	2001 to 2050		
	May 00	Info Sheet			2001 to 2052		
4186	April 98	Application of External Paint and Registration Markings for the Ontario Ministry of Natural Resources	415-80817 B		2034	R	11
	June 99	Rev. 1	415-80817 D 415-80844 A	215T40483 D 215T40484 D 215T40472 E 215T40471 E	2028, 2031 to 2034, and 2037		
4187	April 98	Temporary Installation of a Garmin 165 Global Positioning System (GPS)	-	K215T51020, RNIEO 601	2028, and 3031 to 2034		34
	April 98	Rev 1		K215T51020, RNIEO 601 and 602			
	March 99	Info Sheet					
4188		Service Bulletin Cancelled					
4189	Oct. 98	Re-Inforcement of the Bottom Frame (at FS 296.25, 315.0, 333.75, and 352.50)	415-80806 C		2001 to 2990	C/O	53
	Nov. 98	Info Sheet					
	Jan. 99	Rev. 1	415-80806 E				

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	Aug. 99	Rev. 2	415-80806 F				
	Jan. 01	Info Sheet			2001 to 2044		
	Nov. 05	Rev. 3	415-80806 F-1	K215T31000 E			
	July 12	Info Sheet #4			2001 to 2044		
4190	Aug. 00	Replacement of the Hydraulic, Brake, and Rudder Pressure Transducers	415-80818 C 415-81027 A	K215T75027 NC	2001 to 2048	R	27
4191	Feb. 00	Installation of a Decal on the Electrical Outlets	415-80833 A	K215T53210 NC	2001 to 2050	R	24
A4192	Feb. 99	Replacement of Dome Nut Rivets on Ejector Pump Collector Tank	415-80828 A	215T64186 D-2 215T64059 NC-12	2001 to 2040	R	28
4193	Oct. 98	Installation of Access Covers to Flood Switch and Probe Microswitches Proposal Sheet			2001 to 2990	C/O	53
	March 06	Installation of Access Covers to Flood Switch and Probe Microswitch	415-81287 A	K215T40275 NC			
	April 10	Info Sheet	415-81287 A-1				
	Jan. 12	Rev. 1	415-81287 A1 415-79491 A	K215T40275 A			
4194	July 99	Relocation of the Boarding Ladder and Boarding Handle Stowage Retaining Straps	415-80834 A	K215T40040 NC	2001 to 2046	R	25

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4195	Jan. 03	Installation of a Forward Looking Infrared (FLIR) system	415-81116 H 415-90904 G		2001 to 2990	C/O	42
	May 04	Rev. 1	415-81116 K 415-90904 G				
	Feb. 06	Rev. 2	415-81116 M 415-80904 H	K215T33517 D, RNIEO 601 (for A/C 2001 - 2990) K215T51300 E, (RNIEO 601 for A/C 2034 only) K215T50400 E K215T51500 A, (RNIEO 601 for A/C 2028, 2031-2034, 2037, 2038, 2040 and 2043 only) K215T51502 NC 215T50626, RNIEO 604 (for A/C 2001-2990)			
4196		Service Bulletin Cancelled					
4197		Service Bulletin Cancelled					
4198		Service Bulletin Cancelled					
4199		Service Bulletin Cancelled					
4200		Service Bulletin Cancelled					

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
A4201	July 99	Special Inspection and Modification to the Fuel Drain Line Assemblies in the Front and Rear Spar Area	415-80909 A		2001 to 2042	R	28
	Aug. 99	Rev. 1	415-80843 A415-80909 A				
	May 03	Rev. 2	415-80843 A 415-80909 A-1 415-80990 C 415-80991 A	K215T64055 F and RNIEO 603, 605, and 606 K215T64068 NC and RNIEO 601 (RSI) C-3169, C-3170, and C-3180			
4202	Feb 99	Installation of Improved Flight Control Handwheels	415-80605 A	K215T90500 NC	2001 to 2990	C/O	27
4203	July 01	Special Inspection/Replacement of Grimes Aerospace Four-Way Solenoid Operated Valve Identification Plates with Duplicate Serial Numbers	415-80731 A-1	(RSI) C-3148 NC	2001 to 2036	R	29 32
	Oct. 01	Info Sheet					
4204	Jan. 99	Inspection of the Main Landing Gear (MLG) Uplock Hook (Héroux Part No. 160-408)	-		2001 to 2040	R	32
4205	Jan. 00	Replacement of Analog Output Modules (AMO) Mounting Plate and Hardware	415-80852 A	K215T26061 NC	2001 to 2990	R	42
	Nov. 00	Info Sheet			2001 to 2050		

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4206	April 99	Inspection and Modification of the Engine Intake Adaptor Heater Harness	415-80855 A	K215T58202 NC (RSI) C-3172	2001 to 2040	R	30
	Jan. 00	Info Sheet					
4207	March 00	Special Inspection and Modification to the Aileron Cable Installation (Rear Spar WS 236.09 and WS 152.80)	415-80857 C-1		2001 to 2057	R	27
	Jan. 01	Info Sheet					
	Oct. 02	Info Sheet	415-80857 D-1		2001 to 2057 and 2060		
	Oct. 03	Rev. 1	415-80857 D-3	K215T92100 D	2001 to 2990		
	Oct. 05	Info Sheet					
	Sep. 11	Info Sheet					
	March 12	Info Sheet					
	Jan. 16	Rev. 2	415-80857 D-5 415-81195 B-7		Aircraft Validity: 2001 to 2990 Service Effectivity: 2001 and 2062		
4208		Service Bulletin Cancelled					
4209	April 99	Inspection of Packing in the Cabin Heater Fire Extinguisher Installation	-		2001 to 2040	R	26

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4210	Aug. 03	Removal of Flap Asymmetry False Indication – Kit Improvement	415-80865 A	215T58100, RNIEO 601	2028 to 2990	R	27
	March 10	Info Sheet	415-80865 E-1		2028 to 2072 and 2075 to 2990		
	Dec. 05	Info Sheet	415-80865 C				
4211	Nov. 99	Addition of Seal to the Pilot Escape Hatch	415-80920 A		2001 to 2990	R	52
	Sept. 04	Rev. 1	415-80920 A 415-81206 A	K215T33501 A	2001 to 2062		
	Dec. 05	Info Sheet	415-80920 A 415-81206 C		2001 to 2990		
	June 09	Info Sheet					
4212		Service Bulletin Cancelled					
4213	April 99	Special Inspection of the Adaptor Heater Contactors (1K2HA / 2K2HA)	-	(RSI) C-3167	2001 to 2039	R	24
4214	Oct. 99	Replacement of Bus Bars 1W8PA and 2W8PA with Wires	415-80870 A	K215T52184 NC	2001 to 2036		24
	Nov. 01	Info Sheet					
4215	Sept. 99	Replacement of Washers in the Battery Junction Box (JB) and Generator Boxes 1 and 2		K215T52183 NC	2001 to 2044	R	24

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4216	March 00	Relocation of ESS/BATT Lock-out Contactor Circuit Breaker	415-80901 B		2001 to 2036	R	24
	Jan. 02	Rev. 1	415-80901 C				
	Oct. 02	Rev. 2	415-80901 C	K215T52185 C			
A4217	Nov. 99	Special Inspection of the Rudder Torque Flange	-	(RSI) C-3182	2001 to 2990	R	27
4218	Oct. 00	Addition of Short Circuit Protection to the Battery Direct Bus Feed Line Wires	415-80893 B	K215T52110 A (RSI) C-3177	2001 to 2050	M	24
4219	July 99	Inspection of the Pilot and Copilot Seat Height Control System	415-80903 A		2001 to 2042		25
4220	Dec. 00	Replacement of the Radio Altimeter Antennas	415-80897 C	K215T70029 B	2001 to 2050	R	34
	July 13	Rev. 1	415-80897 E 415-81317 A 415-79091 A	K215T70029 D			
	Aug. 13	Rev. 2	415-80897 E 415-81317 A 415-79091A 415-79824 A	K215T70029 E	2001 to 2990		

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	Nov. 14	Rev. 3			Aircraft Validity: 2001 to 2990 Service Effectivity: 2027, 2042, 2044, 2047, 2049, 2050, 2052 to 2054, 2056, 2057, 2063, 2065, 2077, 2081, 2085, and 2087 to 2091		
	Oct. 15	Rev. 4			Aircraft Validity: 2001 to 2990 Service Effectivity: 2027, 2041, 2042, 2044, 2046, 2047, 2049, 2050, 2052 to 2054, 2056 to 2060, 2063, 2065, 2066, 2070, 2073, 2074, 2077, 2081, 2085, and 2087 to 2091		

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4221	June 99	Installation and Removal of the Rescue Boat Deployment Package	415-80912 A 415-80913 A	215T00001, RNIEO 611 DSD-00001 C DSD-00003 C	2041	C/O	25
4222	July 99	Installation of a Flat Seal and Drainage Improvements for the Direct Vision (DV) Window	415-80906 A 415-80914 B		2001 to 2990	R	56
	Nov. 05	Rev. 1	415-80906 A 415-80914 C				
	May 06	Rev. 2	415-80906 A 415-80914 D	K215-30102 NC (For Part A) K215T30040 B (For Part B) K215T30040, RNIEO 601 (A/C 2058 only)			
4223	Feb. 01	Modification to the Elevator Trim Override System Circuit	415-80879 D	K215T51400 NC K215T51401 B	2001 to 2050	R	24
4224	Jan. 01	Replacement of the Bus Bars, Terminal Lugs, and Feedthroughs in the Battery Junction Box and Generator Box No. 1 and No. 2	415-80905 F	K215T52190 B	2001 to 2050	M	24
	Nov. 01	Info Sheet					
4225	Oct. 02	Inspection of the High Current Ground Stud Doublers			2001 to 2036	R	24
	June 03	Rev. 1		(RSI) C-3161 A-2			
4226	Feb. 00	Adjustment of the Main Landing Gear Downlock Microswitches	-	(RSI) C-3166 NC-1	2001 to 2039	R	32

CL-415



MODEL CL-215-6B11 (415)
 SERVICE BULLETIN INDEX
 PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4227		Service Bulletin Cancelled					
4228	April 00	Replacement of the Fuel Cell Cover Bolts	415-80926 A		2001 to 2048	R	28
	Oct. 00	Info Sheet					
4229		Service Bulletin Cancelled					
4231	Dec. 99	Inspection/Installation of the Engine Control Cable Spacers in the Nacelle Area	-		2040 to 2042	R	76
4230	Feb. 04	Relocation of the Low Pressure (LP) Impeller Spray Nozzle for the Compressor Wash System	415-80911 B		2001 to 2990	C/O	71
	Jan. 07	Rev. 1					
	April 10	Info Sheet	415-80911 K				
	Nov. 10	Info Sheet					
	March 11	Rev. 2		K215T60704 A, EO A-1, EO A-2, and EO A-3 RNIEO 601, 602, and 603 (A/C 2065 only) RNIEO 604 and 605 (A/C 2063 and 2065 only)			

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	April 12	Info Sheet			2001, 2002, 2006, 2007, 2010, 2013 to 2015, 2024, 2057, 2063 and 2065		
4232	Dec. 99	Removal of Sodium Dichromate Bags from the Aircraft Hull	415-80929 A		2001 to 2043	C/O	53
	March 00	Rev. 1	415-80929 B	215T40000, RNIEO 602	2001 to 2042		
4233	Oct. 00	Replacement of the EFIS Power Diodes in Relay Panel "C"	415-80954 A		2001 to 2059	M	24
	May 01	Rev. 1		K215T51424 NC (RSI) C-3201			
	June 01	Info Sheet					
4234	March 01	Installation of a Backup Pressure Relief Valve and Replacement of Studs	415-80951 B	K215T60440 A (RSI) C-3200 NC	2001 to 2053	M	61
4235	Feb. 00	Improvement to the Water Door Bearing Housing	-		2001 to 2050	R	42
4236	May 01	Replacement of the Flight Deck Speakers Proposal Sheet	-		2001 to 2056	C/O	23
	April 01	Replacement of the Flight Deck Speakers	415-81001 C		2001 to 2056	C/O	23
	Oct. 09	Rev. 1	415-81001 D 415-79034 A	K215T51025 A			

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4237	May 03	Removal of HF Communication System and Stowage of Connectors	415-80946 B		2001, 2002, 2006, 2007, 2010, 2011, 2013 to 2015, 2018, and 2024	C/O	23
	March 04	Rev. 1					
	July 04	Rev. 2	415-80946 C	K215T52109 A	2001 to 2062		
	Sept. 05	Info Sheet					
	Dec. 05	Info Sheet	415-80946 C-1		2001 to 2024 and 2026 to 2990		
4241	Sept. 00	Addition of Sealant on the Water Level Sensor	415-80971 A	215T26061, RNIEO 601	2001 to 2051	R	42
4242	Feb. 01	Inspection of the Nose Landing Gear (NLG) Emergency Gear Down Priority Valves		(RSI) C-3207 A	2001 to 2990	M	32
	Nov. 14	Rev. 1 Inspection of the Nose Landing Gear (NLG) Emergency Gear Down Priority Valve		(RSI) C-3207 A-1	Aircraft Validity: 2001 to 2990 Service Effectivity: 2001 to 2990		
4243	Dec. 01	Installation of the Utility Handling System	415-81159 A		2001 to 2990	C/O	25
	May 05	Rev. 1		DSD-00009 NC DSD-00010 NC DSD-00011 A			

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4244		Service Bulletin Cancelled					
4245	Jan. 01	Inspection of Fasteners on the Pilot and Copilot Elevator Forward Torque Tube Input Quadrants	415-80983 B		2001 to 2054	M	27
	Feb. 01	Rev. 1		215T92578, RNIEO 601 (RSI) C-3206 A			
4246		Service Bulletin Cancelled					
4247	Nov. 00	Replacement of the Aircraft Hull Drain Plugs Proposal Sheet	-		2001 to 2099		53
	Sept. 04	Replacement of the Aircraft Hull Drain Plugs	415-80931 E	K215T34049 C	2001 to 2099	C/O	53
4248		Service Bulletin Cancelled					
4249	Aug. 06	Improved Sealing of the Hydraulic Servicing Panel and Fuel/Defuel Control Panel	415-81238 A		2001 to 2062	R	53
	Aug. 10	Info Sheet	415-81238 A2 415-79054 B		2001 to 2066		
	April 11	Rev. 1	415-81238 A2 415-79054 B 415-79412 A	K215T30505 E			
4250	March 01	Installation of a Starter/Generator Baffle	415-80978 B	K215T63904 A	2001 to 2990	R	24
	Dec. 05	Info Sheet	415-80978 D		2001 to 2062 and 2064 to 2990		

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	March 08	Info Sheet	415-80978 E		2001 to 2062 and 2064 to 2990		
	March 10	Rev. 1	415-80978 E-1		2001 to 2062 and 2064		
	Sept. 12	Info Sheet		K215T63904 B			
4251	April 00	Modification of the Rudder Gear/Trim Tab Drain Hole	415-80968 A	215T24290, RNIEO 601	2001 to 2057	C/O	55
4252	Nov. 01	Installation of a Diode in the Fuel Control Panel	415-80995 C		2001 to 2990	R	28
	Oct. 03	Rev. 1	415-80995 D				
	Nov. 04	Rev. 2	415-80995 E				
	Feb. 05	Rev. 3	415-80995 E				
	Feb. 05	Info Sheet					
	Nov. 05	Info Sheet	415-80995 F				
	Dec. 05	Info Sheet	415-80995 F		2001 to 2062 and 2064 to 2990		
	March 10	Info Sheet	415-80995 F-1		2001 to 2062, 2064 to 2072, and 2075 to 2990		

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	Sept. 10	Rev. 4	415-80995 F-3 415-79288 A	K215T51537 D	2001 to 2062, 2064 to 2072, 2075 to 2079, and 2082 to 2990		
	Aug. 11	Info Sheet	415-79288 A-1		2001 to 2062, 2064 to 2072, and 2075 to 2990		
	Sept. 14	Rev. 5	415-80995 F-4 415-79288 A-1		2001 to 2062, 2064 to 2072, 2075 to 2079, 2080 to 2990		
4253	June 00	Special Inspection of the Water Door Solenoid Valve Connectors	-		2001 to 2990	R	42
	Dec. 07	Rev. 1	-	(RSI) C-3190 B			
4254	April 00	Reinforcement of the Aircraft Hull at FS 333.75 and 352.50	415-80998 A		2001, 2002, 2006, 2007, 2010, 2011, to 2015, 2018, and 2024	C/O	53
	Feb. 01	Rev. 1	415-80998 B		2001, 2002, 2006, 2007, 2010, 2011, 2013 to 2015, 2018, and 2024		

CL-415



MODEL CL-215-6B11 (415)
 SERVICE BULLETIN INDEX
 PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	Jan. 03	Rev. 2	415-80998 D	K215T30523 B K215T30523, RNIEO 601 for A/C 2002 and RNIEO 602 for A/C 2014 215T30522 215T30536 215T30539 215T30540 215T30546 215T30547 215T30548 215T30549 215T30551 215T30554 215T30556 215T30557 215T30558 215T30559			
4255	Sept. 00	Installation of Protective Tape on the Main Landing Gear	415-80986 C	K215T80001 B	2001 to 2990	R	32
	Dec. 05	Info Sheet	415-80986 D		2001 to 2062 and 2066 to 2990		
4256	May 02	Installation of an AFT Cabin Enlarged Cargo Door	S415-90001 D		2055 and 2056	C/O	52
	Feb. 04	Rev. 1	S415-90001 K				

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	May. 09	Rev. 2	S415-90001 U S415-90035 A S415-90036 A S415-90063 A S415-90051 A S415-90040 A S415-90 41 A1 S415-90023 C1 S415-90079 A S415-90042 A S415-90052 A S415-900476 A 415-78638 A	K215T32001 C, RNIEO 601,602,603,604,616,617, 618,619,620,621,622 (For A/C 2055) and RNIEO 603,604,605,606,608, 609,610,611,612,613,614, 615 (For A/C 2056) K215T32002 D, RNIEO 603,604,605 (For A/C 2055) and RNIEO 601,602 (For A/C 2056) K215T32004 C, RNIEO 601,602,603,604,609,611, 612,613,614 (For A/C 2055) and RNIEO 603,605,606,607,608,610 (For A/C 2056) K215T32006 A, RNIEO 605,606,607 (For A/C 2055) and RNIEO 601,602,603,604 (For A/C 2056) K215T32007 NC K215T32009 B, RNIEO 601 (For A/C 2055 and 2056) K215T30051 B, RNIEO 601,602,606,607,608,609, 610(For A/C 2055) and RNIEO 601,603,604,605 (For A/C 2056) (Cont'd)	2001 to 2990		

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
				K215T30303 C, RNIEO 604,605,606 (For A/C 2055) and RNIEO 601,602,603,605,606 (For A/C 2056) K215T30911 NC, RNIEO 612 (For A/C 2056 only) K215T33056 A K215T52130 D, RNIEO 601,602,603 (For A/C 2055) and RNIEO 601(For A/C 2056) K215T75030 NC, RNIEO 601(For A/C 2055 and 2056) 215T32015 NC, RNIEO Extension (For A/C 2055 only) 215T32016 NC, RNIEO Extension(For A/C 2056 only) K215T40500 NC			
4257	July 09 May 00	Info Sheet Special Inspection of the Gust Lock Teleflex Cable			2001 to 2024, and 2026 to 2046	R	27
4258	Nov. 02 Dec. 02	Special Inspection of the Aileron Gust Lock Control Cable at FS 419.52 Rev. 1			2001 to 2059	M	27

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	Feb. 03	Rev. 2		215-31062, RNIEO 601 (RSI) C-3216 NC			
A4259	Jan. 01	Special Inspection/Replacement of the Clamp on the Fuel Drain Line – Lower Cowling	415-81026 A 415-81030 A 415-81092 A	(RSI) C-3217 A	2001 to 2053	M	28
4260	Oct. 00	Application of Paint and Markings for Demo Tour in Brazil A/C Serial No. 2051	415-81067 A	215T40476, RNIEO 601 and 215T40487, RNIEO 601	2051	R	11
4261	Nov. 02	Protection Improvement to the Generator and Battery Shunt Wires	415-81038 A	K215T52100 NC	2001 to 2065	R	24
	Dec. 05	Info Sheet	415-81038 C				
4262	Nov. 00	Installation of Water Door Deflectors	415-81017 B		2005, 2012, 2016, 2017, 2019, 2022, 2023, and 2026	C/O	42
	July 01	Rev. 1	415-81017 C	K215T33506 B			
	Dec. 06	Info Sheet	415-81017 C-1		2001, 2002, 2005 to 2007, 2010, 2012 to 2017, 2019, 2022 to 2024, 2026, 2057, and 2063		
4263		Service Bulletin Cancelled					

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4264	March 03	Special Inspection and Rework of the Aileron/Rudder Interconnect Pulley Installation	415-81040 A	215T90371, RNIEO 601 (RSI) C-3218 A	2001 to 2050	M	27
4265	Sept. 03	Replacement of the Aileron Trim Switch	415-81047 B	K215T51649 A	2001 to 2990	C/O	27
4266	Feb. 01	Special inspection of the Nose Landing Gear (NLG) Back Pressure Valve and Pressure Relief Valve	415-80600 H	(RSI) C-3213 A	2001 to 2990	M	32
4267	June 01	Special Inspection of the Water Door Priority Valves	-	(RSI) C-3208 A	2001 to 2027, 2029 to 2033, 2028, and 2034 to 2990	R	42
	Jan. 06	Rev. 1					
4268	May 01	Replacement of the Pitch Disconnect - Control Cable Stop Assembly Proposal Sheet	-		2001 to 2067		27
	March 01	Replacement of the Pitch Disconnect - Control Cable Stop Assembly	415-81003 B	K215T95700 A	2001 to 2067	C/O	27
	Dec. 05	Info Sheet	415-81003 C-1		2001 to 2063 and 2066 to 2990		
	Jan. 07	Info Sheet	415-81003 C-3		2001 to 2064 and 2066 to 2990		
	April 09	Info Sheet	415-81003 D-2		2001 to 2066		

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4269	March 01	Service Bulletin Cancelled	415-81003 B				
4270	Feb. 04	Inspection of the Aileron Multiplier Cable Guard at FS 234.50	415-81165 A	215-90266, RNIEO 601 (RSI) C-3227 A	2001 to 2062	M	27
	Feb. 06	Info Sheet	415-81165 B1		2001 to 2063 and 2066 to 2990		
	Oct. 07	Info Sheet	415-81165 B3		2001 to 2063		
4271	Dec. 00	Production Aircraft Water Test Post C of A	415-81087 A	(RSI) F-3603 and C-3229	2053	M	42
	Dec. 00	Info Sheet	415-81087 A-1		2053 and 2054		
	Jan. 01	Info Sheet	415-81087 A-2		2053 to 2055		
	Jan. 01	Info Sheet	415-81087 A-3		2053 to 2056		
	March 01	Info Sheet	415-81087 A-4		2053 to 2065		
	April 01	Info Sheet	415-81087 A-5		2053 to 2057		
	Dec. 01	Info Sheet	415-81087 A-6		2053 to 2057 & 2060		
	Oct. 05	Info Sheet	415-81087 A-7		2053 to 2057, 2060, and 2063		

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4272	Feb. 09	Info Sheet	415-81087 A-9		2053 to 2057, 2060, 2063, and 2070	C/O	34
	June 09	Info Sheet	415-81087 A-11		2053 to 2060, 2063, and 2070 to 2990		
	Aug. 03	Installation of the Nose-Mounted Weather Radar and Radome Primus 660	S415-90000 E S415-90017 B		2055		
	June 06	Rev. 1	S415-90000 E S415-90017 B 415-81289 A 415-81294 E 415-81311 A		2055 to 2058		
	Oct. 06	Rev. 2	S415-90000 J S415-90017 B 415-81289 A 415-81294 E 415-81311 A		2001 to 2055 and 2057 to 2990		
	Nov. 06	Rev. 3	415-81289 A-1 415-81294 K 415-81311 B-1		2001 to 2055 and 2057 to 2990		
April 07	Rev. 4	S415-90000 V 415-81289 A-1 415-81294 W 415-81311 H		2001 to 2055 and 2057 to 2990			

CL-415



MODEL CL-215-6B11 (415)
 SERVICE BULLETIN INDEX
 PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	Oct. 07	Rev. 5	S415-90000 Y 415-81289 A-1 415-81294 Y 415-81311 L		2001 to 2055 and 2057 to 2990		
	Dec. 07	Info Sheet					
	Sept. 08	Info Sheet					
	Oct. 08	Rev. 6	S415-90000 Y 415-81289 A-1 415-81294 Y 415-81311 M-1 415-78420 A				
	April 09	Rev. 7	S415-90074 A S415-90023 C1 S415-90043 A 415-81311 M-1 S415-90048 A S415-90044 A	K215T30600 C K215T30603 F, RNIEO 601,602,603,604,605,606, 607,608,609,610,611,612, 613,614,615,616,617(For A/C 2055) and RNIEO 623,624,625,626,627,628, 629,648(For A/C 2056) K215T30911 E K215T50626 C, RNIEO 601,602,603,604(For A/C 2055) K215T51006 G, RNIEO 601(For A/C 2055) and RNIEO 605(For A/C 2056)	2068 and 2071		
				(Cont'd)			

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
				K215T51007 D, RNIEO 601,603(For A/C 2055) and RNIEO 604,605(For A/C 2056) K215T51012 NC K215T51303 E, RNIEO 601(For A/C 2055) and RNIEO 605,606,607,612 (For A/C 2056) K215T58010 F, RNIEO 602,603,604,605,606 (For A/C 2056) K215T70100 NC, RNIEO 601(For A/C 2056) K215T70101 NC, RNIEO 601(For A/C 2055) and RNIEO 602(For A/C 2056) K215T70451 D K215T70456 A, RNIEO 601,602(For A/C 2056) K215T70471 A, RNIEO 601(For A/C 2056) K215T70490 C, RNIEO 601(For A/C 2056) K215T70600 D, RNIEO 601,602,603,604(For A/C 2056) (Cont'd)			

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	May 09	Info Sheet		K215T70605 B K215T95010 B, RNIEO 601,602,603 (For A/C 2055) and RNIEO 604,605,606 (For A/C 2056) K215T95020 E, RNIEO 601,602 (For A/C 2055) and RNIEO 603,604 (For A/C 2056) 215T50852 D-1 (A/C 2055 only)			
	Nov. 11	Info Sheet					
	Feb. 12	Rev. 8			2001 to 2055 and 2057 to 2990		
	April 12	Info Sheet					
	June 12	Info Sheet					
	Sept. 12	Info Sheet					

CL-415



MODEL CL-215-6B11 (415)
 SERVICE BULLETIN INDEX
 PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	Dec. 12	Rev. 9	S415-90226 A-1 415-79681 A-1 S415-90221 A S415-90225 A 415-81311 M-3 S415-90228 A-1 S415-90144 A 415-79686 A-1 S415-90223 A S415-90109 A S415-90044 A 415-78493 A S415-90027 A-1				
	Feb. 13	Rev. 10					
	Aug. 13	Info Sheet			2063, 2064, 2066, 2068, 2070, 2071, and 2073 to 2990		
4273	May 02	Installation of a Pressure Refueling Control Panel Splash Guard	S415-90008 C		2055 and 2056	C/O	28
	Nov. 02	Rev. 1	S415-90008 D	K215T52131 NC (RNIEO 601 and 602 for A/C 2055 only) K215T30911 NC (RNIEO 608 for A/C 2055 only)			

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4274	June 08	Info Sheet	S415-90008 D-1		2055, 2056, 2068, and 2071		
	Jan. 09	Info Sheet					
	May 02	Installation of Structural Provisions for the Multi Mission Management System	S415-90005 C		2055 and 2056	C/O	34
	June 04	Rev. 1	S415-90005 D2				
	May 09	Rev. 2			2055, 2056, 2068, and 2071		
	June 09	Rev. 3	S415-90005 L S415-90070 B				
	Sept. 10	Rev. 4	S415-90005 L S415-90070 B S415-90098 A	K215T51011 F (RNIEO 601 and 602 for A/C 2056 only) K215T70485 E K215T50634 B K215T50638 C (Rev C for A/C 2068 and 2071 only) K215T50639 NC K215T70668 C K215T51061 B	2055, 2056, 2068, and 2071		
4275	April 03	Installation of Left and Right Side Bubble Windows	S415-90002 C-1		2055	C/O	56
	June 08	Info Sheet	S415-90002 C-2		2055, 2056, 2068, and 2071		

CL-415



MODEL CL-215-6B11 (415)
 SERVICE BULLETIN INDEX
 PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	March 09	Rev. 1	S415-90002 C-2 S415-90045 A		2001 to 2990		
	Nov. 10	Rev. 2	S415-90002 C-2 S415-90045 A S415-90168 A S415-90177 A	K215T30090 E, RNIEO 601,602,603,604,605,606, 607 (For A/C 2055) and RNIEO 601,602,605, 609 (For A/C 2056)	2001 to 2990		
4276	May 02	Installation of Structural Provisions for Left and Right Side Bubble Windows	S415-90014 B		2056	C/O	56
	Oct. 02	Rev. 1	S415-90008 D	K215T30090 A, RNIEO 608 and 611			
4277	May 02	Relocation of the Oil Replenishment System	S415-90003 E		2055 and 2056	C/O	71
	Nov. 02	Rev. 1	S415-90014 F				
	June 08	Info Sheet	S415-90003 G-1		2055, 2056, 2068, and 2071		
	March 09	Rev. 2	S415-90003 G-1 S415-90060 A 415-78306 C 415-81272 A	K215T63909 A K215T63910 D, RNIEO 601 and 602 (For A/C 2055 and 2056 only) K215T63911 NC, RNIEO 603 (For A/C 2055 only) K215T63913 NC K215T63914 NC K215T58050 C	2055, 2056, 2068, and 2071		

CL-415



MODEL CL-215-6B11 (415)
 SERVICE BULLETIN INDEX
 PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	Nov. 11	Rev. 3	S415-90003 G-1 S415-90060 A S415-90064 A S415-90130 A S415-90157 A S415-90094 A S415-90142 A 415-7 8306 C-1 415-81272 A	K215T63909 B K215T63910 J, RNIEO 601 and 602 (For A/C 2055 and 2056 only) K215T63911 NC, RNIEO 603 (For A/C 2055 only) K215T63913 NC K215T63914 NC K215T58050 C	2055, 2056, 2068, and 2071		
4278	May 02	Relocation of the Type 3 Emergency Exit Door	S415-90004 D		2055 and 2056	C/O	52
	June 08	Info Sheet	S415-90004 D-2		2055, 2056, 2068, and 2071		
	Feb. 09	Rev. 1	S415-90004 F1 S415-90046 A	K215T32010 D K215T58052 NC K215T32011 A K215T32012 A (A/C 2055 and 2056 only) 215-33104 (For Ref only) Pats Inc. drawings: 651-1-394 651-1-396	2055, 2056, 2068, and 2071		
4279	May 02	Installation of a Temporary Ballast Tray at FS 133.00	S415-90015 A	K215T41100 NC (RSI) F-3634 NC	2056	C/O	53
4280	Aug. 02	Removal of a Temporary Ballast Tray at FS 133.00	S415-90020 A	K215T41101 NC	2056	M	53

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4281	Nov. 03	Installation of the Nose-Mounted Weather Radar and Radome Primus 660	S415-90013 D S415-90019 C	K215T30600 C, RNIEO 601, 602, 603 and 604 K215T30603 C, RNIEO 601 K215T30911 D, RNIEO 609 K215T51006 E, RNIEO 602 K215T51007 B, RNIEO 601 and 603 K215T51012 NC K215T51303 C, RNIEO 602, 603 and 604 K215T58010 B K215T95020 C, RNIEO 601 K215T50626 A, RNIEO 601 K215T70100 NC K215T70456 NC K215T70471 NC K215T70494 A K215T70600 B K215T70451 A K215T70605 A K215T70101 NC K215T70490 A K215T95010 A 215T50852 D	2056	C/O	34
4283	Feb. 01	Reinforcement of the Aircraft Hull at FS 313.00 and 371.50	415-81077 A		2003, 2004, 2008, 2009, 2012, 2016, 2017, 2019 to 2023, and 2026 to 2990	C/O	53

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	March 01	Info Sheet	415-81077 B				
	May 01	Info Sheet	415-81077 C				
	Jan. 04	Info Sheet	415-81077 C		2003, 2004, 2005, 2008, 2009, 2012, 2016, 2017, 2019 to 2023, and 2026 to 2990		
	Sept. 05	Rev. 1					
	Dec. 05	Info Sheet	415-81077 E		2003 to 2005, 2008, 2009, 2012, 2016, 2017, 2019 to 2023, and 2026 to 2990		
	Jan. 07	Rev. 2					
	Dec. 08	Rev. 3	415-81077 G	K215T30524 C			
	Jan. 09	Info Sheet					
	Nov. 12	Rev. 4	415-81077 G-2 415-79702 A	K215T30524 D			
4284	Mar. 01	Application of Temporary Markings for Greek Aircraft Serial No. 2054	415-81104 A	215T40485, RNIEO 601	2054	M	11

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4285	April 01	Application of Sealant to Aircraft Hull at the Water Door	415-81066 A	215T30526, RNIEO 601	2051 to 2057	R	53
4286	Mar 01	Application of External Paint Scheme and Markings for the Greek Aircraft	415-81107 A	215T40485, RNIEO 602 215T40485 215T40487	2050, 2052, and 2054	M	11
A4287	Aug. 01	Special Inspection of Rear Vertical Engine Mount Struts	-		2001 to 2067	M	71
	Sept. 02	Rev. 1					
	Jan. 03	Rev. 2	415-81114 B	(RSI) C-3232 C			
4289	Sept. 03	Installation of Additional Retainer Packings - Accumulator Pressure Gauges	415-81108 A	(RSI) C-3231 A	2001 to 2055	M	27
4290	July 02	Installation of Water Door Stop Protective Covers	415-81091 B		2110 to 2990	C/O	42
	Aug. 03	Rev. 1	415-81091 C				
	May 05	Rev. 2	415-81091 E	K215T33507 D			
4291	April 03	Installation of Structural Provisions for the External Shapes	S415-90006 C		2055 and 2056	C/O	57
	June 08	Info Sheet	415-90006 D-1		2055, 2056, 2068, and 2071		
	Jan. 09	Info Sheet					

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	Oct. 09	Rev. 1	S415-90006 D-1 S415-90141 A	For A/C 2055 and 2056, K215T10510 B and RNIEO 601 (2055) K215T30910 A Saab Nyge Aero Drawings: NA-CL-101-140 A NA-CL-101-170 D NA-CL-101-210 NC NA-CL-101-212 A NA-CL-101-215 B NA-CL-101-219 NC For A/C 2068 and 2071, K215T10510 B K215T30910 B NA-CL-101-140, Latest Revision NA-CL-108-015, Latest Revision NA-CL-108-072, Latest Revision NA-CL-108-001, Latest Revision NA-CL-108-073, Latest Revision NA-CL-108-002, Latest Revision (RSI) C-3846 A and C-3849 A (For A/C 2071 Only)	2055, 2056, 2068, and 2071		

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4292	Jan. 03	Installation of Provisions for the Weight-On-Wheels (WOW)	S415-90009 B		2055 and 2056	C/O	32
	May 08	Info Sheet	415-90009 B-1		2055, 2056, 2068, and 2071		
	Jan. 09	Info Sheet					
	Aug. 09	Rev. 1		K215T51013 B RNIEO 601 (For A/C 2055 and 2056) RNIEO 602 (For A/C 2055)			
4293	Jan. 03	Addition of Bright/Dim Lighting Capabilities for the SAR Mission Equipment	S415-90007 C		2055 and 2056	R	33
	June 08	Info Sheet	415-90007 F		2055, 2056, 2068, and 2071		
	Jan. 09	Info Sheet	415-90007 G				
	Oct. 09	Rev. 1	S415-90007 C S415-90090 B				
	April 11	Rev. 2	S415-90007 G S415-90090 B S415-90220 A	K215T51015 K RNIEO 601 (For A/C 2055)			
4294	Jan. 04	Removal of Foam System and Installation of Two Bilge Pump System	S415-90010 D		2055 and 2056	R	42
	July 08	Rev. 1	S415-90010 H-1		2055, 2056, 2068, and 2071		

CL-415



MODEL CL-215-6B11 (415)
 SERVICE BULLETIN INDEX
 PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	March 09	Rev. 2	S415-90010 H-1 S415-90047 A		2001 to 2990		
	June 09	Rev. 3	S415-90010 J S415-900468A (MOD SUM S415-90047 NOT APPLICABLE)		2001 to 2990		
	July 09	Info Sheet					
	Sept. 10	Rev. 4	S415-90010 J S415-900468A S415-90167 A 415-97113 B (MOD SUM S415-90047 NOT APPLICABLE)	K215T40058 D, RNIEO 601,602,603,604 (For A/C 2055) and RNIEO 601,602,603,604,605,606 (For A/C 2056) K215T40058 L, EO L-1 (For A/C 2001 to 2054 and 2057 to 2990)	2001 to 2990		
4295	May 02	Relocation of Miscellaneous Equipment	S415-90012 B		2055 and 2056	C/O	25
	June 08	Info Sheet	S415-90012 C		2055, 2056, 2068, and 2071		
	March 09	Rev. 1	S415-90012 C S415-90062 A				
	Oct. 09	Rev. 2	S415-90012 C S415-90062 A S415-90083 B	K215T52186 E			

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4296	May 02	Application of External Paint Scheme and Markings for the Greek Aircraft (SAR Configuration)	S415-90011 C		2055 and 2056	C/O	11
	Nov. 02	Rev. 1	S415-90011 D				
	Dec. 02	Rev. 2	S415-90011 D S415-90021 A	K215T40489 B K215T30911, RNIEO 610 and 611 For A/C 2056 only 215T40487, RNIEO 605 215T40486, RNIEO 601			
4297	May 02	Installation of Provisions for the Nose Mounted Weather Radar and Radome Primus 660	S415-90013 C	K215T51303 A, RNIEO 603 K215T30600 B and RNIEO 603 K215T30911 NC, RNIEO 609 K215T51007 A, RNIEO 603	2056	C/O	34
4298	July 01	Application of External Paint Scheme and Markings for the Italian Aircraft	415-81135 A	215T40474, RNIEO 601 215T40475, RNIEO 601 215T40476, RNIEO 602 215T52024, RNIEO 601 215-40530, RNIEO 603 K215T40020, RNIEO 602	2051	RBD	11
	Dec. 03	Info Sheet	415-80519 A-2		2051, 5059, 2060, and 2062		
4299	May 04	Inspection for Missing Fasteners	415-81137 A	K215T31000, RNIEO 605 (RSI) C-3238 NC	2001 to 2062	R	53
4300	April 03	Upgrade of the Attitude and Heading Reference Unit (AHRU) to Mod 7	415-81141 A	(RSI) C-3237 A	2051 to 2058	C/O	34

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4301	June 01	Application of External Paint Scheme and Markings for the Greek Aircraft	415-81148 A		2056	RBD	11
	Sept. 01	Rev. 1	415-81148 B	215T40485, RNIEO 604 and NIEO 3 215T40487, RNIEO 602 and NIEO 3			
4302	Dec. 02	Replacement of Water Door Priority Valve Hose Assemblies	415-81007 A	K215T75026 NC	2001 to 2061	R	42
	March 06	Info Sheet			2001 to 2027 and 2029, Post SB 215-4131 and 2028, and 2030 to 2061		
A4303	Feb. 03	Inspection and Repair of the Fire Extinguishing Discharge Indicators for the Main Engine and Cabin Heater (Refer Service Bulletin 877493-26-437 from Kiddy Aerospace)			2001 to 2060	M	26
	March 03	Rev. 1		(RSI) C-3241 A-2 C-3249 A			
4304	Aug. 01	Installation and Removal of the Attitude and Heading Reference Unit (AHRU) Mod 7 for Evaluation	415-81138 A 415-81139 A	215T52254, RNIEO 601 and 602 (RSI) C-3235 NC and F-3607 NC	2058	R	34

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4305		Service Bulletin Cancelled					
A4306	Nov. 01	Special Inspection of the Hydraulic Lines in the Nacelle Transition Box		(RSI) C-3245 NC	2001 to 2075	M	29
4307	Jan. 03	Replacement of the Nacelle Transition Box Cover Plates	415-81163 A	215T16546, RNIEO 601 (RSI) C-3245 NC	2001 to 2075	R	29
4308	April 02	Special Inspection of the Right Side Horizontal Stabilizer Leading-Edge Upper Skin			2001 to 2990	R	55
	Sept. 02	Rev. 1	415-81179 A				
	Oct. 02	Rev. 2	415-81179 A				
	April 03	Rev. 3	415-81179 B	K215T23027 A			
	May 03	Info Sheet					
	Dec. 05	Info Sheet	415-81179 C		2001 to 2062		
4309	May 02	Modification to the Pilot and Co-Pilot Seat Control System	415-81164 A	(RSI) C-3246 A	2001 to 2062	M	25
4311	Jan. 02	First Aid Kit Update	415-81110 A		2001 to 2055	R	25
4310		Service Bulletin Cancelled Ref: Service Information S.I. 23-00-00-012					

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4312	Feb. 02	Replacement of the Front and Rear Engine Inlet Case Assemblies			2001, 2002, 2006, 2007, 2010, 2011, 2013 to 2015, 2018, and 2024	C/O	72
4313	Jan. 02	Application of Paint Scheme and Markings for Demo Tour aircraft	415-81167 A	215T40471 E 215T40471, RNIEO 602 215T40472 F 215T40472, RNIEO 603 215T40473 G 215T40473, RNIEO 601	2057	R	11
4314	March 03	Removal of Foam Concentrate Tanks and Water Header Tanks	415-81177 D	K215T30060 C and RNIEO 601	2057	C/O	42
4315	June 03	Installation of Additional Clamping for the Cabin Fresh Air Ducting	415-81189 B	K215T40705 NC	2001 to 2057	R	21
4316	Dec. 03	Addition of Corrosion Protection for the Water System Electrical Connectors	415-81178 A		2001 to 2990	R	42
	April 09	Rev. 1	415-81178 A	K215T50037 A			
	March 10	Info Sheet	415-81178 C				
4317	Nov. 02	Inspection of Static Selector Valve Placard		(RSI) C-3259 NC	2001 to 2062	M	34
4318		Service Bulletin Cancelled					
4319	March 03	Modification to the Shed Bus Logic	415-81166 A-2 S415-90017 B		2001 to 2990	M	24

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4321	Nov. 08	Rev. 1	415-81166 D-1	K215T51017 A 215T50852 D-1	2001 to 2073		
	June 02	Application of Paint Scheme and Markings for Croatian Aircraft	415-70148 J-1 415-80600 T-2 415-80652 F		2058 to 2990	R	11
A4323	Jan. 10	Rev. 1	415-70148 J-2 415-80600 J 415-80652 E-1 415-79025 B 415-79032 A 415-79072 A 415-78959 A-1	215T40480 D 215T40481 C 215T40482 C 215T40008 C			
	June 02	Inspection of the Rudder Torque Tube Flange Radius			2001 to 2990	R	27
	June 02	Rev. 1					
4324	Nov. 05	Rev. 2		(RSI) C-3282 A			
	Feb. 03	Modification to the Aileron Cable Installation (Post Service Bulletin 215-4207)	415-81181 D		2001 to 2990	R	27
	May 05	Rev. 1	415-81181 F				
	Oct. 05	Info Sheet					
	Dec. 05	Rev. 2	415-81181 G	K215T90011 B K215T90011, RNIEO 601 for A/C 2060 (RSI) C-3271 A	2001 to 2062		

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4325	Aug. 12	Info Sheet	415-81181 H-3	K215T90011 C K215T90011, RNIEO 601 for A/C 2060 (RSI) C-3271 A			
	Oct. 02	Reinforcement of the Rear Spar on the Vertical Stabilizer	S415-90018 B		2055 and 2056	R	53
	June 03	Info Sheet	S415-90018 B-1		2055 to 2057		
	Jan. 06	Info Sheet	S415-90018 B-2		2001 to 2990		
	May 06	Rev. 1	S415-90018 B-2 415-81295A1				
4326	March 09	Rev. 2	S415-90018 B-2 415-81295 A-1 415-78789 A	K215T21112 B K215T21112, RNIEO 601 for A/C 2055 only and RNIEO 602 for A/C 2058 only			
	Aug. 02	Application of External Paint Scheme and Markings for the U.S. National Guard Demo Tour	415-81184 A		2057	R	11
	Oct. 02	Rev. 1	415-81184 B	K215T40490 NC 215T40487 B and RNIEO 604 215T40034 B and RNIEO 602			

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4327	Nov. 02	Modification to the Main Landing Gear (MLG) and the Nose Landing Gear (NLG) Instruction Name Plate	415-81185 A	K215T33574 NC	2001 to 2990	R	12
4328	June. 04	Replacement of the Rudder Torque Tube	415-81191 G		2001 to 2990	R	27
	July 04	Rev. 1					
	May 05	Rev. 2	415-81191 J		2001 to 2062		
	Nov. 05	Info Sheet	415-81191 K		2001 to 2065		
	Nov. 05	Info Sheet	415-81191 K		2001 to 2062		
	May 08	Rev. 3	415-81191 R	K215T92721 F	2001 to 2062		
	Aug 20	Rev. 4		K215T92721 K	2001 to 2062		
4329		Service Bulletin Cancelled					
4330		Service Bulletin Cancelled					
4331	Sept. 03	Improvement to the Corrosion Protection on the Cabin Floor Structure	415-81149 B	K215T40071 NC	2001 to 2990	R	53
4332	Dec. 04	Special Inspection of the Upper and Lower Finlet Attachment Fittings	RSI C-3285 NC	(RSI) C-3285 NC	2001 to 2990	M	55
4333	May 03	Inspection of the Inboard and Outboard Lower Flap Skins		(RSI) C-3261 A	2001 to 2062	R	27

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4336	Jan. 04	Installation of a Cockpit Egress Handle	415-81168 B-1		2001 to 2990	R	25
	Feb. 04	Rev. 1	415-81168 C				
	Sept. 05	Rev. 2	415-81168 D				
	May 06	Rev. 3	415-81168 E				
	Jan. 07	Rev. 4	415-81168 F-1				
	Oct. 07	Rev. 5	415-81168 J				
	March 09	Rev. 6	415-81168 J 415-78784 A				
	Oct. 11	Rev. 7	415-81168 J 415-78784 A 415-79428 A-1	K215T40600 D RNIEO 601 for A/C 2055 and 2056 only			
4337	Jan. 04	Modification to the Rudder/Aileron Interconnect Pulley Support	415-81200 A		2001 to 2062	M	27
	April 04	Rev. 1	415-81200 B	K215T90367 A (RSI) C-3279 A			
4338	Oct. 03	Replacement of Hardware on the Water Door Torque Shaft	415-81198 A		2001 to 2990	C/O	42
	Nov. 05	Rev. 1	415-81198 B	K215T26313 NC	2001 to 2065		
	Dec. 05	Info Sheet	415-81198 B-1		2001 to 2063		

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4339	Nov. 03	Replacement of the Water Door Damper Hardware	415-80620 A		2001 to 2036	C/O	42
	Dec. 04	Info Sheet					
	Nov. 05	Rev. 1	415-80620 B	K215T26109 NC			
	Dec. 14	Rev. 2			Aircraft Validity: 2001 to 2990 Service Effectivity: 2001, 2002, 2006, 2007, 2010, 2013, 2014, 2015, and 2024		
4340	March 04	Re-routing of the Propeller Control Harness Wires	415-80201 A	K215T50553 NC	2003, 2004, 2008, 2009, and 2012	R	61
4341	Dec. 03	Modification to the Roller Assembly, Manual Release, Four-Tank System	415-80999 A		2001 to 2990	R	42
	Feb. 04	Info Sheet					
	Jan. 07	Rev. 1		K215T26062 NC			
	June 09	Info Sheet					
4342	Nov. 03	Replacement of the Uplock Actuator Bearing	415-81202 A	K215T26110 NC	2001 to 2062	R	42

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	Oct. 07	Info Sheet	415-81202 B3				
	Dec. 10	Info Sheet	415-81202 B4				
4343	Dec 03	Replacement of the VHF Integrated Navigation Receiver to Eliminate Possible Erroneous ILS Information (Removal of FAA AD 2003-04-06)	415-81204 A	K215T51014 A	2001 to 2062	R	34
4344	Oct. 04	Replacement of Bolts in the Elevator Bearing Spigot Assembly	415-81183 A-1		2001 to 2022	R	27
	Oct. 07	Rev. 1	415-81183 C	K215T90550 B	2001 to 2062		
	March 08	Info Sheet					
4345	March 04	Installation of a Security Chain on the Refuelling Cap Assembly	415-81207 A	K215T64070 NC	2001 to 2990	C/O	28
4346	May 04	Temporary Removal of the Saphir 20 Auxiliary Power Unit (APU) Power Plant in Accordance with Supplemental Type Certificate (LSTC) No. SA04-53 (415-4346 This is a Removal Instruction Document, not a Service Bulletin)			2001, 2002, 2006, 2007, 2010, 2011, 2013 to 2015, and 2024		49
4347	May 04	Installation of Structural Provisions for the Collins 124F (V2) Direction Finder (DF) Antenna	S415-90023 B	K215T51150 A	2055 and 2056	C/O	93
	June 08	Info Sheet	S415-90023 C-1		2055, 2056, 2068, and 2071		

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	Aug. 10	Info Sheet	S415-90023 C-3		2001 to 2055, and 2057 to 2990		
4348	Feb. 05	Installation of a Lubricating Fitting on the Main Landing Gear Torque Links	415-81201 A		2001 to 2062	C/O	32
	July 08	Rev. 1	415-81201 C-3	K215T85100 NC			
	April 10	Info Sheet					
4349	July 04	Inspection of the Bilge Pump Discharge Hose Assemblies (Temporary Installation)	S415-90010 F	K215T40058, RNIEO 606 (RSI) C-3286 A	2056	M	42
4350	Sept. 04	Replacement of the Integrated Communication Units	415-81213 A		2052 to 2990	C/O	23
	Feb. 06	Info Sheet	415-81213 C		2052 to 2990		
	April 08	Rev. 1	415-81213 D-4	K215T51690 NC	2052 to 2064, 2066, and 2067		
	April 10	Info sheet	415-81213 D-6		2052 to 2064, and 2066 to 2990		
A4351	Dec. 04	Inspection for Correct Breathing Tube Connection on the Scott Aviation Oxygen Mask	RSI C-3283 NC		2001 to 2990	M	35

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4352	March 05	Addition of lubricant to the Engine Driven Pump (EDP) Spline	415-81214 A		2001 to 2062	R	29
	Feb. 06	Rev. 1	415-81214 B	K215T75231 NC			
4353	March 06	Installation of Second Foam/Bilge Pump	415-81216 B		2057	C/O	42
	April 06	Rev. 1	415-81216 E		2001 to 2990		
	Jan. 07	Rev. 2		K215T40029 C 215T40019 A			
4354	April 05	Installation of a Mooring Cleat and Vertical Handhold	S415-90001 L		2055 and 2056	C/O	25
	May 07	Rev. 1	S415-90001 P S415-90028 A	K215T40550 B			
4355	April 05	Replacement of Contact Washers in the MDC	415-81120 A		2001 to 2062	R	24
	Nov. 05	Info Sheet	415-81120 B		2001 to 2065		
	May 06	Rev. 1	415-81220 C1		2001 to 2064		
	Dec. 06	Rev. 2	415-81220 C1	K215T52191 A			
	Feb. 07	Info Sheet					
4356		Service Bulletin Cancelled					

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4357	Oct. 05	Installation of Landing Gear Harness Repair Kit	415-81237 A	K215T58019 NC	2001 to 2990	C/O	32
	Jan. 06	Info Sheet					
	May 14	Rev. 1	415-81237 B	K215T58019 A			
4358	Feb. 07	Installation of New Water Quantity Sensors	415-78223 E		2001 to 2064	C/O	42
	Aug. 07	Rev. 1	415-78223 F	K215T26073 C			
	Oct. 08	Info Sheet					
	June 10	Info Sheet					
4360		Service Bulletin Cancelled					
4361	Nov. 07	Installation of a Flap Interconnect Cable Bracket and Pulley	415-81286 A		2002 to 2005	C/O	27
	Nov. 09	Rev. 1	415-81286 A 415-79017 A1	K215T92361 A			
4362	July 05	Removal of the Pilot/Co-Pilot Seat Upper Shoulder Harness Roller	415-81250 A	215T40000, RNIE0 604 (RSI) F-3653 NC	2001 to 2990	M	25
	Dec. 05		415-81250 B		2001 to 2062		
	March 10	Info Sheet	415-81250 B-1				

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4363	Sept. 05	Relocation of the Main Landing Gear (MLG) Door Ground Stud	415-81150 A		2001 to 2075	C/O	32
	June 11	Rev. 1	415-81150 A-3	K215T33508 NC	2001 to 2083		
	Aug. 11	Info Sheet					
	Sept. 12	Rev. 2	415-81150 A-3 415-79583 B	K215T33508 A			
4364	Feb. 06	Installation of a Water Door Open Caution System (415-4364 This is an Installation Instruction Document, not a Service Bulletin)	None		2001 to 2990	C/O	31
	March 10	Rev. 1					
	Sept. 12	Rev. 2 Installation of a Water Door Open Caution System (Elisen Technologies STC SA 06-3)	STC SA 06-3	CAM31151203 C CAM5320665 NC CAM5320667 F CAM5320546 C CAM5320545 J CAM5320551 H CAM1130666 NC CAM5320550 B CAM5320509 H	2001, 2002, 2006, 2007, 2010, 2011, 2013 to 2015, 2018, 2024, 2025, 2057, 2063, and 2065 Post Service Bulletin SB 215-4237		

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	Feb. 16	Rev. 3			Aircraft Validity: 2001, 2002, 2006, 2007, 2010, 2011, 2013 to 2015, 2018, 2024, 2025, 2057, 2063, and 2065 Post Service Bulletin SB 215-4237 (Cont'd)		

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
					Service Effectivity: By separate kit, this STC is authorized for installation on (Kit No. 215K4364) 2001, 2002, 2006, 2007, 2010, 2011, 2013 to 2015, 2018, 2024, 2025, 2057, 2063, and 2065 (Kit No. 215K4364 A and 215K4364 A-1) 2063 (Kit No. 215K4364 B) none		

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1



215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	May 16	Rev. 4			Aircraft Validity: 2001, 2002, 2006, 2007, 2010, 2011, 2013 to 2015, 2018, 2024, 2025, 2057, 2063, and 2065 Post Service Bulletin SB 215-4237 Service Effectivity: By separate kit, this STC is authorized for installation on (Kit No. 215K4364) 2001, 2002, 2006, 2007, 2010, 2011, 2013 to 2015, 2018, 2024, 2025, 2057, 2063, and 2065 (Cont'd)		

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4365	April 06	Installation of an L3 Flight Data Recorder (FDR) and Provisions for a Micro Quick-Access Recorder (QAR) and a Digital Clock	415-81273 E 415-81274 E	K215T52013 C (FDR installation) K215T52013, RNIEO 603,604,605 and 606 for A/C 2057 only K215T52014 C (Clock installation) RNIEO 603 and 604 for A/C 2057 only	(Kit No. 215K4364 A and 215K4364 A-1) 2057, 2063, and 2065. (Kit No. 215K4364 B) 2001, 2002, 2006, 2007, 2010,2013, 2014, 2015, and 2024 2057	M	31
4366	July 06	Installation of Cockpit Voice Recorder (CVR)	415-81280 D		2051 to 2054 and 2057 to 2063	C/O	23
	Sept. 06	Rev. 1	415-81280 E		2051 to 2054 and 2057 to 2990		

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	Feb. 07	Rev. 2	415-81280 H		2051 to 2054 and 2057 to 2990		
	April 07	Rev. 3	415-81280 L		2051 to 2054 and 2057 to 2990		
	June 07	Info Sheet					
	Nov. 08	Rev. 4	415-81280 N-1				
	Nov. 10	Info Sheet					
	Oct. 10	Rev. 5	415-81280 N-2 415-78748 B 415-78749 C 415-78750 C 415-78751 A 415-78787 B 415-78826 A 415-78848 A 415-78922 A	K215T52016 M K215T52016, RNIEO 601 (RNIEO 603 for A/C 2009, 2048, 2059, 2060 and 2062 only) (RNIEO 604 for A/C 2009, 2058 to 2060 and 2062 only) K215T40478 C	2001 to 2054 and 2057 to 2990		
	Feb. 11	Info Sheet	415-78787 C				

CL-415



MODEL CL-215-6B11 (415)
 SERVICE BULLETIN INDEX
 PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	June 12	Rev. 6	415-81280 N-2 415-78748 B 415-78749 C 415-78750 C 415-78751 A 415-78787 D 415-78826 A 415-78848 B 415-78922 A	K215T52016 N K215T52016, RNIEO 601 (RNIEO 603 for A/C 2009, 2048, 2059, 2060 and 2062 only) (RNIEO 604 for A/C 2009, 2058 to 2060 and 2062 only) K215T40478 C	2001 to 2054 and 2057 to 2990		
	Dec. 15	Rev. 7	415-81280 N-2 415-78748 B 415-78749 C 415-78750 C 415-78751 A 415-78787 D 415-78826 A 415-78848 A 415-78922 A 415-79973 A	K215T52016 V K215T52016, RNIEO 601 (RNIEO 603 for A/C 2009, 2048, 2059, 2060 and 2062 only) (RNIEO 604 for A/C 2009, 2058 to 2060, and 2062 only) K215T40478 C	Aircraft Validity: 2001 to 2054, and 2057 to 2094 Effectivity: 2001 to 2004, 2006, 2007, 2009 to 2011, 2013 to 2015, 2020, 2021, 2024, 2029, 2030, 2035, 2036, 2045, 2047, 2048, 2055 to 2060, 2062 to 2075, 2077, 2079 to 2081, 2084, 2085, 2087, and 2088		

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF	
4367	June 06	Installation of an L3 Flight Data Recorder (FDR), A micro Quick-Access Recorder (QAR), and a Digital Clock	415-81273 E 415-81302 D 415-81274 G		2051 to 2054 and 2057 to 2990	C/O	31	
	Oct. 06		Rev. 1	415-81273 E 415-81302 D 415-81274 G 415-81345 B				2003 to 2005, 2008, 2009, 2012, 2016, 2017, 2019 to 2023, 2026 to 2054, and 2057 to 2063
	Nov. 06		Rev. 2	415-81273 E 415-81302 H 415-81274 H 415-81345 C				2003 to 2005, 2008, 2009, 2012, 2016, 2017, 2019 to 2023, 2026 to 2054, and 2057 to 2063
	Feb. 07		Rev. 3	415-81273 H 415-81302 J 415-81274 J 415-81345 E				2003 to 2005, 2008, 2009, 2012, 2016, 2017, 2019 to 2023, 2026 to 2054, and 2057 to 2990

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	March 07	Rev. 4	415-81273 H 415-81302 J 415-81274 J 415-81345 E		2003 to 2005, 2008, 2009, 2012, 2016, 2017, 2019 to 2023, 2026 to 2054, and 2057 to 2990		
	April 07	Rev. 5	415-81273 H 415-81302 J 415-81274 K 415-81345 G		2003 to 2005, 2008, 2009, 2012, 2016, 2017, 2019 to 2023, 2026 to 2054, and 2057 to 2990		
	Oct. 07	Rev. 6	415-81273 H 415-81302 L 415-81274 K 415-81345 H		2003 to 2005, 2008, 2009, 2012, 2016, 2017, 2019 to 2023, 2026 to 2054, and 2057 to 2990		

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	Nov. 08	Rev. 7	415-81273 H 415-81302 M-2 415-81274 K-1 415-81345 J-2 415-78766 D 415-78772 A 415-78773 B 415-78774 A-1	K215T52013 P, (FDR Installation for applicable aircraft Serial No. 2051 and subsequent) K215T52013, RNIEO 601,602,603,604,605 and 606 for A/C 2057 only K215T52013, RNIEO 607 for A/C 2058 only K215T52013, RNIEO 608 for A/C 2051 to 2054 and 2057 to 2990 K215T52014 F, Clock Installation RNIEO 601,602,603 and 604 for A/C 2057 only K215T52014 F, Clock Installation RNIEO 606 for A/C 2009, 2058 to 2060, and 2062 K215T52018 E, FDR Installation (Cont'd)	2003 to 2005, 2008, 2009, 2012, 2016, 2017, 2019 to 2023, 2026 to 2054, and 2057 to 2990		

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1



215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	March 11	Rev. 8		RNIEO 601 applicable A/C 2001 to 2050 RNIEO 601 applicable A/C 2001 to 2050 RNIEO 602 applicable for aircraft with Service Bulletin 215-4272 "INSTALLATION OF THE NOSE MOUNTED WEATHER RADAR AND RADOME PRIMUS 660" installed RNIEO 603 for A/C 2009 only K215T40478 A			
	Feb.12	Info Sheet		K215T52013 Y K215T52014 G K215T52018 G K215T40478 C	2001 to 2055, and 2057 to 2990		

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	Oct. 12	Rev. 9	415-81273 H-1 415-81302 M-3 415-78766 D 415-78772 A 415-78773 B 415-78774 A-1 415-81274 K-3 415-78764 A-1 415-78767 A 415-81345 J-3 415-78768 B 415-78769 B 415-78770 A 415-78771 A 415-79031 A 415-79142 A 415-78935 A 415-78785 A 415-78893 C 415-79140 A 415-79145 A 415-81350 A 415-79126 A-1 415-79231 A-1	K215T52013 AB, (FDR Installation for applicable A/C Serial No. 2051 and subsequent) K215T52013, RNIEO 601, 602, 603, 604, 605, and 606 for A/C Serial No. 2057 only K215T52013, RNIEO 607 for A/C Serial No. 2058 only. K215T52013, RNIEO 608 for A/C Serial Nos. 2051 to 2054 and 2057 to 2990 K215T52014 G, Clock Installation RNIEO 601, 602, 603, and 604 for A/C Serial No. 2057 only. RNIEO 606 for A/C Serial Nos. 2009, 2058 to 2060, and 2062. K215T52018 H, FDR Installation applicable A/C Serial No. 2001 to 2050.	2003 to 2005, 2008, 2009, 2012, 2016, 2017, 2019 to 2023, 2026 to 2054, and 2057 to 2990		

(Cont'd)

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	Oct. 12	Info sheet		RNIEO 601, RNIEO 602 applicable for aircraft with Service Bulletin 215-4272 "INSTALLATION OF THE NOSE MOUNTED WEATHER RADAR AND RADOME PRIMUS 660" installed. RNIEO 603 for A/C Serial No. 2009 only. K215T40478 K			
	Oct. 12	Info sheet		K215T40478 C			
	Feb. 14	Rev. 10	415-79706 A 415-79768 A	K215T52013 AC K215T52014 H			
4368	Sept. 08	Replacement of the SFIM Industries Flight Data recorder (FDR) with a L3 FDR and Installation of a Micro Quick Access Recorder (QAR) and a Digital Clock	415-78658 A		2001, 2002, 2006, 2007, 2010, 2013, to 2015, and 2024	C/O	31

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	Feb. 10	Rev. 1	415-78658 A 415-79141 A 415-78875 A 415-79145 A 415-81274 K-2 415-81273 H-1 415-81302 M-3 415-78826 A 415-78848 A				
	Jan. 11	Rev. 2	415-78658 A 415-79141 A 415-78875 A 415-79145 A 415-81274 K-2 415-81273 H-1 415-81302 M-3 415-78826 A 415-78848 A 415-79126 A	K215T52019 C K215T52014 G K215T40478 C			
4369	July 06	Installation of a Protective Cover for the Aileron Servo Connector	415-81322 A	K215T40101 NC	2058	R	25
	Oct. 06	Info Sheet # 1	415-81322 A-1		2003, 2004, 2009, 2020, 2021, 2029, 2030, 2035, 2036, 2045, 2047, 2048, 2058 to 2060, and 2062		

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	Oct. 08	Info Sheet # 2	415-81322 A-2		2003, 2004, 2009, 2020, 2021, 2029, 2030, 2035, 2036, 2045, 2047, 2048, 2058 to 2060, 2062, 2066, 2070, 2073, and 2074		
	Feb. 11	Info Sheet # 3	415-81322 A-3		2003, 2004, 2009, 2020, 2021, 2029, 2030, 2035, 2036, 2045, 2047, 2048, 2058 to 2060, 2062, 2066, 2070, 2073, 2074, 2080, and 2081		

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	Feb. 11	Info Sheet # 4	415-81322 A-4		2003, 2004, 2009, 2020, 2021, 2029, 2030, 2035, 2036, 2045, 2047, 2048, 2058 to 2060, 2062, 2066, 2070, 2073, 2074, 2079, and 2080		
	March 12	Info Sheet			2003, 2004, 2009, 2020, 2021, 2029, 2030, 2035, 2036, 2045, 2047, 2048, 2058 to 2060, 2062, 2066, 2070, 2073, 2074, 2079, 2080, 2085, 2087, and 2088		
	March 12	Info Sheet					
4370	May 07	Replacement of the Aileron and Elevator Static Dischargers	415-78245 B		2001 to 2068	C/O	23
	Sept. 07	Rev. 1		K215T15002 A			

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	Dec. 12	Rev. 2	415-78245 B-2		2001 to 2990		
4373	Jan. 07	Modification to the Symbol Generators SG-605 Silver Label, Part No. 7011672-607	None		2001 to 2990	M	34
4374	June 06	Installation of Structural Provisions for the Multi-Mission Management System (MMMS)	415-81285 C		2003, 2004, 2009, 2020, 2021, 2029, 2030, 2035, 2036, 2045, 2047, 2048, 2058 to 2060 and 2062	C/O	34
	Sept. 06	Rev. 1	415-81285 E				
	Oct. 06	Rev. 2	415-81285 F				
	Nov. 06	Rev. 3	415-81285 F-1				
	Jan. 07	Info Sheet	415-81285 F-1				
	Feb. 07	Rev. 4	415-81285 H				
	April 07	Rev. 5	415-81285 J				
	Oct. 07	Rev. 6	415-81285 L				
	Feb. 08	Info Sheet					

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	July 08	Rev. 7	415-81285 M-1		2003, 2004, 2009, 2020, 2021, 2029, 2030, 2035, 2036, 2045, 2047, 2048, 2058 to 2060, 2062, 2068, and 2071		
	Oct. 08	Rev. 8	415-81285 M-2	K215T51011 D, and RNIEO 603 for A/C 2009, 2048, 2058 to 2060, and 2062 only RNIEO 604 for A/C 2058 only RNIEO 605 for A/C 2009, 2058 to 2060, and 2062 only K215T70485 E, and RNIEO 601 and 602 for A/C 2058 only K215T50634 B, and RNIEO 601 for A/C 2058 only K215T50638 B, and RNIEO 601 for A/C 2058 only K215T50639 NC K215T70668 C K215T51061 B	2003, 2004, 2009, 2020, 2021, 2029, 2030, 2035, 2036, 2045, 2047, 2048, 2058 to 2060, 2062, 2068, 2070, 2071, 2073, and 2074		

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	June 12	Rev. 9	415-79097 A 415-81285 M-4 S415-90070 B S415-90098 A S415-90227 A	K215T51011 F K215T70485 H K215T50634 B K215T50638 C K215T50639 NC K215T70668 C K215T51061 B	2003, 2004, 2009, 2020, 2021, 2029, 2030, 2035, 2036, 2045, 2047, 2048, 2058 to 2060 2062, 2066, 2068, 2070, 2071, 2073, 2074, 2079, 2080, 2085, 2087 and 2088		
4375	March 07	Application of External Paint Scheme and Markings for the French Aircraft	415-78260 H 415-80600 N1 415-81284 C	215T40478 H, EO H-1 215T40470 F, EO F-2 215T40034 B 215T40008 NC, EO-12 215-30078 A, EO-A4 and EO-A8 RAF 215-100	2065	R	11
4376	May 06	Installation of Provisions for a Cockpit Voice Recorder (CVR) Model 2100-1020-02e	415-81315 A	K215T52016 D K215T52016, RNIEO 602	2063	C/O	23
4377	May 07	Replacement of the Attitude Heading Reference System (AHRS)	415-78277 C		2003 and 2009	C/O	34
	May 07	Info Sheet					
	May 07	Info Sheet					

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	Oct. 07	Rev. 1	415-78277 E	K215T52254 D RNIEO 601 and 602 for A/C 2009 only	2003, 2004, 2009, 2020, 2021, 2029, 2030, 2035, 2036, 2047, and 2048		
	June 12	Rev. 2	415-78277 E	K215T52254 G	2003, 2004, 2009, 2020, 2021, 2029, 2030, 2035, 2036, 2047, and 2048		
4378	April 12	Installation of the Pilot/Copilot seat Upper Shoulder Harness Roller (Refer Service Bulletin 42210-02 Rev. A and Amend 2 from Mirabel Aero Service)	415-81348 A1	K215T40008 NC	2001 to 2080	C/O	25
	June 12	Info Sheet					
4380	April 08	Installation of a New Servicing Instruction Placard for the Oil Replenishment System	415-78306 A	K215T63914 NC (RSI) C-3804 B	2001 to 2074	R	79
4382	June 08	Special Inspection of the Rudder Flight Control Cables at FS 486.00	415-78346 A		2019 to 2065	R	27
	June 08	Info Sheet					23
	Feb. 10	Rev. 1	415-78346 A 415-78918 A	K215T95701 A (RSI) C-3805 A			23

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4383	Feb. 08	Inspection for Clearance of the Aileron Pulleys at FS 434	None	(RSI) C-3809 NC	2001 to 2066	M	27
4385	Aug. 07	Replacement of the Nose Landing Gear (NLG) Centering Cam	None	(RSI) C-3806 NC	2001 to 2065	R	32
	Nov. 07	Info Sheet					32
4386	Oct. 07	Replacement of the Emergency Water Dump Pulley Bracket	415-78234 B	K215T94701 A	2001 to 2066	C/O	42
	Jan. 09	Info Sheet	415-78234 B		2001 to 2074		42
	Feb. 10	Info Sheet	415-78234 B-4		2001 to 2076		42
A4387	Dec. 07	Inspection of Wire Bundles at FS 234	None	(RSI) C-3807 NC	2001 to 2066	M	24
	Jan. 08	Info Sheet					24
4388		Service Bulletin Cancelled					
4389	Oct. 07	Application of External Paint Scheme and Markings for the Italian aircraft	415-81135 A-2 415-80664 D 415-80500 K1		2066	R	11
	Oct. 07	Rev. 1	415-81135 A-2 415-80664 D 415-80500 K1 415-78384 B 415-78388 A				

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4390	Oct. 07	Rev. 2	415-81135 A-2 415-80664 F 415-80500 K1 415-78384 D 415-78388 A				
	Dec. 07	Rev. 3	415-81135 A-2 415-80664 F 415-80500 K-1 415-78384 E 415-78388 A	K215T40707 B and RNIEO 601, 603 and 604 (Note RNIEO 604 cancels RNIEO 602) K215T40020, RNIEO 602			
	June 09	Replacement of Existing Emergency Locator Transmitter (ELT) for ELT Units that Transmit on 406 MHz	415-78629 F		2001 to 2071	R	25
	Oct. 09	Rev. 1	415-78629 F1 415-79057 A1		2001 to 2990		
	Oct. 09	Rev. 2	415-78629 F1 415-79057 A1				
	Dec. 09	Rev. 3	415-78629 F1 415-79057 A1 415-79114 A				
June 10	Rev. 4	415-78629 F2 415-79057 A1 415-79114 B-1 415-79198 A		2001 to 2075			

CL-415



MODEL CL-215-6B11 (415)
 SERVICE BULLETIN INDEX
 PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	March 11	Rev. 5	415-78629 F2 415-79057 A1 415-79114 B-2 415-79198 A-1 415-79259 A-1 415-79291 A-1	K215T52020 D (For A/C 2071 and 2072) K215T52111 C (For 2001 to 2070 and 2073 to 2077)	2001 to 2077 (Effectivity is split Mod Sum specific)		
	Nov. 10	Info Sheet					
	Sept. 12	Rev. 6	415-78629 F-2 415-79057 A-1 415-79114 B-5 415-79198 A-3 415-79259 A-1 415-79291 A-2 415-79616 A	K215T52020 D (For A/C 2071 and 2072) K215T52111 F (For 2001 to 2070 and 2073 to 2077)			
	April 14	Rev. 7	415-78629 F-2 415-79057 A-2 415-79339 A-4 415-79114 B-5 415-79198 A-3 415-79259 A-1 415-79291 A-2 415-79339 A-4 415-79514 A 415-79616 A 415-79653 A 415-79856 A	K215T52020 G (For A/C 2071 and 2072) K215T52111 G K215T52033 NC. (For 2001 to 2070 and 2073 to 2077)			

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	June 14	Rev. 8	415-78629 F-2 415-79057 A-2 415-79339 A-4 415-79114 B-5 415-79198 A-3 415-79259 A-1 415-79291 A-2 415-79339 A-4 415-79514 A 415-79616 A 415-79653 A 415-79856 B-1	K215T52020 G (For A/C 2071 and 2072) K215T52111 G K215T52033 B (For 2001 to 2070 and 2073 to 2077)			
4392	Nov. 07	Installation of Antenna Seals to Prevent Corrosion PROPOSAL SHEET			2001 to 2990		34
4393	Jan. 08	Modification to Enlarge the Existing Rudder Manual Trim Tab Motor Access Panel PROPOSAL SHEET			2001 to 2990		53
4394	May 08	Inspection of the Rudder Lower Torque Tube Upper Bearing	None	(RSI) C-3810 B	2001 to 2990	R	27
	June 11	Info Sheet					
4395	Dec. 08	Replacement of the Rudder Bearing	None	(RSI) C-3811 NC	2014 and 2015	R	27
4396		Service Bulletin Cancelled					

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4397	Oct. 08	Modification to the Boarding Ladder Stowage Bracket Supports	415-87373 A	K215T41000 NC	2001, 2002, 2006, 2007, 2010, 2013, to 2015, 2024, 2057, 2063, and 2065	C/O	25
4398	Dec. 08	Installation of a Protective Breathing Equipment (PBE)	415-87372 A	K215T40713 NC	2001, 2002, 2006, 2007, 2010, 2013, to 2015, 2024, 2057, 2063, and 2065	C/O	35
4399	Nov. 08	Installation of a Knife Holder Support Bracket	415-78432 B	K215T40711 A	2001, 2002, 2006, 2007, 2010, 2013, to 2015, 2024, 2057, 2063, and 2065	C/O	25
	Dec. 10	Info Sheet	415-78432 B 415-79024 A				
	Jan. 13	Rev. 1	415-78432 B 415-79726 A	K215T40711 C	2001 to 2990		

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4400	Aug. 08	Modification of the L3 Flight Data Recorder (FDR) (from Mod 8 to Mod 9)	None	(RSI) C-415-3812 NC	2003 to 2005, 2008, 2009, 2012, 2016, 2017, 2019 to 2023, 2026 to 2054, and 2057 to 2990	R	23
4401	Dec. 08	Installation of a Flight Crew Suitcase Support Rack	415-78500 B		2001, 2002, 2006, 2007, 2010, 2013, to 2015, 2024, 2057, 2063, and 2065	C/O	25
	Dec. 10	Rev. 1	415-78500 B 415-79246 A	K215T40714 A			
4402	May 09	Inspection of the RH Nacelle Struts for Nickle Plating	None	(RSI) C-3813 A	2067	R	54
	March 10	Info Sheet					
	Nov. 10	Info Sheet					
4403	Jan. 11	Installation of an SPZ-4500 Autopilot and a Multi Mission Management System (MMMS) (STC No. 04-32)	None		2001 to 2990		22

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4404	Dec. 08	Installation of Stowage Provisions for the Plug Pole (G215T100006-53) and the Propeller restrainers (G215T100026-1) Ground Handling Equipment	415-78382 A		2001, 2002, 2006, 2007, 2010, 2013, to 2015, 2024, 2057, 2063, and 2065	C/O	25
	Dec. 10	Rev. 1	415-78382 A 415-79171 A	K215T40706 A			
	Feb. 13	Rev. 2	415-78382 B 415-79171 A 415-79769 A	K215T40706 B	2001 to 2990		
	April 14	Info Sheet	415-78382 B 415-79171 A 415-79769 A 415-78909 A	K215T40706 C			
	Aug. 15	Rev. 3	415-78382 B 415-79171 A 415-79769 A 415-78909 B	K215T40706 C	Aircraft Validity: 2001 to 2990 Service Effectivity: 2001, 2002, 2006, 2007, 2010, 2013, 2014, 2015, 2024, 2027, 2041, 2046, 2057, 2061, 2063, 2065, 2072, and 2075		

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4405	Dec. 08	Installation of Provisions for Personal Floatation Device (PFD)	415-78429 A		2001, 2002, 2006, 2007, 2010, 2013, to 2015, 2024, 2057, 2063, and 2065	C/O	25
	Dec. 10	Rev. 1	415-78429 A 415-78895 A 415-78992 A	K215T40709 B			
	May 12	Rev. 2	415-78429 A 415-78895 A 415-78992 A 415-79419 A	K215T40709 C			
	Mar. 13	Rev. 3	415-78429 A 415-78895 A 415-78992 A 415-79419 A 415-79760 A	K215T40709 E	2001 to 2990		
4407	Dec. 08	Installation of a Loose Equipment Stowage Box	415-78408 A	K215T40708 NC	2001, 2002, 2006, 2007, 2010, 2013, to 2015, 2024, 2057, 2063, and 2065	C/O	25
	May 12	Rev. 1	415-78408 A 415-79434 A	K215T41708 NC K215T40403 NC			

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	April 13	Rev. 2	415-78408 A 415-79434 B-1	K215T40708 NC K215T40403 B			
4408	Dec. 08	Installation of Structural Provisions for an Emergency Life Raft	415-78431 A	K215T40710 NC	2001, 2002, 2006, 2007, 2010, 2013, to 2015, 2024, 2057, 2063, and 2065	C/O	25
4409	Oct. 08	Installation of Structural Provisions for an Accelerometer	415-78618 A	K215T40556 NC	2001, 2002, 2006, 2007, 2010, 2013, to 2015, 2024, 2057, 2063, and 2065	C/O	25
	Oct. 09	Info Sheet	415-78618 A-1		2001 to 2990		
4410	July 08	Special Inspection of the Aft Fuselage Hull Between FS 501 and FS 720	None		2001 to 2990	R	53
	July 08	Rev. 1		(RSI) C-3815 NC-1			
4411		Service Bulletin Cancelled					
4413	July 09	Replacement of a Cotter Pin in the Trim Tab Position Transmitter Link Assembly	None	(RSI) C-3814 NC	2057 to 2068	R	27
4414	July 09	Special Inspection of the Accumulator Screw Caps P/N 08-8425-014 on Tactair Accumulator P/N 08-8423-010 (MS28700-3)	None	(RSI) C-3817 B	2001 to 2990	M	27

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	March 10	Rev. 1		(RSI) C-3817 B-1			
	June 14	Info Sheet Special Inspection of the Accumulator Screw Caps on Accumulator P/N MS28700-3					
4415	Dec. 08	Special Inspection of the Elevator Actuator Fitting Assembly Mounting Hardware	None	(RSI) C-3819 NC	2001 to 2067	R	55
4416	Dec. 08	Application of Paint Scheme, Internal and External Markings for the Malaysian Aircraft	415-78409 C	K215T40712 NC 215T40494 A 215T40495 NC 215T40496 NC 215T00001 AF	2068	R	11
4417	May 09	Replacement of Aileron Pulley Brackets Between FS 434.0 and 447.0	415-78608 B1		2001 to 2075	R	27
	July 09	Rev. 1					
	May 11	Rev. 2	415-78608 B1 415-79154 A				
	Oct. 11	Rev. 3	415-78608 B1 415-79154 B	K215T92113 B			
4418	Jan. 09	Replacement/Installation of the Nose Landing Gear (NLG) Right Side Door	415-78781 B	K215T33002 A	2069	C/O	32
4419	Oct. 09	Special Inspection of the Lightning Holes at FS 371.50	415-79112 A	K215T30025 A	2001 to 2067	C/O	53

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4422	Sept. 09	Replacement of the Remote Signal Processing Unit (RSPU)	415-79076 A	K215T52006 NC	2001 to 2072	R	31
	Feb. 12	Rev. 1	415-79076 A	K215T52006 NC			
4423	April 11	Relocation of the Flight Control Hydraulic Accumulator	415-79046 B 415-79393 A		2001 to 2990	M	27
	Sept. 11	Rev. 1	415-79046 B 415-79393 A 415-79464 A	(RSI) C-3839 A K215T75051 E			
	May 12	Rev. 2	415-79046 B 415-79393 A 415-79464 B	(RSI) C-3839 A K215T75051 E			
	Dec. 13	Rev. 3	415-79046 B-2 415-79393 A 415-79464 B 415-79823 B-1 415-79614 B	(RSI) C-3839 B K215T75051 J K215T75013 B		R	
	Dec. 13	Info Sheet					
	Dec. 15	Rev. 4	415-79046 B-3 415-79393 A-1 415-79464 B-1 415-79614 B-1 415-79823 C 415-79982 B	(RSI) C-3839 D K215T75051 L K215T75013 C	2001 to 2081		
	March 16	Rev. 5					

CL-415



MODEL CL-215-6B11 (415)
 SERVICE BULLETIN INDEX
 PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
A4424	Jan. 10	Inspection of the Emergency Water Dump Pulley Bracket and Structure at FS 150.50	415-79064 A		2001 to 2085	M	42
	May 10	Rev. 1	415-79064 B				
	June 10	Rev. 2		(RSI) C-3838 B-1 K215T94703 A			
	Nov. 11	Rev. 3		(RSI) C-3838 B-1 K215T94703 B			
	Dec. 12	Rev. 4		415-79064 B-1 415-78957 B	2001 to 2990		
A4425	Sept. 09	Special Inspection of the Main Distribution Centre (MDC) Electrical Ground Plate	None		2001 to 2072	M	24
	Dec. 09	Rev. 1					
	Feb. 10	Rev. 2		(RSI) C-3840 A (RSI) C-3851 NC			
4426	Oct. 12	Replacement of the Pilot and Copilot Digital Clocks (with Flight Data Recorder (FDR) already installed or being installed in conjunction with this Service Bulletin)	415-79507 B-1 415-79231 A-1	K215T52027 A K215T52028 B	2001 to 2990	R	31
	Dec. 12	Info sheet				C/O	
	Aug. 14	Rev. 1	415-79507 B-4 415-79231 A-3		2001 to 2087		

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4427	Oct. 09	Wiring Modification to the Flight Data Recorder (FDR) Installation with the Penny and Giles ADC Unit Installed	415-79031 A		2071	R	31
	Jan. 11	Rev. 1	415-79031 A 415-79142 A 415-79145 A 415-81350 A	K215T52013 Y	2068 and 2070 to 2990		
	Dec. 12	Info sheet					
	Dec. 12	Info sheet					
	Jan. 13	Rev. 2	415-79031 A 415-79142 A 415-79145 A 415-79231 A-1 415-81350 A	K215T52013 AB	2001 to 2990		
	June 14	Rev. 3	415-79031 A 415-79142 A 415-79145 A 415-79231 A-3 415-79768 A 415-81350 A	K215T52013 AC	2001 to 2087		

CL-415



MODEL CL-215-6B11 (415)
 SERVICE BULLETIN INDEX
 PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4428	March 16	Rev. 4 Wiring Modification to the Flight Data Recorder (FDR) when Changing the Old ADC Type for the Penny & Giles ADC	415-79031 A415-79098 A415-79142 A-1 415-79145 A-1 415-79231 A-3 415-79768 A 415-81350 A-1 415-79446 A-1	K215T52013 AD K215T52018 H	Aircraft Validity: 2001 to 2067, and 2069 Service Effectivity: 2002, and 2024		
	Dec. 09	Replacement of the Existing Air Data Computer (ADC) Unit with a New Penny and Giles ADC Unit	415-79098 A		2001 to 2067 and 2069	C/O	34
	Jan. 10	Info Sheet					
	Jan. 10	Info Sheet					
	May 11	Rev. 1		415-79098 A 415-79199 A	K215T51001 A		
	Feb. 14	Info Sheet		415-78885 A 415-79098 A 415-79199 A	K215T51001 B		
	March 16	Rev. 2		415-79098 A 415-79199 A 415-78885 B		Aircraft Validity: 2001 to 2067, and 2069 Service Effectivity: 2002, 2023, 2024, 2026, 2064, 2067, and 2069	

CL-415



MODEL CL-215-6B11 (415)
 SERVICE BULLETIN INDEX
 PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4430	Sept. 10	AFT Hull Reinforcement Between FS 501.00 and FS 684.00	415-79206 A 415-79275 A	K215T30036 A (RSI) C-3863 NC	2001 to 2990	C/O	53
4432	Oct. 12	Replacement of the Pilot and Copilot Digital Clocks (Without Flight Data Recorder (FDR) Installed)	415-79507 B-1	K215T52040 A	2001 to 2990 without Service Bulletin 215-4367 installed	R	31
	Oct. 12	Rev. 1	415-79507 B-1 415-79648 A	K215T52040 B			
	Dec. 12	Info sheet				C/O	
	Jan. 13	Info sheet	415-79507 B-1 415-79648 A 415-79738 A	K215T52040 C			
	Jan. 15	Rev. 2	415-79507 B-4 415-79648 A 415-79738 B 415-79796 A 415-79921 A	K215T52040 E	Aircraft Validity: 2001 to 2990 without Service Bulletin 215-4367 installed Service Effectivity: 2079, 2080, and 2087 to 2091		

CL-415



MODEL CL-215-6B11 (415)
 SERVICE BULLETIN INDEX
 PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	May 16	Rev. 3			Aircraft Validity: 2001 to 2990 without Service Bulletin 215-4367 installed Service Effectivity: 2072, 2075, 2079, 2080, 2087, 2088, 2089, 2090, and 2091		
A4433	May 10	Replacement of the Flight Control Tab Hinges Bearings	None	(RSI) C-3869 A	2067 to 2075	M	27
4434	Jan. 11	Removal of Water Header Tanks Search and Rescue (SAR) configuration	415-78554 A	K215T30007 NC	2068 and 2071	C/O	42
A4435	July 10	Special Inspection (Visual) of the Accumulator Screw Caps on Tactair or York Accumulator P/N 08-8423-010 (MS28700-3)	None		2001 to 2990	M	27 32
	July 10	Rev. 1					
	July 10	Rev. 2		(RSI) C-3876 NC			
	June 14	Info Sheet Special Inspection (visual) of the Accumulator Screw Caps on Accumulator P/N MS28700-3					

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
A4436	Sept. 11	Fuselage Replacement of MDC Rack Panel and Installation of Additional Harness Support	415-79299 C	(RSI) C-3880 NC	2001 to 2076	M	53
	Feb. 12	Rev. 1	415-79299 D 415-79544 B	K215T52127 B (RSI) C-3880 A			
4437	Feb. 11	Replacement of the Honeywell AH-800 and/or the LITEF LCR-93 Attitude and Heading Reference Unit (AHRU) with a LITEF LCR-100 AHRU	415-79362 A 415-79341 B		2001 to 2078	C/O	34
	Feb. 11	Info Sheet #1					
	March 11	Rev. 1	415-79362 A 415-79341 B 415-79403 A		2001 to 2079		
	June 11	Rev. 2	415-79362 A 415-79341 B 415-79403 A 415-79180 A 415-79383 A 415-79384 A F415-3421 C F415-3422 C	K215T52023 E K215T52007 NC K215T52029 NC K215T52030 NC 215T51520 E			

CL-415



MODEL CL-215-6B11 (415)
 SERVICE BULLETIN INDEX
 PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	Sept. 11	Info Sheet	415-79362 A415-79341 B 415-79403 A 415-79180 A 415-79383 A 415-79384 A 415-79472 A-1 F415-3421 C F415-3422 C	K215T52023 E K215T52007 B K215T52029 NC K215T52030 NC 215T51520 E			
	June 12	Info Sheet					
	Aug. 14	Rev. 3	415-79362 A 415-79341 B 415-79403 A 415-79180 A 415-79383 A 415-79384 A 415-79472 A-1 415-79485 A F415-3421 C F415-3422 C		2023		
	Sept. 14	Rev. 4			2003, 2020, 2023, and 2078		
	Oct. 14	Rev. 5			Aircraft Validity: 2001 to 2990 Service Effectivity: 2003, 2020, 2023, and 2078		

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	Sept. 15	Rev. 6	415-79362 A 415-79341 B 415-79403 B 415-79180 A 415-79383 A 415-79384 A 415-79472 A-1 415-79485 A 415-79971 A F415-3421 C F415-3422 C	K215T52023 E K215T52007 B K215T52029 NC K215T52030 A 215T51520 E	Aircraft Validity: 2001 to 2990 Service Effectivity: 2003, 2020, 2023, 2038, and 2078		
	March 16	Rev. 7			Aircraft Validity: 2001 to 2990 Service Effectivity: 2002, 2003, 2019, 2020, 2022 to 2024, 2028, 2037, 2038, 2065, 2068, 2071, and 2076 to 2078		

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	May 16	Rev. 8			Aircraft Validity: 2001 to 2990 Service Effectivity: 2002, 2003, 2019, 2020, 2022 to 2024, 2027, 2028, 2037, 2038, 2065, 2068, 2071, 2072, and 2076 to 2078		
4438	March 11	Installation of a Foam Failure Indication System	415-79413 A		2076 and 2077	C/O	42
	Aug. 11	Info Sheet	415-79413 A-1		2076 and 2077 to 2990		
	Oct. 11	Rev. 1	415-79413 A-1 415-79499 A	K215T51059 D			
	Nov. 12	Info sheet	415-79413 A-1 415-79499 A 415-79588 A	K215T51059 E			
	Jan. 14	Rev. 2					

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4439	May 14	Info Sheet	415-79413 A-1 415-79499 B-1 415-79588 A		2003 to 2005, 2008, 2009, 2012, 2016, 2017, 2019 to 2023, 2026 to 2056, 2058 to 2062, 2064, 2066, and subsequent		
	Jan. 11	Installation of Structural Provisions for the Flight Management System (FMS)	415-78699 A	K215T50005 NC K215T70485 G K215T50634 B K215T50638 C K215T50639 NC	2076, 2077, 2080 and 2081	C/O	34
	April. 11	Info Sheet	415-78699 B		2001 to 2990		
	Oct. 11	Info Sheet					
	Oct. 12	Info sheet		415-78699 A S415-90227 A	K215T50005 NC K215T70485 H K215T50634 B K215T50638 C K215T50639 NC		

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	Oct. 14	Rev. 1	415-78699 C 415-81285 N S415-90227 B	K215T50005 NC K215T70485 H K215T50634 C K215T50638 C K215T50639 NC 215T51077 A	Aircraft Validity: 2001 to 2990 Service Effectivity: 2076, 2077, 2079, 2080, 2081, 2084, 2085, 2087, 2088, and 2091		
	Jan. 15	Rev. 2	415-78699 C 415-80014 B 415-81285 N S415-90227 B	K215T50005 NC K215T50040 NC K215T70485 H K215T50634 C K215T50638 C K215T50639 NC 215T51077 A			
	June 15	Rev. 3	415-78699 C 415-78511 C 415-79954 A 415-81285 N S415-90227 B	K215T50005 NC K215T70485 H K215T50634 C K215T50638 C K215T50639 NC K215T50007 A 215T51077 A	Aircraft Validity: 2001 to 2990 Service Effectivity: 2076, 2077, 2079, 2080, 2081, 2084, 2085, 2087, 2088, 2090, and 2091		23 34

CL-415



MODEL CL-215-6B11 (415)
 SERVICE BULLETIN INDEX
 PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	Nov. 15	Rev. 4	415-78699 C 415-78511 C 415-79954 A 415-80014 B-1 415-81285 N S415-90227 B	K215T50005 NC K215T50040 NC K215T70485 H K215T50634 C K215T50638 C K215T50639 NC K215T50007 A 215T51077 A	Aircraft Validity: 2001 to 2990 Service Effectivity: 2076, 2077, 2079, 2080, 2081, 2084, 2085, 2087, 2088, 2090, 2091, and 2094		
4440	Nov. 13	Airframe System and Structures – Identification of Unserialized Life Limited Components	415-79388 B	(RSI) C-3885 A K215T90012 NC	2001 and subsequent	R	05
4441	Jan. 11	Removal of the Garmin 165 Global Positioning System (GPS) from the Aircraft	415-79151 B	K215T50006 NC K215T70668 C K215T52031 C	2076, 2077, 2080, 2081	C/O	34
	Jan. 11	Info Sheet					
	April 11	Info Sheet	415-79151 C		2001 to 2990		
	May 14	Rev. 1	415-79151 C 415-78568 A 415-79811 A S415-90005 L	K215T50006 B K215T70668 C K215T52031 NC			

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	Sept. 14	Rev. 2	415-79151 C 415-78568 A 415-79811 A 415-79492 A S415-90005 L	K215T50006 C K215T70668 C K215T52031 NC	Aircraft Validity: 2001 to 2990 Service Effectivity: 2076, 2077, 2081, 2084, 2090, and 2091		
4442	Jan. 11	Inspection of the Engine Drain Hose	415-79151 B		2001 to 2079	R	71
	March 11	Rev. 1		(RSI) C-3881 A			
4443	June 11	Replacement of the Engine Drain Hose Assemblies	415-79440 A	K215T60544 NC (RSI) C-3881 D	2001 to 2079	M	71
	Sept. 11	Info Sheet					
4446	March 11	Installation of a Water door Open Caution System with Flight Management System (FMS) and Global Positioning System (GPS) Installed	None (STC SA06-3)		2001 to 2990 with SB 4439 installed	C/O	31
	Jan. 12	Info Sheet					
	Jan. 12	Info Sheet					
	Feb. 12	Rev. 1	STC SA06-3	CAE53203616 A CAM53203615 C CAM5320550 B CAM5320551 E			

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	March 12	Rev. 2	STC SA06-3	CAE53203616 A CAM53203615 C CAM5320550 B CAM5320551 E			
	Dec. 12	Info Sheet		CAE53203616 A CAM53203615 E CAM5320550 B CAM5320551 H			
	Jan. 15	Rev. 3	STC SA06-3	CAE53203616 B CAM53203615 E CAM5320550 C CAM5320551 H CAM1130554 B CAM1130554, NIEO 514-006 NC (for A/C 2091 only)			
	Jan. 15	Rev. 4	STC SA06-3	CAE53203616 B CAM53203615 E CAM5320550 C CAM5320551 J CAM1130554 B CAM1130554, NIEO 514-006 NC (for A/C 2091 only)			
4447	Feb. 11	Replacement of the Studs for the Main Entrance Door Ladder	415-78647 A	K215T30033 NC	2077	R	53

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
A4450	July 11	Inspection of the Main Landing Gear (MLG) Upper Member Forward Lug Using Liquid Penetrant Method	None	(RSI) C-3892 A	2001 to 2990	M	32
A4451	July 11	Inspection of the Main Landing Gear (MLG) Upper Member Forward Lug Using Eddy Current Method	None	(RSI) C-3892 A	2001 to 2990	M	32
	Jan. 12	Rev. 1		(RSI) C-3892 B			
A4452	Oct. 11	Inspection of the Rudder Torque Tube Lower Bearing	None	(RSI) C-3894 A-1	2001 to 2990	M	27
	Jan. 12	Rev. 1					
A4453	April 12	Inspection of the Bushings in the Nacelle Upper Strut Assemblies	None	(RSI) C-3902 NC		M	54
	Nov. 12	Info sheet					
4455	Oct. 13	Replacement of the Radio Management Unit (RMU)	415-79487 B	K215T93003 A	2001 to 2990	C/O	23
	Jan. 15	Rev. 1	415-79487 B 415-78317 A	K215T93003 B	Aircraft Validity: 2001 to 2990 Service Effectivity: 2090 to 2095		

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	Feb. 15	Rev. 2			Aircraft Validity: 2001 to 2990 Service Effectivity: 2023, and 2090 to 2095		
	Feb. 15	Rev. 3			Aircraft Validity: 2001 to 2990 Service Effectivity: 2022, 2023, 2026, and 2090 to 2095		
	May 16	Rev. 4			Aircraft Validity: 2001 to 2990 Service Effectivity: 2022, 2023, 2026, 2027, 2072, 2075, and 2090 to 2095		
4456	May 12	Inspection of the Elevator Control Pressure Switch		(RSI) C-3906 NC	2001 to 2990	M	27

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4457	April 12	Modification of the Pilot and Copilot Portable Oxygen System (Post Installation of Service BULLETIN 215-4051)	415-79495 A 415-79519 A	K215T40028	2001, 2002, 2006, 2007, 2010, 2013 to 2015, 2024, 2057, 2063, 2076 and 2077	R	35
	June 12	Rev. 1	415-79495 A 415-79519 A 415-79564 A		2001, 2002, 2006, 2007, 2010, 2013 to 2015, 2024, 2057, 2063, 2076, 2077 and 2081		
	Oct. 12	Rev. 2	415-79495 A 415-79519 B 415-79564 B	K215T40028			
	Dec. 12	Info sheet			2001, 2002, 2005 to 2007, 2010, 2012 to 2017, 2019, 2022 to 2024, 2026, 2057, 2063, 2065, 2076, 2077 and 2081		
	May 13	Rev. 3	415-79495 A 415-79519 B-1 415-79564 B	K215T40028			

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4459	April 12	Replacement of the Shock Strut Assembly (RH) Name Plate		RSA 1000101565-1	2084	C/O	32
4460	Sept. 12	Inspection of Aileron Gear Tab for Part Numbers and Serial Numbers	None	(RSI) C-3911 NC	2001 to 2078	R	27
	Oct. 12	Rev. 1					
4461	Sept. 12	Modification of the Pilot and Copilot Portable Oxygen System (This Service Bulletin replaces 215-4051 and 215-4457)	415-79589 A-1	K215T40028 F	2003 to 2005, 2008, 2009, 2012, 2016, 2017, 2019 to 2023, 2026 to 2056, 2058 to 2062, 2064, 2066 to 2075, 2078 to 2080, and 2082 to 2990	C/O	35
	Dec. 12	Info sheet	415-79589 A-2		2003, 2004, 2008, 2009, 2020, 2021, 2027 to 2056, 2058 to 2062, 2064, 2066 to 2075, 2078 to 2080, and 2082 to 2990		

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4462	Sept. 12	Inspection of the Flap Actuator for a Possible Fouling Condition	None	(RSI) C-3913 A	2001 to 2085	R	27
	June 14	Rev. 1		(RSI) C-3913 B			
4463	Sept. 12	Inspection of the Upper and Lower Elevator Horn Skins (P/N 215-25004-106 and 215-25004-15)	None	(RSI) C-3916 NC	2001 to 2081	R	55
	Jan. 13	Rev. 1	415-79782 B	(RSI) C-3916 B K215T25001 A	2001 to 2089		
	Feb. 13	Info sheet Inspection of the Upper and Lower Elevator Horn Skins (P/N 215-25004-106 and 215-25004-15 LH Upper and Lower) (P/N 215-25004-107 and 215-25004-14 RH Upper and Lower)					
	Feb. 13	Rev. 2	415-79782 B	(RSI) C-3916 C-1 K215T25001 A			
	May 14	Rev. 3 Inspection and/or Replacement of the Upper and Lower Elevator Horn Skins (P/N 215-25004-106 and 215-25004-15 LH Upper and Lower) (P/N 215-25004-107 and 215-25004-14 RH Upper and Lower)	415-79782 B 415-79814 C	(RSI) C-3916 C-1 K215T25001 D	2001 and subsequent		
	Feb. 16	Rev. 4 (Cancels SB)					

CL-415



MODEL CL-215-6B11 (415)
 SERVICE BULLETIN INDEX
 PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4464	Jan. 13	Special Inspection of the Large Terminal Lugs Crimping Quality in the Main Distribution Centre (MDC)	None	(RSI) C-3914 A	2074 to 2083	R	24
4465	Sept. 12	Verification of Torque Value on Aileron Control Multiplier Bolt	None	(RSI) C-3919 NC	2001 to 2990	R	27
	Nov. 12	Info sheet					
	Nov. 15	Rev. 1			Aircraft Validity: 2001 to 2086 Service Effectivity: 2001 and 2086		
4466	Sept. 13	Inspection for Possible Interference between the Water Door Actuator Idler Arm Retaining Bolt and Support Structure	415-79813 A	(RSI) C-3914 A K215T31001 NC	2001 to 2990	R	42
4467	Nov. 12	Replacement of the Flight Data Recorder (FDR) No. 3 Digital Clock	415-79706 A	K215T52014 H	2001 to 2084 with Service Bulletins 215-4367 or 215-4368 installed	C/O	31
	Dec. 12	Info sheet				R	
	Jan. 13	Rev. 1 Software Update for the Flight Data Recorder (FDR) Clock					

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1



215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4468	April 13	Installation of Additional Grease Fittings on the Upper and Lower Torque Tube Bearing	415-79727 A	K215T92700 NC	2001 to 2990	R	27
	April 13	Rev. 1					
	Oct. 14	Rev. 2 Installation of Additional Grease Fittings on the Upper and Lower Torque Tube Bearing Assemblies			Aircraft Validity: 2001 to 2990 Service Effectivity: No Serial Numbers listed at this time		
	Nov. 14	Rev. 3			Aircraft Validity: 2001 to 2990 Service Effectivity: 2001, 2010, and 2063		
	Dec. 14	Rev. 4			Aircraft Validity: 2001 to 2990 Service Effectivity: 2001, 2002, 2006, 2007, 2010, 2013 to 2015, 2024, 2057, 2063, and 2065		

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	Oct. 15	Rev. 5			Aircraft Validity: 2001 to 2990 Service Effectivity: 2001, 2002, 2005, 2006, 2007, 2010, 2012 to 2017, 2019, 2022 to 2024, 2026, 2057, 2063, 2065, 2078, 2082, 2083, and 2086		
	Nov. 15	Rev. 6			Aircraft Validity: 2001 to 2990 Service Effectivity: 2001, 2002, 2005, 2006, 2007, 2010, 2012 to 2017, 2019, 2022 to 2024, 2026, 2034, 2057, 2063, 2065, 2077, 2078, 2082, 2083, and 2086		

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4469	Dec. 12	Special Inspection of the Aircraft Hull Stringers for Missing Drain Holes	None	(RSI) C-3922 A	2001 to 2083	R	53
	Dec. 12	Info sheet					
4470	Dec. 13	Hydraulic Accumulators (MS28700-3) – Life Limit of 10 000 Flight Hours	None	(RSI) C-3927 B	2001 to 2990	R	05
	June 14	Rev. 1		(RSI) C-3927 C			
4472	June 13	Inspection / Replacement of the Joint Fitting on the Elevator Torque Tube Control Assembly (Common to the Pitch Disconnect)	None	(RSI) C-3928 NC	2076 to 2080	R	27
	April 14	Rev. 1		(RSI) C-3928 B			
4474	July 13	Identification of the Left and Right Elevator Spring Tab Assemblies	None	(RSI) C-3929 NC	2001 to 2078	R	27
4475	July 13	Modification to the Aural Warning Speaker Box Assembly	None	(RSI) C-3930 A	2001 to 2990	R	23
4476	May 13	Inspection of the Aileron Control System Cables	None	(RSI) C-3938 A	2076 to 2088	R	27
	Jan. 14	Rev. 1 Inspection of the Aileron Control System Cables and Flap Interconnect System Cables		(RSI) C-3938 C	2076 to 2090		
4477	Sept. 13	Replacement of Powered Aileron System Teflon Parts Due to Excess Charge of Fiberglass	None	(RSI) C-3934 B	2076 to 2090	R	27

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4480	June 14	Info Sheet					
	Nov. 14	Rev. 1		(RSI) C-3934 B1	Aircraft Validity: 2076 to 2090 Service Effectivity: 2076 to 2090		
	Sept. 15	Rev. 2		(RSI) C-3934 C			
4481	Sept. 13	Inspection of the Aileron Interconnect Pulley Assembly Guard Pins	None	(RSI) C-3935 NC	2085 to 2092	R	27
	Nov. 14	Rev. 1			Aircraft Validity: 2085 to 2092 Service Effectivity: 2085 to 2089		
4483	Oct. 13	Replacement of the Elevator Normal Trim Actuator	None	(RSI) C-3940 NC	2087 and 2088	R	27
	March. 15	Rev. 1		(RSI) C-3940 B	Aircraft Validity: 2087 Service Effectivity: 2087		
4483	Dec. 13	Installation of Software Upgrade for the Digital Clock P/N APE4190-070	None	(RSI) C-3931 NC	2001 to 2089	R	31

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4484	Sept. 14	Replacement of the Emergency Water Dump Handle Assembly	None	(RSI) C-3946 A	2070 to 2088	R	42
	Nov. 15	Rev. 1			Aircraft Validity: 2070 to 2088 Service Effectivity: 2070 and 2088		
4485	June 15	Installation of a Third Integrated VHF Communications System	415-78327 F	K215T52041 B	Aircraft Validity: 2001 to 2990 Service Effectivity: 2090	C/O	23
4487	June 15	Mode S ADS-B Out System Installation - ICU Replacement	415-78602 E	K215T70020 B	Aircraft Validity: 2001 to 2990 Service Effectivity: 2090	C/O	23
	June 15	Rev. 1					

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4488	May 14	Inspection / Rework of Forward Horizontal to Vertical Stabilizer Attachment Fittings (left and right sides) for Loose Bolts	415-78335 A	(RSI) C-3932 NC K215-23002 NC	2001 to 2092	R	55
	Dec. 15	Rev. 1	415-78335 C-1 215-50978 A	(RSI) C-3932 NC K215-23002 B	Aircraft Validity: 2001 to 2093 Service Effectivity: 2003, 2004, 2009, 2020, 2021, 2028, 2030 to 2040, 2043, 2047, 2048, 2058 to 2060, 2062, 2066, 2070, 2073, 2074, 2079, 2080, 2085, 2087 to 2089, and 2093		

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	Jan. 16	Rev. 2			Aircraft Validity: 2001 to 2092 Service Effectivity: 2003, 2004, 2009, 2020, 2021, 2028, 2030 to 2040, 2043, 2047, 2048, 2058 to 2060, 2062, 2066, 2070, 2073, 2074, 2077, 2078, 2079, 2080, 2081, 2082, 2083, 2084, 2085, 2086, 2087 to 2089, 2091, and 2092		

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1



215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	April 16	Rev. 3			Aircraft Validity: 2001 to 2092 Service Effectivity: 2001 to 2004, 2006, 2007, 2009, 2010, 2013 to 2015, 2020, 2021, 2024, 2028, 2030 to 2040, 2043, 2047, 2048, 2057 to 2060, 2062, 2063, 2065, 2066, 2070, 2073, 2074, 2077, 2078, 2079, 2080, 2081, 2082, 2083, 2084, 2085, 2086, 2087 to 2089, 2091, and 2092		

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4490	April 14 June 14	Reconfiguration of the Cabin Seating Rev. 1	415-79866 A-1 415-79866 A-2 415-79913 A	K215T40240 NC	2091 2005, 2012, 2016, 2017, 2019, 2022, 2023, 2026, 2077, 2078, 2081 to 2084, 2086, 2089, 2091 and 2092	C/O	25
4494	Oct. 14 Sept. 15	Replacement of the Aileron Gear and Trim Tab Assembly Nameplates Rev. 1 (Cancels SB)	None	(RSI) C-3951 A	2076 to 2090	R	27
4495	Dec. 15	Modification to the Integrated Navigation Units to Eliminate False "MLS ERR" Message on the Radio Management Unit	415-79871 A	K215T93005 NC	Aircraft Validity: 2001 to 2089 Service Effectivity: No Serial Numbers listed at this time	R	34

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	Feb. 16	Rev. 1			Aircraft Validity: 2001 to 2089 Service Effectivity: 2003, 2004, 2009, 2020, 2021, 2028 to 2038, 2040, 2043, 2045, 2047, 2048, 2058 to 2060, 2062, 2066, 2070, 2073, 2074, 2078, 2082, and 2083		

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1



215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	April 16	Rev. 2			Aircraft Validity: 2001 to 2089 Service Effectivity: 2001 to 2004, 2006, 2007, 2009, 2010, 2013 to 2015, 2020, 2021, 2024, 2028 to 2038, 2040, 2043, 2045, 2047, 2048, 2057 to 2060, 2062, 2063, 2065, 2066, 2070, 2073, 2074, 2078, 2082, and 2083		
4496	Sept. 14	Replacement of the Portable Fire Extinguisher	415-79849 A1	K215T40041 NC	Aircraft Validity: 2001 to 2990 Service Effectivity: No Serial Numbers listed at this time	C/O	26

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1



215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
	March 15	Rev. 1	415-79849 B	K215T40041 A	Aircraft Validity: 2001 to 2092 Service Effectivity: No Serial Numbers listed at this time		
	April 15	Rev. 2			Aircraft Validity: 2001 to 2092 Service Effectivity: 2059 and 2073		
	April 15	Rev. 3				R	
4497	Aug. 14	Removal of Cabin RH Seat Restraint Harnesses	415-79932 A	K215T40242 NC	2005, 2012, 2016, 2017, 2019, 2022, 2023, 2026	C/O	25
4499	Aug. 15	Inspection of Aileron Manual Trim System for Excessive Backlash		(RSI) C-3953 NC	Aircraft Validity: 2001 to 2990 Service Effectivity: 2001 to 2990	R	27

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016



NUMERICAL SEQUENCE SECTION 1

215-	DATE OF ISSUE	SUBJECT	MOD SUMMARY	KIT DRAWING	EFFECTIVITY	COMPLIANCE	ATA REF
4500	Nov. 15	Replacement of the Auto Probe System Mode Selection Switch	415-80200 A	K215T93811 NC	Aircraft Validity: 2001, 2002, 2006, 2007, 2010, 2013, 2014, 2015, 2024, and 2057, 2063, 2065, 2077, 2081, 2084, 2091 Post Service Bulletin 215-4176 Service Effectivity: 2077, 2081, 2084, 2091, 2094	C/O	42
4501	Jul. 16	Conversion of Model No. 14SF-19 Propeller Blades to Model No. 14SF-17 Propeller Blades and Optional Incorporation of a Stronger Trailing Edge	415-78908 A	K215T61900 NC K215T61910 NC	Aircraft Validity: 2001 to 2990 Service Effectivity: 2001 to 2095	C/O	61
4502	Nov. 15	Application of Aeroflite Scheme, External, and Internal Markings	415-80229 B	215T40550 EDL-01 Rev 1 215T40489 EDL-01 Rev 1 215T40486 EDL-03 Rev 3 215T40034 EDL-02 Rev 2215T40550 NC 215T40489 NC 215T40486 D 215T40034 C	Aircraft Validity: 2095 Service Effectivity: 2095	C/O	11

CL-415

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016
NUMERICAL SEQUENCE
SECTION 1



THIS PAGE INTENTIONALLY LEFT BLANK

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 5 – Time Limits – Maintenance Checks

215-	SUBJECT	COMPLIANCE
4440	Airframe System and Structures – Identification of Unserialized Life Limited Components	R
4470	Hydraulic Accumulators (MS28700-3) – Life Limit of 10 000 Flight Hours	R

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 11 – Placards and Markings

215-	SUBJECT	COMPLIANCE
4031	Application of External Paint and Registration Markings for the Government of Quebec	R
4043	Exterior Markings French Translation	RBD
4062	Installation of a Decal on the Airspeed Limitations Placards	R
4091	Replacement of the Airspeed Limitations Placards	R
4113	Replacement of the Airspeed Limitations Placards	R
4150	Application of External Paint Scheme and Markings for the Italian Aircraft	R
4171	Addition of Anti-Skid Paint to the Top of the Aircraft	C/O
4175	Application of Italian Internal/External Markings and Paint Scheme	C/O
4186	Application of External Paint and Registration Markings for the Ontario Ministry of Natural Resources	R
4260	Application of Paint and Markings for Demo Tour in Brazil A/C Serial No. 2051	R
4284	Application of Temporary Markings for Greek Aircraft Serial No. 2054	M
4286	Application of External Paint Scheme and Markings for the Greek Aircraft	M
4298	Application of External Paint Scheme and Markings for the Italian Aircraft	RBD
4301	Application of External Paint Scheme and Markings for the Greek Aircraft	RBD
4296	Application of External Paint Scheme and Markings for the Greek Aircraft (SAR Configuration)	C/O

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 11 – Placards and Markings (Cont'd)

215-	SUBJECT	COMPLIANCE
4313	Application of Paint Scheme and Markings for Demo Tour Aircraft	R
4321	Application of Paint Scheme and Markings for the Croatian Aircraft	R
4326	Application of External Paint Scheme and Markings for the U.S. National Guard Demo Tour	R
4375	Application of External Paint Scheme and Markings for the French Aircraft	R
4389	Application of External Paint Scheme and Markings for the Italian Aircraft	R
4416	Application of Paint Scheme, Internal and External Markings for the Malaysian Aircraft	R
4502	Application of Aeroflite Scheme, External, and Internal Markings	C/O

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 12 – Servicing

215-	SUBJECT	COMPLIANCE
4053	Replacement of the Hydraulic Accumulator Decal	R
4327	Modification to the Main Landing Gear (MLG) and the Nose Landing Gear (NLG) Instruction Name Plate	R

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 21 – Air Conditioning

215-	SUBJECT	COMPLIANCE
4002	Modification to the Cockpit Heater System	R
4009	Installation of a Rubber Gasket on the Compressor/Condenser Removal Cover Assembly	RBD
4114	Refrigerant Conversion in the Air Conditioning System	C/O
4136	Installation of Evaporator/Blower Insulation Blankets PROPOSAL SHEET	R
4315	Installation of Additional Clamping for the Cabin Fresh Air Ducting	R

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 22 – Auto Flight

215-	SUBJECT	COMPLIANCE
4090	Replacement of the Rudder Trim Compensator Unit (RTCU)	R

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 23 – Communications

215-	SUBJECT	COMPLIANCE
4041	Modification to the High Frequency Communication Antenna Routing	RBD
4070	Replacement of the Service Interphone Jack FS 541.0	C/O
4162	Installation of a Third Crewmember Intercom PROPOSAL SHEET	C/O
4162	Installation of a Third Crewmember Intercom	C/O
4183	Installation of a VHF/FM Press-to-Talk (PTT) Feature on the Pilot and Copilot Control Handwheel PROPOSAL SHEET	C/O
4183	Installation of a VHF/FM Press-to-Talk (PTT) Feature on the Pilot and Copilot Control Handwheel	C/O
4236	Replacement of the Flight Deck Speakers PROPOSAL SHEET	C/O
4236	Replacement of the Flight Deck Speakers	C/O
4237	Removal of HF Communication System and Stowage of Connectors	C/O
4350	Replacement of the Integrated Communication Units	C/O
4366	Installation of a Cockpit Voice Recorder (CVR)	C/O
4370	Replacement of the Aileron and Elevator Static Dischargers	C/O
4376	Installation of Provisions for a Cockpit Voice Recorder (CVR) Model 2100-1020-02	C/O
4400	Modification of the L3 Flight Data Recorder (FDR) (from Mod 8 to Mod 9)	R

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 23 – Communications (Cont'd)

215-	SUBJECT	COMPLIANCE
4439	Installation of Structural Provisions for the Flight Management System (FMS)	C/O
4455	Replacement of the Radio Management Unit (RMU)	C/O
4475	Modification to the Aural Warning Speaker Box Assembly	R
4485	Installation of a Third Integrated VHF Communications System	C/O
4487	Mode S ADS-B Out System Installation – ICU Replacement	C/O

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 24 – Electrical Power

215-	SUBJECT	COMPLIANCE
4033	Washer Part Number Change for the Battery Hold Down Assembly	RBD
4050	Refuel Aircraft with the Battery Master Switch Off	R
4067	Installation of an Alternate Power Source for the Oil Replenishment System	R
A4094	Introduction of Automatic Battery/Essential Bus Tie Modification	R
4115	Installation of a O-Ring on the Starter/Generator PROPOSAL SHEET	R
4120	Installation of Dual Power Supply	R
4168	Addition of Short-Circuit Protection to the Battery Charger System	R
A4184	Special Inspection and Modification of the High Current Feed Thru in the MDC	R
4191	Installation of a Decal on the Electrical Outlets	R
4213	Special Inspection of the Adaptor Heater Contactors (1K2HA / 2K2HA)	R
4215	Replacement of Washers in the Battery Junction Box (JB) and Generator Boxes 1 and 2	R
4216	Relocation of ESS/BATT Lock-out Contactor Circuit Breaker	R
4218	Addition of Short Circuit Protection to the Battery Direct Bus Feed Line Wires	M
4223	Modification to the Elevator Trim Override System Circuit	R
4224	Replacement of the Bus Bars, Terminal Lugs, and Feedthroughs in the Battery Junction Box and Generator Box No. 1 and No. 2	M

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 24 – Electrical Power (Cont'd)

215-	SUBJECT	COMPLIANCE
4233	Replacement of the EFIS Power Diodes in Relay Panel "C"	M
4250	Installation of a Started/Generator Baffle	R
4225	Inspection of the High Current Ground Stud Doublers	R
4261	Protection Improvement to the Generator and Battery Shunt Wires	R
4319	Modification to the Shed Bus Logic	M (for SAR)
4355	Replacement of Contactor Washers in the MDC	R
A4387	Inspection of Wire Bundles at FS 234	M
A4425	Special Inspection of the Main Distribution Centre (MDC) Electrical Ground Plate	M
4464	Special Inspection of the Large Terminal Lugs Crimping Quality in the Main Distribution Centre (MDC)	R

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 25 – Equipment/Furnishings

215–	SUBJECT	COMPLIANCE
4001	Equipment Installation and Removal for Ferry Flights	RBD
4010	Restricted to Utility and Utility to Restricted	R
4012	Rework of the Flight Engineer Seat Support Structure	R
4025	Removal of Access Ladder Mounting Studs	RBD
4027	Replacement of the Glareshield Shroud	RBD
4049	Structural Provision for the Emergency Locator Transmitter (ELT) Models 8.1 and 14.1 PROPOSAL SHEET	R
4049	Structural Provision for the Emergency Locator Transmitter (ELT) Models 8.1 and 14.1	R
4051	Modification to the Portable Oxygen Bottle Installation PROPOSAL SHEET	C/O
4054	Installation of Instructional Decals on the Flight Engineer Seat	R
4069	Ferry Flight Equipment Installation	R
4096	Installation of an Observer Seat	C/O
4126	Installation of a Propeller–Restraint Attachment Bracket	C/O
4135	Installation of a Metric Graduation Scale on the Fuel Dipstick PROPOSAL SHEET	C/O
4135	Installation of a Metric Graduation Scale on the Fuel Dipstick	C/O
4170	Installation of a Rescue Boat Handling Package	C/O
4173	Replacement of the List of Content Decal for the Spare Bulb kit	R

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 25 – Equipment/Furnishings (Cont'd)

215–	SUBJECT	COMPLIANCE
4194	Relocation of the Boarding Ladder and Boarding Ladder Handle Stowage Retaining Straps	R
4219	Inspection of Pilot and Copilot Seat Height Control System	R
4221	Installation and Removal of the Rescue Boat Deployment Package	C/O
4243	Installation of the Utility Handling System (UHS)	C/O
4295	Relocation of Miscellaneous Equipment	C/O
4309	Modification to the Pilot and Co-Pilot Seat Control System	M
4311	First Aid Kit Update	R
4336	Installation of a Cockpit Egress Handle	R
4354	Installation of a Mooring Cleat and Vertical Handhold	C/O
4362	Removal of the Pilot/Co-Pilot Seat Upper Shoulder Harness Roller	M
4369	Installation of a Protective Cover for the Aileron Servo Connector	R
4378	Installation of the Pilot/Copilot seat Upper Shoulder Harness Roller (Refer Service Bulletin 42210-02 Rev. A and Amend. 2 from Mirabel Aero Service)	C/O
4390	Replacement of the Existing Emergency Locator Transmitter (ELT) for ELT Units that Transmit on 406 MHz	R
4397	Modification to the Boarding Ladder Stowage Bracket Supports	C/O
4399	Installation of a Knife Holder Support Bracket	C/O
4401	Installation of a Flight Crew Suitcase Support Rack	C/O

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 25 – Equipment/Furnishings (Cont'd)

215-	SUBJECT	COMPLIANCE
4404	Installation of Stowage Provisions for the Plug Pole (G215T100006-53) and the Propeller restrainers (G215T100026-1) Ground Handling Equipment	C/O
4405	Installation of Provisions for Personal Floatation Device (PFD)	C/O
4407	Installation of a Loose Equipment Stowage Box	C/O
4408	Installation of Structural Provisions for an Emergency Life Raft	C/O
4409	Installation of Structural Provisions for an Accelerometer	C/O
4416	Installation of a Knife Holder Support Bracket	C/O
4490	Reconfiguration of the Cabin Seating	C/O
4497	Removal of Cabin RH Seat Restraint Harnesses	C/O

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 26 – Fire Protection

215-	SUBJECT	COMPLIANCE
4052	Relocation of the Cockpit Fire Extinguisher Bottle	R
4209	Inspection of Packings in the Cabin Heater Fire Extinguisher Installation	R
A4303	Inspection and Repair of the Fire Extinguishing Discharge Indicators for the Main Engine and Cabin Heater (Refer Service Bulletin 877493-26-437 from Kiddy Aerospace)	M
4496	Replacement of the Portable Fire Extinguisher	R

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 27 – Flight Controls

215-	SUBJECT	COMPLIANCE
4016	Rework to the Aileron Gust Lock	RBD
4019	Removal/Installation of a Slotted Pin	RBD
4024	Replacement of the Flight Control Panel	R
4032	Provision for Lockwiring the Rudder–Pedal Adjustment Cables	R
4046	Replacement of the Trim Comparator Unit	R
4047	Modification to the Rudder Auto–Trim System	R
4053	Replacement of the Hydraulic Accumulator Decal	R
4059	Replacement of the Flight Control Handwheel	C/O
4066	Replacement of the Rudder Trim Actuator and Transmitter Screws	R
4071	Replacement of the Release Latch for the Pitch Disconnect Handle	C/O
4112	Replacement of the Magnaghi Servo Actuators	M
4128	Replacement of the Spring in the Artificial Feel Spring–Pot Assembly PROPOSAL SHEET	C/O
4128	Replacement of the Spring in the Artificial Feel Spring–Pot Assembly	C/O
4134	Circuit Improvements added to Prevent False/Misleading Indications	R
4144	Inspection/Rework of the Elevator Normal Trim Actuator Programming Lever	R
4152	Installation of a Check Valve and a Relief Valve in the Powered Rudder Hydraulic System	R

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 27 – Flight Controls (Cont'd)

215-	SUBJECT	COMPLIANCE
4156	Addition of a Washer on the Control Rod	R
4157	Replacement of the Accumulator Pressure Gauge	R
4163	Replacement of the Flap Position Indicator PROPOSAL SHEET	C/O
4163	Replacement of the Flap Position Indicator	C/O
4190	Replacement of the Hydraulic, Brake, and Rudder Pressure Transducers	R
4202	Installation of Improved Flight Control Handwheels	C/O
4207	Special Inspection and Modification to the Aileron Cable Installation (Rear Spar WS 236.09 and WS 152.80)	R
4210	Removal of Flap Asymmetry False Indication – Kit Improvement	R
A4217	Special Inspection of the Rudder Torque Tube Flange	R
4245	Inspection of Fasteners on the Pilot and Copilot Elevator Forward Torque Tube Input Quadrants	M
4257	Special Inspection of the Gust Lock Teleflex Cable	R
4258	Special Inspection of the Aileron Gust Lock Control Cable at FS419.52	M
4264	Special Inspection and Rework of the Aileron/Rudder Interconnect Pulley Installation	M
4265	Replacement of the Aileron Trim Switch	C/O
4268	Replacement of the Pitch Disconnect – Control Cable Stop Assembly PROPOSAL SHEET	C/O

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 27 – Flight Controls (Cont'd)

215-	SUBJECT	COMPLIANCE
4268	Replacement of the Pitch Disconnect – Control Cable Stop Assembly	C/O
4270	Inspection of the Aileron Multiplier Cable Guard at FS 234.50	M
4289	Installation of Additional Retainer Packings – Accumulator Pressure Gauges	M
A4323	Inspection of the Rudder Torque Tube Flange Radius Modification to the Rudder/Aileron Interconnect Pulley Support	R
4324	Modification to the Aileron Cable Installation (Post Service Bulletin 215-4207)	R
4328	Replacement of the Rudder Torque Tube	R
4333	Inspection of the Inboard and Outboard Lower Flap Skins	R
4337	Modification to the Rudder/Aileron Interconnect Pulley Support	M
4344	Replacement of Bolts in the Elevator Bearing Spigot Assembly	R
4361	Installation of a Flap Interconnect Cable Bracket and Pulley	C/O
4382	Special Inspection of the Rudder Flight Control Cables at FS 486.00	R
4383	Inspection for Clearance of the Aileron Pulleys at FS 434	M
4394	Inspection of the Rudder Lower Torque Tube Upper Bearing	R
4395	Replacement of the Rudder Bearing	R
4413	Replacement of a Cotter Pin in the Trim Tab Position Transmitter Link Assembly	R

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 27 – Flight Controls (Cont'd)

215-	SUBJECT	COMPLIANCE
4414	Special Inspection of the Accumulator Screw Caps on Accumulator P/N MS28700-3	M
4417	Replacement of Aileron Pulley Brackets Between FS 434.0 and 447.0	R
A4435	Special Inspection (visual) of the Accumulator Screw Caps on Accumulator P/N MS28700-3	M
4423	Relocation of the Flight Control Hydraulic Accumulator	M
A4452	Inspection of the Rudder Upper Torque Tube Lower Bearing	M
4456	Inspection of the Elevator Control Pressure Switch	M
4460	Inspection of Aileron Gear Tab for Part Numbers and Serial Numbers	R
4462	Inspection of the Flap Actuator for a Possible Fouling Condition	R
4465	Verification of Torque Value on Aileron Control Multiplier Bolt	R
4468	Installation of Additional Grease Fittings on the Upper and Lower Torque Tube Bearing Assemblies	R
4472	Inspection / Replacement of the Joint Fitting on the Elevator Torque Tube Control Assembly (Common to the Pitch Disconnect)	R
4474	Identification of the Left and Right Elevator Spring Tab Assemblies	R
4476	Inspection of the Aileron Control System Cables and Flap Interconnect System Cables	R
4477	Replacement of Powered Aileron System Teflon Parts Due to Excess Charge of Fiberglass	R
4480	Inspection of the Aileron Interconnect Pulley Assembly Guard Pins	R

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 27 – Flight Controls (Cont'd)

215-	SUBJECT	COMPLIANCE
4481	Replacement of the Elevator Normal Trim Actuator	R
4494	Replacement of the Aileron Gear and Trim Tab Assembly Nameplates	R
4499	Inspection of Aileron Manual Trim System for Excessive Backlash	R

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 28 – Fuel

215–	SUBJECT	COMPLIANCE
4015	Installation of Protective Sleeves on the Exterior Cap Chains	RBD
4017	Installation of a Bonding Jumper on the Pressure Refuel Line	RBD
4030	Installation of Fuel Transfer Line Protective Covers	R
4036	Replacement of the Ejector Pump Collector Tank Fasteners	C/O
4048	Relocation of the Collector Tank Manual Shut-Off Valve Controls	R
4082	Identification of the Collector Tank Shut-Off Valve Positions	RBD
4085	Installation of Guides for the Pressure Relief Valve	R
4087	Installation of a Fuel Drain Quick Disconnect PROPOSAL SHEET	R
4087	Installation of a Fuel Drain Quick Disconnect	R
4138	Modification to the Fuel Cell Interconnect Drain System	R
4141	Modification to the Pressure Refueling System	R
4155	Installation of a Diode in the LH Pump Power Legend	R
A4192	Replacement of Dome Nut Rivets on Ejector Pump Collector Tank	R
A4201	Special Inspection and Modification to the Fuel Drain Line Assemblies in the Front and Rear Spar Area	R
4228	Replacement of the Fuel Cell Cover Bolts	R
4252	Installation of a Diode in the Fuel Control Panel	R
A4259	Special Inspection/Replacement of the Clamp on the Fuel Drain Line – Lower Cowling	M

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 28 – Fuel (Cont'd)

215-	SUBJECT	COMPLIANCE
4273	Installation of a Pressure Refueling Control Panel Splash	C/O
4345	Guard Installation of a Security Chain on the Refuelling Cap Assembly	C/O

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 29 – Hydraulic Power

215-	SUBJECT	COMPLIANCE
4018	Installation of a Charge Chart on the Accumulator Charging-Bay Access Door	RBD
4142	Material Change of the Aft Hydraulic Bay Bulkhead Tee Fitting	R
4203	Special Inspection/Replacement of Grimes Aerospace Four-Way Solenoid Operated Valve Identification Plate with Duplicate Serial Numbers	R
A4306	Special Inspection of the Hydraulic Lines in the Nacelle Transition Box	M
4307	Replacement of the Nacelle Transition Box Cover Plates	R
4352	Addition of Lubricant to the Engine Driven Pump (EDP) Spline	R

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 30 – Ice and Rain Protection

215-	SUBJECT	COMPLIANCE
4003	Installation of Electro Magnetic Interference (EMI) Filters	R
4098	Installation of Corrosion Protective Tape on the Engine Intake V-Band Coupling	R
4206	Inspection and Modification of the Engine Intake Adaptor Heater Harness	R

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 31 – Indicating/Recording Systems

215-	SUBJECT	COMPLIANCE
4080	Introduction of Parker Gull Integrated Instrument Display System (IIDS)	R
4117	Installation of Additional Parameters to the Flight Data Recorder (FDR)	R
4134	Circuit Improvements added to Prevent False/Misleading Indications	R
4165	Addition of High Cam Light Indicators on the Engine Control Panel PROPOSAL SHEET	C/O
4165	Addition of High Cam Light Indicators on the Engine Control Panel	C/O
4364	Installation of a Water Door Open Caution System (Elisen Technologies STC SA 06-3)	C/O
4365	Installation of an L3 Flight Data Recorder (FDR) and Provisions for a micro Quick-Access Recorder (QAR) and a Digital Clock	M
4367	Installation of an L3 Flight Data Recorder (FDR), A micro Quick-Access Recorder (QAR), and a Digital Clock	C/O
4368	Replacement of the SFIM Industries Flight Data recorder (FDR) with a L3 FDR and Installation of a Micro Quick Access recorder (QAR) and a Digital Clock	C/O
4422	Replacement of the Remote Signal Processing Unit (RSPU)	R
4426	Replacement of the Pilot and Copilot Digital Clocks (With Flight Data Recorder (FDR) already installed or being installed in conjunction with this Service Bulletin)	C/O
4427	Wiring Modification to the Flight Data Recorder (FDR) when Changing the Old ADC Type for the Penny & Giles ADC	R

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 31 – Indicating/Recording Systems (Cont'd)

215-	SUBJECT	COMPLIANCE
4432	Replacement of the Pilot and Copilot Digital Clocks (Without Flight Data Recorder (FDR) Installed)	C/O
4446	Installation of a Water door Open Caution System with Flight Management System (FMS) and Global Positioning System (GPS) Installed	C/O
4467	Replacement of the Flight Data Recorder (FDR) No. 3 Digital Clock	R
4483	Installation of Software Upgrade for the Digital Clock P/N APE4190-070	R

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 32 – Landing Gear

215-	SUBJECT	COMPLIANCE
4013	Replacement of the Nose Landing Tire	RBD
4021	Inspection of the Main Landing Gear Shock Strut Assembly	RBD
4034	Replacement of the Nose Wheel Steering (NWS) Input-Lever End-Cap	R
4081	Modification to the Landing Gear Control Handle Wiring Harness	R
4111	Replacement of the Main Landing Gear (MLG) and Nose Landing Gear (NLG) Harnesses	R
4123	Replacement of the Emergency-Brake Control Cable PROPOSAL SHEET	C/O
4123	Replacement of the Emergency-Brake Control Cable	C/O
4157	Replacement of the Accumulator Pressure Gauge	R
4203	Special Inspection/Replacement of Grimes Aerospace Four-Way Solenoid Operated Valve Identification Plate with Duplicate Serial Numbers	R
4204	Inspection of the Main Landing Gear (MLG) Uplock Hook (Héroux Part No. 160-408)	R
4226	Adjustment of the Main Landing Gear Downlock Microswitches	R
4242	Inspection of the Nose Landing Gear (NLG) Emergency Gear Down Priority Valve	M
4255	Installation of Protective Tape on the Main Landing Gear	R
4266	Special inspection of the Nose Landing Gear (NLG) Back Pressure Valve and Pressure Relief Valve	M
4292	Installation of Provisions for the Weight-on-Wheels (WOW)	C/O

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 32 – Landing Gear (Cont'd)

215-	SUBJECT	COMPLIANCE
4348	Installation of a Lubricating Fitting on the Main Landing Gear Torque Links	C/O
4357	Installation of Landing Gear Harness Repair Kit	C/O
4363	Relocation of the Main Landing Gear (MLG) Door Ground Stud	C/O
4385	Replacement of the Nose Landing Gear (NLG) Centering Cam	R
4414	Special Inspection of the Accumulator Screw Caps on Accumulator P/N MS28700-3	M
4418	Replacement/Installation of the Nose Landing Gear (NLG) Right Side Door	C/O
A4435	Special Inspection (Visual) of the Accumulator Screw Caps on Accumulator P/N MS28700-3	M
A4450	Inspection of the Main Landing Gear (MLG) Upper Member Forward Lug Using Liquid Penetrant Method	M
4459	Replacement of the Shock strut Assembly (RH) Name Plate	C/O

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 33 – Lights

215-	SUBJECT	COMPLIANCE
4028	Replacement of Screws for the Emergency Battery	RBD
4063	Installation of an Alternate Power Source for the Empennage and the Main Distribution Centre (MDC) Service Light PROPOSAL SHEET	R
4063	Installation of an Alternate Power Source for the Empennage and the Main Distribution Centre (MDC) Service Light	R
4160	Addition of Corrosion Protection to the Navigation Tail Light Assembly PROPOSAL SHEET	R
4293	Addition of Bright/Dim Lighting Capabilities for the SAR Mission Equipment	R

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 34 – Navigation

215–	SUBJECT	COMPLIANCE
4011	Installation of a Garmin 165 Global Positioning System PROPOSAL SHEET	C/O
4011	Installation of a Garmin 165 Global Positioning System	C/O
4022	Installation of a Decal on the ATC Transponder Antenna Assembly	RBD
4065	Replacement of the VHF Integrated Navigation Receivers	R
4077	Replacement of the Airspeed Indicator Nipple (Static Side)	R
4079	Replacement of the Air Data Computer (ADC) Placard	C/O
4095	Installation of a WX-1000 Stormscope	C/O
4101	Installation of a Caution Decal for the Attitude and Heading Reference System (AHRS) Unit	C/O
4164	Installation of Speed Bugs on the Airspeed Indicators (ASI) PROPOSAL SHEET	C/O
4164	Installation of Speed Bugs on the Airspeed Indicators (ASI)	C/O
4220	Replacement of the Radio Altimeter Antennas	R
4272	Installation of the Nose-Mounted Weather Radar and Radome Primus 660	C/O
4274	Installation of Structural Provisions for the Multi Mission Management System (MMMS)	C/O
4281	Installation of the Nose-Mounted Weather Radar and Radome Primus 660	C/O
4297	Installation of Provisions for the Nose Mounted Weather Radar and Radome Primus 660	C/O

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 34 – Navigation (Cont'd)

215-	SUBJECT	COMPLIANCE
4300	Upgrade of the Attitude and Heading Reference Unit (AHRU) to Mod 7	C/O
4304	Installation and Removal of the Attitude and Heading Reference Unit (AHRU) Mod 7 for Evaluation	R
4317	Inspection of Static Selector Valve Placard	M
4343	Replacement of the VHF Integrated Navigation Receiver to Eliminate Possible Erroneous ILS Information (Removal of FAA AD 2003-04-06)	R
4373	Modification to the Symbol Generators SG-605 Silver Label, Part No. 7011672-607	M
4374	Installation of Structural Provisions for the Multi Mission Management System (MMMS)	C/O
4377	Replacement of the Attitude Heading Reference System (AHRU)	C/O
4428	Replacement of the Existing Air Data Computer (ADC) Unit with a New Penny and Giles ADC Unit	C/O
4437	Replacement of the Honeywell AH-800 and/or the LITEF LCR-93 Attitude and Heading Reference Unit (AHRU) with a LITEF LCR-100 AHRU	C/O
4439	Installation of Structural Provisions for the Flight Management System (FMS)	C/O
4441	Removal of the Garmin 165 Global Positioning System (GPS) from the Aircraft	C/O
4495	Modification to the Integrated Navigation Units to Eliminate False "MLS ERR" Message on the Radio Management Unit	R

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 35 – Oxygen

215-	SUBJECT	COMPLIANCE
4051	Modification to the Pilot and Copilot Portable Oxygen System	R
A4351	Inspection for Correct Breathing Tube Connection on the Scott Aviation Oxygen Mask	M
4398	Installation of a Protective Breathing Equipment (PBE)	C/O
4457	Modification of the Pilot and Copilot Portable Oxygen System (Post Installation of Service Bulletin 215-4051)	R
4461	Modification of the Pilot and Copilot Portable Oxygen System (This Service Bulletin Replaces 215-4051 and 215-4457)	C/O

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 39 – Electrical/Electronic Multipurpose Parts

215-	SUBJECT	COMPLIANCE
4064	Replacement of the Junction Box (JB) Tray	R

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 42 – Aerial Fire-Fighting

215-	SUBJECT	COMPLIANCE
4004	Modification to the Foam System Piping	RBD
4007	Installation of Fixed Piping in the Water Tanks	R
4014	Addition of Placards on the Foam Tanks	RBD
4020	Modification to the Foam System Piping	RBD
4029	Replacement of the Water Door Tension Rods	R
4035	Replacement of the Foam Refill/Bilge Pump Switch	R
4037	Rework of the Water Door Beam Attachment Holes	RBD
4038	Replacement of the Water Door Torque Shaft Seals	R
4045	Water Door Sealing Improvements	R
4057	Installation of Standardized Fasteners	C/O
4072	Modification to the Ground Water-Filling System PROPOSAL SHEET	C/O
4072	Modification to the Ground Water-Filling System	C/O
4075	Modification to the Ground Water-Filling System	C/O
4092	Replacement of the Water Drop Control System	R
4099	Miscellaneous Improvements to the Two-Pump Foam System	C/O
4100	Miscellaneous Improvements to the One-Pump Foam System	C/O
4102	Modification to the Flapper Door	R
4103	Replacement of the Probe Down Microswitches	R

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 42- Aerial Fire-Fighting (Cont'd)

215-	SUBJECT	COMPLIANCE
4107	Replacement of the Foam Tank Access Panels	R
4116	Replacement of the Water Door Isolator Valve	R
4119	Relocation of the Foam Tank Vent Pipe	R
4102	Modification to the Flapper Door	R
4121	Modification to the Foam Selector Valves (One Pump System)	R
4122	Provision for Lockwiring the Uplock Actuator Hose Assemblies	C/O
4124	Removal of a Fouling Nutplate From the Floor-Seal Assembly	R
4131	Installation of Up-Lock Priority Valves	R
4132	Installation of an Enable/Disable Switch in the Water Drop Control System	C/O
4133	Replacement of the Water Drop Control (WDC) Panel	R
4137	Replacement of the Foam Vacuum Relief Valve	R
4147	Modification to the Foam Selector Valves	R
4149	Replacement of the Restrictor Assemblies for the Water Door Actuators	R
4151	Application of a Protective Coating on the Water Door Proximity Switches	R
4166	Installation of a Foam Pump Injection Failure Indication	C/O
4174	Installation of a Metric Ground Fill Adaptor	C/O
4176	Installation of an Auto Probe Retraction System	C/O

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 42- Aerial Fire-Fighting (Cont'd)

215-	SUBJECT	COMPLIANCE
4195	Installation of a Forward Looking Infrared (FLIR) System	C/O
4205	Replacement of the Analog Output Modules (AOM) Mounting Plate and Hardware	R
4235	Improvement to the Water Door Bearing Housing	R
4241	Addition of Sealant on the Water Level Sensor	R
4253	Special Inspection of the Water Door Solenoid Valve Connectors	R
4262	Installation of Water Door Deflectors	C/O
4267	Special Inspection of the Water Door Priority Valves	R
4271	Production Aircraft Water Test Post C of A	M
4290	Installation of Water Door Stop Protective Covers	C/O
4294	Removal of Foam System and Installation of Two Bilge Pump System	R
4302	Replacement of Water Door Priority Valve Hose Assemblies	R
4314	Removal of Foam Concentrate Tanks and Water Header Tanks	C/O
4316	Addition of Corrosion Protection for the Water System Electrical Connectors	R
4338	Replacement of Hardware on the Water Door Torque Shaft	C/O
4339	Replacement of the Water Door Damper Hardware	C/O
4341	Modification to the Roller Assembly, Manual Release, Four-Tank System	R
4342	Replacement of the Uplock Actuator Bearing	R

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 42- Aerial Fire-Fighting (Cont'd)

215-	SUBJECT	COMPLIANCE
4349	Inspection of the Bilge Pump Discharge Hose Assemblies (Temporary Installation)	M
4353	Installation of Second Foam/Bilge Pump	C/O
4358	Installation of New Water Quantity Sensors	C/O
4386	Replacement of the Emergency Water Dump Pulley Bracket	C/O
A4424	Inspection of the Emergency Water Dump Pulley Bracket and Structure at FS 150.50	M
4434	Removal of Water Header Tanks Search and Rescue (SAR) Configuration	C/O
4438	Installation of a Foam Failure Indication System	C/O
4466	Inspection for Possible Interference between the Water Door Actuator Idler Arm Retaining Bolt and Support Structure	R
4484	Replacement of the Emergency Water Dump Handle Assembly	R
4500	Replacement of the Auto Probe System Mode Selection Switch	C/O

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 49 – Auxiliary Power

215-	SUBJECT	COMPLIANCE
4026	Replacement of the Onboard Compressor Wash System Drain Line	RBD
4039	Provision for a Ground Support Equipment Blanking Plate	RBD
4058	Replacement of the Ground Auxiliary Power Unit (GAPU) Compressor/Turbine Wash Restrictor Valve	R
415-4118	Auxiliary Power Unit (APU) Control Panel Relocation in Accordance with Limited Supplemental Type Certificate (LSTC) No. Q-LSA01-023 (415-4118 This is an Installation Instruction Document, not a Service Bulletin)	C/O
415-4346	Temporary Removal of the SAPHIR 20 Auxiliary Power Unit (APU) Powerplant in Accordance with STC No. SA04-53 (415-4118 This is a Removal Instruction Document, not a Service Bulletin)	R

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 52 – DOORS

215-	SUBJECT	COMPLIANCE
4211	Addition of a Seal to the Pilot Escape Hatch	R
4256	Installation of an Aft Cabin Enlarged Cargo Door	C/O
4278	Relocation of the Type 3 Emergency Exit Door	C/O

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 53 – Fuselage

215–	SUBJECT	COMPLIANCE
4008	Modification to the Main Distribution Centre/Combustion Heater Shield Assembly	RBD
4057	Installation of Standardized Fasteners	C/O
4061	Reinforcement of the Main Landing Gear (MLG) Actuator Compartment	R
4074	Replacement of Fasteners for Access Panels 255–6 and 255–7	C/O
4078	Prevention of Water Accumulation on the Pilot and Copilot Side Consoles	C/O
4086	Installation of the AFT Hydraulic Bay Floor PROPOSAL SHEET	C/O
4086	Installation of the AFT Hydraulic Bay Floor	C/O
4105	Modification to the Direct Vision (DV) Window Drains	C/O
4110	Installation of a Packer on the Hydraulic–Accumulator Access Door	R
4146	Special Inspection – Missing Rivets at Bulkhead FS 234.5, RBL 48.0, WL 140.0	R
4153	Installation of Centre Pedestal Support Struts	R
4167	Installation of an Access Panel for the Rudder Actuator	C/O
4189	Reinforcement of the Bottom Frame (At FS 296.25, 315.0, 333.75, and 352.50)	C/O
4193	Installation of Access Covers to Flood Switch and Probe Microswitch PROPOSAL SHEET	C/O
4193	Installation of Access Covers to Flood Switch and Probe Microswitch	C/O

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 53 – Fuselage (Cont'd)

215-	SUBJECT	COMPLIANCE
4232	Removal of Sodium Dichromate Bags from the Aircraft Hull	C/O
4247	Replacement of the Aircraft Hull Drain Plugs PROPOSAL SHEET	C/O
4247	Replacement of the Aircraft Hull Drain Plugs	C/O
4249	Improved Sealing of the Hydraulic Servicing Panel and Fuel/Defuel Control Panel	R
4254	Reinforcement of the Aircraft Hull at FS 333.75 and 352.50	C/O
4279	Installation of a Temporary Ballast Tray at FS 133.00	C/O
4280	Removal of a Temporary Ballast Tray at FS 133.00	M
4283	Reinforcement of the Aircraft Hull at FS 313.00 and 371.50	C/O
4285	Application of Sealant to Aircraft Hull at the Water Door	R
4299	Inspection for Missing Fasteners	R
4325	Reinforcement of the Rear Spar on the Vertical Stabilizer	R
4331	Improvement to the Corrosion Protection on the Cabin Floor Structure	R
4410	Special Inspection of the Aft Fuselage Hull Between FS 501 and FS 720	R
4419	Special Inspection of the Lightning Holes at FS 371.50	C/O
4430	Aft Hull Reinforcement Between FS 501.00 and FS 684.00	C/O

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 53 – Fuselage (Cont'd)

215-	SUBJECT	COMPLIANCE
A4436	Replacement of MDC Rack Panel and Installation of Additional Harness Support	M
4447	Replacement of the Studs for the Main Entrance Door Ladder	R
4469	Special Inspection of the Aircraft Hull Stringers for Missing Drain Holes	R

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 54 – Nacelles/Pylons

215-	SUBJECT	COMPLIANCE
4057	Installation of Standardized Fasteners	C/O
4402	Inspection of the RH Nacelle Struts for Nickle Plating	R
A4453	Inspection of the Bushings in the Nacelle Upper Strut Assemblies	M

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 55 – Stabilizers

215-	SUBJECT	COMPLIANCE
4106	Improved Access to Elevator-Actuator Rod-End Attachment-Bolt	R
4108	Replacement of the Lower Finlet L/E Skins	R
4251	Modification of the Rudder Gear/Trim Tab Drain Holes	C/O
4308	Special Inspection of the Right Side Horizontal Stabilizer Leading-Edge Upper Skin	R
4332	Special Inspection of the Upper and Lower Finlet Attachment Fittings	M
4415	Special Inspection of the Elevator Actuator Fitting Assembly Mounting Hardware	R
4463	Inspection and/or Replacement of the Upper and Lower Elevator Horn Skins (P/N 215-25004-106 and 215-25004-15 LH Upper and Lower) (P/N 215-25004-107 and 215-25004-14 RH Upper and Lower)	R
4488	Inspection / Rework of Forward Horizontal to Vertical Stabilizer Attachment Fittings (left and right sides) for Loose Bolts	R

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 56 – Windows

215-	SUBJECT	COMPLIANCE
4222	Installation of a Flat Seal and Drainage Improvements for the Direct Vision (DV) Window	R
4275	Installation of Left and Right Side Bubble Windows	C/O
4276	Installation of Structural Provisions for Left and Right Side Bubble Windows	C/O

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 57 – Wings

215-	SUBJECT	COMPLIANCE
4006	Inspection/Replacement of the Flap Asymmetry Interconnect Fitting	R
4076	Installation of a Front-Spar Lower-Skin Access Panel	R
4139	Modification to the Oil Cooler Fairing Structure	C/O
4185	Reinforcement of the Wing Leading Edge	R
4291	Installation of Structural Provisions for the External Shapes	C/O

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 61 – Propellers

215-	SUBJECT	COMPLIANCE
4088	Installation of a Permanent Propeller–Balancing Harness PROPOSAL SHEET	C/O
4088	Installation of a Permanent Propeller–Balancing Harness	C/O
4234	Installation of a Backup Pressure Relief and Replacement of Studs	M
4340	Re-routing of the Propeller Control Harness Wires	R
4501	Conversion of Model No. 14SF–19 Propeller Blades to Model No. 14SF–17 Propeller Blades and Optional Incorporation of a Stronger Trailing Edge	C/O

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 71 – Power Plant

215-	SUBJECT	COMPLIANCE
4023	Replacement of the Mechanical Fuel Control Unit	R
4040	Onboard Compressor Wash Harness Routing	RBD
4056	Installation of Engine External Wash PROPOSAL SHEET	R
4056	Installation of Engine External Wash	R
4083	Replacement of the Compressor Wash Option Decal	R
4104	Installation of a Flip Guard for the Onboard Compressor Wash Pump Switch	C/O
4127	Installation of an On-Board Compressor Wash Pump (One Foam Tank Configuration) PROPOSAL SHEET	C/O
4154	Installation of an Onboard Compressor/Turbine Wash System (Two Foam Tank Configuration) PROPOSAL SHEET	C/O
4154	Installation of an Onboard Compressor/Turbine Wash System (Two Foam Tank Configuration)	C/O
4172	Relocation of the Left-Hand Nacelle External Engine Wash Coupling PROPOSAL SHEET	C/O
4172	Relocation of the Left-Hand Nacelle External Engine Wash Coupling	C/O
4230	Relocation of the low Pressure (LP) Impeller Spray Nozzle for the Compressor Wash System	C/O
4277	Relocation of the Oil Replenishment System	C/O
A4287	Special Inspection of Rear Engine Mount Studs	M

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 71 – Power Plant (Cont'd)

215-	SUBJECT	COMPLIANCE
4442	Inspection of the Engine Drain Hose	R
4443	Replacement of the Engine Drain Hose Assemblies	M

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 72 – Engine

215-	SUBJECT	COMPLIANCE
4312	Replacement of the Front and Rear Engine Inlet Case Assemblies	C/O

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 73 – Engine Fuel and Controls

215-	SUBJECT	COMPLIANCE
4125	Replacement of the Sealing Nut and Retainer in the Motive Flow Line	R

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 76 – Engine Controls

215-	SUBJECT	COMPLIANCE
4089	Installation of Power-Lever Witness-Marking Decals	C/O
4231	Inspection/Installation of the Engine Control Cable Spacers in the Nacelle Area	R

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 79 – Oil

215-	SUBJECT	COMPLIANCE
4042	French Instructions Placard for the Oil Replenishment System	RBD
4055	Replacement of the Oil Replenishment Placard and Markings	R
4068	Replacement of the Oil Replenishment Placard	R
4073	Replacement of the Fasteners on the Oil Replenishment Door	C/O
4159	Oil Cooler Corrosion Protection	R
4380	Installation of a New Servicing Instruction Placard for the Oil Replenishment System	R

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 80 – Starting

215-	SUBJECT	COMPLIANCE
4060	Modification to the Ground Auxiliary Power Unit (GAPU) Electrical System	R

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 1, ISSUED BEFORE OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 93 – Surveillance

215-	SUBJECT	COMPLIANCE
4347	Installation of Structural Provisions for the Collins 124F (V2) Direction Finder (DF) Antenna	C/O

CL-415

MODEL CL-215-6B11 (CL-415 Variant) SERVICE BULLETIN INDEX

PART 2

Service Bulletins issued after October 1, 2016

DESCRIPTION:

Service Bulletins issued after October 1, 2016 document mitigation or corrective actions related to continuing airworthiness and define service action to be taken within a specified time frame.

Compliance

Mandatory compliance is subject to applicable Airworthiness Directives.

Effectivity

Effectivity is provided in the Planning section of each Service Bulletin, and is subject to applicable Airworthiness Directives.

CL-415

SECTION 1 NUMERICAL SEQUENCE

DEFINITIONS:

V415-

This column contains the number of the Service Bulletin. Service Bulletins listed in Part 2 of this index use the prefix "V415-".

Service Bulletins issued after V415-0001 will be numbered starting at -5000

Service Bulletins with the letter "A" preceding the number are Alert Service Bulletins, for example V415-A5000 These are identified as requiring urgent operator action.

Note: There may be some breaks in the numbering sequence. This is due to Service Bulletin numbers having been reserved for use by the manufacturer and then subsequently not issued.

DATE OF ISSUE

This column contains the issue month and year of the applicable revision, as listed in the SUBJECT column.

SUBJECT

This column contains the title of the Service Bulletin, and any applicable revision numbers.

Cancelled Service Bulletins are also listed in this column for reference, but are not distributed.

ATA REF.

This column lists the applicable ATA chapter reference number.

CL-415



SECTION 2 ATA CHAPTER SEQUENCE

DEFINITIONS

V415-

This column contains the number of the Service Bulletin. Service Bulletins listed in Part 2 of this index use the prefix "V415-".

Service Bulletins issued after V415-0001 will be numbered starting at -5000

Service Bulletins with the letter "A" preceding the number are Alert Service Bulletins, for example V415-A5000 These are identified as requiring urgent operator action.

Note: There may be some breaks in the numbering sequence. This is due to Service Bulletin numbers having been reserved for use by the manufacturer and then subsequently not issued.

SUBJECT

This column contains the title of the Service Bulletin, and any applicable revision numbers.

Cancelled Service Bulletins are also listed in this column for reference, but are not distributed.

CL-415

VIKING*

THIS PAGE INTENTIONALLY LEFT BLANK

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 2, ISSUED AFTER OCT 1, 2016

NUMERICAL SEQUENCE SECTION 1

V415-	DATE OF ISSUE	SUBJECT	ATA REF
0001	Oct. 16	Type Certificate Ownership Transfer	N/A
A5000	Jun. 18	Auxiliary Feathering Pump – Possible Failure Causing Inability to Feather (Hamilton Sundstrand Service Bulletin No. 14SF-61-168)	61
5001	Aug. 20	Main Landing Gear – Serialization and Component History	32
5002	Jan. 21	Water Door System – Introduction of a Life Limit on a Component	05

CL-415

The logo for VIKING, featuring the word "VIKING" in a bold, italicized, sans-serif font with a horizontal line above the letters.

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 2, ISSUED AFTER OCT 1, 2016

NUMERICAL SEQUENCE
SECTION 1

THIS PAGE INTENTIONALLY LEFT BLANK

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 2, ISSUED AFTER OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 5 – Time Limits – Maintenance Checks

V415–	SUBJECT
5002	Water Door System – Introduction of a Life Limit on a Component

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 2, ISSUED AFTER OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 32 – Landing Gear

V415–	SUBJECT
5001	Main Landing Gear – Serialization and Component History

CL-415



MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 2, ISSUED AFTER OCT 1, 2016

ATA CHAPTER SEQUENCE SECTION 2

CHAPTER 61 – Propellers

V415–	SUBJECT
A5000	Auxiliary Feathering Pump – Possible Failure Causing Inability to Feather (Hamilton Sundstrand Service Bulletin No. 14SF-61-168)

CL-415

The logo for VIKING, featuring the word "VIKING" in a bold, italicized, sans-serif font with a horizontal line above the letters.

MODEL CL-215-6B11 (415)
SERVICE BULLETIN INDEX
PART 2, ISSUED AFTER OCT 1, 2016

ATA CHAPTER SEQUENCE
SECTION 2

THIS PAGE INTENTIONALLY LEFT BLANK